



| Tipo | Diam D | Sez T | rif Inglese | rif BS | rif USA | rif Francese |
|---------|--------|-------|-------------|--------|---------|--------------|
| O-Rings | 0,74 | 1,02 | | 001 | 2 - 1 | |
| O-Rings | 0,80 | 1,60 | | | 6-408 | |
| O-Rings | 1,00 | 1,00 | | | | |
| O-Rings | 1,00 | 1,50 | | | | |
| O-Rings | 1,07 | 1,27 | | 002 | 2-2 | |
| O-Rings | 1,15 | 1,00 | | | | R000 |
| O-Rings | 1,20 | 1,10 | | | 9-001 | |
| O-Rings | 1,20 | 3,00 | | | 6-465 | |
| O-Rings | 1,24 | 2,62 | | 102 | 2-102 | |
| O-Rings | 1,30 | 1,10 | | | 9-002 | |
| O-Rings | 1,42 | 1,52 | | 003 | 2-3 | |
| O-Rings | 1,50 | 1,00 | | | 6-369 | |
| O-Rings | 1,78 | 1,02 | | | 5-051 | |
| O-Rings | 1,78 | 1,78 | 2007 | 004 | 2-4 | |
| O-Rings | 1,80 | 1,00 | | | | |
| O-Rings | 1,80 | 1,20 | | | 9-008 | |
| O-Rings | 1,80 | 1,80 | | | | |
| O-Rings | 1,85 | 1,50 | | | 6-418 | |
| O-Rings | 1,98 | 0,84 | | | 6-364 | |
| O-Rings | 2,00 | 1,00 | | | 9-010 | |
| O-Rings | 2,00 | 1,50 | | | | |
| O-Rings | 2,00 | 1,80 | | | | |
| O-Rings | 2,00 | 2,00 | | | | |
| O-Rings | 2,06 | 2,62 | | 103 | 2-103 | |

| | | | | | | |
|---------|------|------|------|-----|-------|-------|
| O-Rings | 2,20 | 1,60 | | | 6-306 | R00 |
| O-Rings | 2,24 | 1,80 | | | | |
| O-Rings | 2,35 | 1,00 | | | 9-012 | |
| O-Rings | 2,40 | 1,70 | | | 6-199 | |
| O-Rings | 2,40 | 1,75 | | | 6-220 | |
| O-Rings | 2,40 | 1,90 | | | 6-538 | RO |
| O-Rings | 2,50 | 1,00 | | | 9-013 | |
| O-Rings | 2,50 | 1,20 | | | 6-167 | |
| O-Rings | 2,50 | 1,30 | | | 6-138 | |
| O-Rings | 2,50 | 1,50 | | | | |
| O-Rings | 2,50 | 1,70 | | | 6-168 | |
| O-Rings | 2,50 | 1,75 | | | 6-399 | |
| O-Rings | 2,50 | 1,80 | | | | |
| O-Rings | 2,50 | 2,00 | | | | |
| O-Rings | 2,57 | 1,78 | 2010 | 005 | 2-5 | |
| O-Rings | 2,60 | 1,90 | | | 5-578 | R1 |
| O-Rings | 2,70 | 1,50 | | | 6-020 | |
| O-Rings | 2,75 | 1,60 | | | | R1BIS |
| O-Rings | 2,80 | 1,50 | | | | |
| O-Rings | 2,80 | 1,60 | | | 9-018 | |
| O-Rings | 2,80 | 1,80 | | | | |
| O-Rings | 2,84 | 2,62 | | 104 | 2-104 | |
| O-Rings | 2,90 | 1,02 | | | 6-487 | |
| O-Rings | 2,90 | 1,78 | 2012 | 006 | 2-6 | |
| O-Rings | 3,00 | 1,00 | | | | |
| O-Rings | 3,00 | 1,20 | | | 6-549 | |
| O-Rings | 3,00 | 1,50 | | | 6-441 | |
| O-Rings | 3,00 | 2,00 | | | 9-021 | |
| O-Rings | 3,00 | 2,50 | | | | |
| O-Rings | 3,00 | 3,00 | | | | |

| | | | | | | |
|---------|------|------|------|-----|-------|----|
| O-Rings | 3,02 | 1,85 | | | 6-365 | |
| O-Rings | 3,10 | 1,60 | | | | |
| O-Rings | 3,15 | 1,80 | | | | |
| O-Rings | 3,17 | 1,78 | | 801 | | |
| O-Rings | 3,20 | 1,60 | | | 9-022 | |
| O-Rings | 3,30 | 1,40 | | | 6-361 | |
| O-Rings | 3,30 | 2,40 | | | | |
| O-Rings | 3,33 | 1,02 | | | 6-307 | |
| O-Rings | 3,35 | 1,18 | | | 5-190 | |
| O-Rings | 3,40 | 1,80 | | | 9-023 | |
| O-Rings | 3,40 | 1,90 | | | 5-579 | R2 |
| O-Rings | 3,50 | 1,00 | | | | |
| O-Rings | 3,50 | 1,10 | | | 6-491 | |
| O-Rings | 3,50 | 1,20 | | | 6-021 | |
| O-Rings | 3,50 | 1,25 | | | 6-402 | |
| O-Rings | 3,50 | 1,50 | | | 6-648 | |
| O-Rings | 3,50 | 2,00 | | | | |
| O-Rings | 3,50 | 3,00 | | | | |
| O-Rings | 3,55 | 1,80 | | | | |
| O-Rings | 3,60 | 2,40 | | | | |
| O-Rings | 3,63 | 2,62 | | 105 | 2-105 | |
| O-Rings | 3,69 | 1,78 | 2015 | 007 | 2-7 | |
| O-Rings | 3,70 | 1,90 | | | 6-251 | |
| O-Rings | 3,75 | 1,80 | | | | |
| O-Rings | 3,80 | 1,90 | | | | |
| O-Rings | 3,90 | 1,80 | | | 6-166 | |
| O-Rings | 4,00 | 1,00 | | | 9-028 | |
| O-Rings | 4,00 | 1,10 | | | 6-019 | |
| O-Rings | 4,00 | 1,50 | | | 6-035 | |
| O-Rings | 4,00 | 1,80 | | | | |

| | | | | | | |
|---------|------|------|------|-----|-------|----|
| O-Rings | 4,00 | 2,00 | | | 6-104 | |
| O-Rings | 4,00 | 2,20 | | | 6-420 | |
| O-Rings | 4,00 | 2,50 | | | 6-428 | |
| O-Rings | 4,00 | 3,00 | | | 9-032 | |
| O-Rings | 4,00 | 4,00 | | | | |
| O-Rings | 4,00 | 5,00 | | | | |
| O-Rings | 4,10 | 1,60 | | | | |
| O-Rings | 4,20 | 1,90 | | | 5-580 | R3 |
| O-Rings | 4,30 | 2,40 | | | 9-034 | |
| O-Rings | 4,34 | 3,53 | | 201 | 2-201 | |
| O-Rings | 4,42 | 2,62 | | 106 | 2-106 | |
| O-Rings | 4,48 | 1,78 | 2018 | 008 | 2-8 | |
| O-Rings | 4,50 | 1,00 | | | 6-401 | |
| O-Rings | 4,50 | 1,50 | | | 6-214 | |
| O-Rings | 4,50 | 1,80 | | | | |
| O-Rings | 4,50 | 2,00 | | | 6-368 | |
| O-Rings | 4,50 | 2,25 | | | 9-036 | |
| O-Rings | 4,50 | 3,00 | | | | |
| O-Rings | 4,60 | 1,78 | | | 9-037 | |
| O-Rings | 4,60 | 2,00 | | | 9-038 | |
| O-Rings | 4,60 | 2,40 | | | | |
| O-Rings | 4,60 | 2,50 | | | | |
| O-Rings | 4,70 | 1,42 | | | 3-901 | |
| O-Rings | 4,70 | 1,60 | | | | |
| O-Rings | 4,70 | 1,90 | | | 6-133 | |
| O-Rings | 4,76 | 1,78 | | 802 | | |
| O-Rings | 4,80 | 1,60 | | | 9-039 | |
| O-Rings | 4,87 | 1,80 | | | | |
| O-Rings | 4,90 | 1,90 | | | 5-581 | R4 |
| O-Rings | 5,00 | 1,00 | | | 9-040 | |

| | | | | | | |
|---------|------|------|------|-----|-------|----|
| O-Rings | 5,00 | 1,20 | | | 6-583 | |
| O-Rings | 5,00 | 1,50 | | | 6-069 | |
| O-Rings | 5,00 | 1,60 | | | | |
| O-Rings | 5,00 | 1,75 | | | 9-043 | |
| O-Rings | 5,00 | 1,80 | | | | |
| O-Rings | 5,00 | 2,00 | | | 6-110 | |
| O-Rings | 5,00 | 2,50 | | | 9-045 | |
| O-Rings | 5,00 | 3,00 | | | | |
| O-Rings | 5,00 | 4,00 | | | | |
| O-Rings | 5,00 | 5,00 | | | | |
| O-Rings | 5,10 | 1,60 | | | | |
| O-Rings | 5,15 | 1,80 | | | | |
| O-Rings | 5,23 | 2,62 | 3021 | 107 | 2-107 | |
| O-Rings | 5,28 | 1,02 | | | 6-565 | |
| O-Rings | 5,28 | 1,78 | 2021 | 009 | 2-9 | |
| O-Rings | 5,30 | 1,80 | | | | |
| O-Rings | 5,30 | 2,40 | | | | |
| O-Rings | 5,35 | 1,50 | | | 6-063 | |
| O-Rings | 5,50 | 1,00 | | | | |
| O-Rings | 5,50 | 1,50 | | | 9-047 | |
| O-Rings | 5,50 | 2,00 | | | | |
| O-Rings | 5,50 | 2,40 | | | | |
| O-Rings | 5,50 | 2,50 | | | | |
| O-Rings | 5,50 | 3,00 | | | | |
| O-Rings | 5,60 | 1,40 | | | 6-338 | |
| O-Rings | 5,60 | 1,80 | | | | |
| O-Rings | 5,60 | 2,40 | | | | |
| O-Rings | 5,70 | 1,90 | | | 5-582 | R5 |
| O-Rings | 5,70 | 3,20 | | | 6-548 | |
| O-Rings | 5,80 | 1,90 | | | | |

| | | | | | | |
|---------|------|------|------|-----|-------|-------|
| O-Rings | 5,94 | 3,53 | | 202 | 2-202 | |
| O-Rings | 6,00 | 1,00 | | | 6-543 | |
| O-Rings | 6,00 | 1,50 | | | 6-038 | |
| O-Rings | 6,00 | 1,80 | | | 9-051 | |
| O-Rings | 6,00 | 2,00 | | | 6-001 | |
| O-Rings | 6,00 | 2,20 | | | | R6BIS |
| O-Rings | 6,00 | 2,50 | | | | |
| O-Rings | 6,00 | 3,00 | | | 6-071 | |
| O-Rings | 6,00 | 4,00 | | | | |
| O-Rings | 6,00 | 4,50 | | | | |
| O-Rings | 6,00 | 5,00 | | | | |
| O-Rings | 6,00 | 6,00 | | | | |
| O-Rings | 6,02 | 2,62 | 3024 | 108 | 2-108 | |
| O-Rings | 6,07 | 1,63 | | 902 | 3-902 | |
| O-Rings | 6,07 | 1,78 | 2025 | 010 | 2-10 | |
| O-Rings | 6,10 | 1,60 | | | | |
| O-Rings | 6,20 | 1,50 | | | 6-344 | |
| O-Rings | 6,30 | 1,60 | | | 6-374 | |
| O-Rings | 6,30 | 1,80 | | | | |
| O-Rings | 6,30 | 2,40 | | | 9-054 | |
| O-Rings | 6,35 | 1,78 | | 803 | | R5BIS |
| O-Rings | 6,40 | 1,68 | | | 6-326 | |
| O-Rings | 6,40 | 1,90 | | | 5-583 | R5A |
| O-Rings | 6,50 | 1,00 | | | | |
| O-Rings | 6,50 | 1,50 | | | 6-581 | |
| O-Rings | 6,50 | 2,00 | | | 6-572 | |
| O-Rings | 6,50 | 2,50 | | | | |
| O-Rings | 6,50 | 3,00 | | | | |
| O-Rings | 6,60 | 1,50 | | | 6-480 | |
| O-Rings | 6,60 | 2,40 | | | | |

| | | | | | | |
|---------|------|------|------|-----|-------|----|
| O-Rings | 6,70 | 1,80 | | | | |
| O-Rings | 6,75 | 1,78 | 106 | 610 | 5-052 | |
| O-Rings | 6,80 | 1,80 | | | 9-057 | |
| O-Rings | 6,80 | 1,90 | | | | |
| O-Rings | 6,80 | 2,00 | | | 6-440 | |
| O-Rings | 6,90 | 1,80 | | | | |
| O-Rings | 7,00 | 1,00 | | | | |
| O-Rings | 7,00 | 1,20 | | | 9-058 | |
| O-Rings | 7,00 | 1,50 | | | 6-011 | |
| O-Rings | 7,00 | 1,60 | | | 6-052 | |
| O-Rings | 7,00 | 2,00 | | | 6-311 | |
| O-Rings | 7,00 | 2,50 | | | 6-028 | |
| O-Rings | 7,00 | 3,00 | | | 6-080 | |
| O-Rings | 7,00 | 4,00 | | | | |
| O-Rings | 7,00 | 5,00 | | | | |
| O-Rings | 7,00 | 6,00 | | | | |
| O-Rings | 7,10 | 1,60 | | | | |
| O-Rings | 7,10 | 1,80 | | | | |
| O-Rings | 7,20 | 1,90 | | | 5-584 | R6 |
| O-Rings | 7,20 | 2,00 | | | 6-117 | |
| O-Rings | 7,30 | 2,40 | | | 9-064 | |
| O-Rings | 7,30 | 2,70 | | | 6-162 | |
| O-Rings | 7,50 | 1,00 | | | | |
| O-Rings | 7,50 | 1,50 | | | 6-091 | |
| O-Rings | 7,50 | 1,80 | | | | |
| O-Rings | 7,50 | 2,00 | | | 6-432 | |
| O-Rings | 7,50 | 2,40 | | | | |
| O-Rings | 7,50 | 2,50 | | | 6-134 | |
| O-Rings | 7,50 | 3,00 | | | | |
| O-Rings | 7,52 | 3,53 | 4028 | 203 | 2-203 | |

| | | | | | | |
|---------|------|------|------|-----|-------|-----|
| O-Rings | 7,60 | 1,85 | | | 9-067 | |
| O-Rings | 7,60 | 2,40 | | | | |
| O-Rings | 7,60 | 2,62 | 3030 | 109 | 2-109 | |
| O-Rings | 7,65 | 1,63 | | 903 | 3-903 | |
| O-Rings | 7,65 | 1,78 | 2031 | 011 | 2-11 | |
| O-Rings | 7,65 | 2,65 | | | 9-069 | |
| O-Rings | 7,75 | 1,88 | | | 5-673 | |
| O-Rings | 7,80 | 1,90 | | | | |
| O-Rings | 7,80 | 3,60 | | | 6-317 | |
| O-Rings | 7,80 | 4,60 | | | 6-486 | |
| O-Rings | 7,94 | 1,78 | | 804 | | |
| O-Rings | 8,00 | 1,00 | | | 6-437 | |
| O-Rings | 8,00 | 1,25 | | | 6-592 | |
| O-Rings | 8,00 | 1,50 | | | 6-074 | |
| O-Rings | 8,00 | 1,80 | | | | |
| O-Rings | 8,00 | 1,88 | | | 5-585 | |
| O-Rings | 8,00 | 1,90 | | | | R6A |
| O-Rings | 8,00 | 2,00 | | | 6-002 | |
| O-Rings | 8,00 | 2,20 | | | 6-520 | |
| O-Rings | 8,00 | 2,50 | | | 6-564 | |
| O-Rings | 8,00 | 3,00 | | | 6-390 | |
| O-Rings | 8,00 | 3,50 | | | | |
| O-Rings | 8,00 | 4,00 | | | 9-075 | |
| O-Rings | 8,00 | 4,50 | | | | |
| O-Rings | 8,00 | 5,00 | | | | |
| O-Rings | 8,10 | 1,60 | | | 6-192 | |
| O-Rings | 8,20 | 1,50 | | | 6-345 | |
| O-Rings | 8,30 | 2,40 | | | 6-070 | |
| O-Rings | 8,50 | 1,00 | | | | |
| O-Rings | 8,50 | 1,50 | | | 9-078 | |

| | | | | | | |
|---------|------|------|------|-----|-------|-------|
| O-Rings | 8,50 | 1,80 | | | | |
| O-Rings | 8,50 | 2,00 | | | | |
| O-Rings | 8,50 | 2,50 | | | | |
| O-Rings | 8,50 | 3,00 | | | | |
| O-Rings | 8,60 | 2,40 | | | | |
| O-Rings | 8,73 | 1,78 | 108 | 611 | 5-612 | |
| O-Rings | 8,76 | 1,80 | | | | |
| O-Rings | 8,79 | 1,14 | | | 6-277 | |
| O-Rings | 8,80 | 1,90 | | | | |
| O-Rings | 8,90 | 1,80 | | | 6-111 | |
| O-Rings | 8,90 | 1,90 | | | 5-586 | R7 |
| O-Rings | 8,90 | 2,70 | | | 5-587 | R8 |
| O-Rings | 8,92 | 1,83 | | | 3-904 | |
| O-Rings | 9,00 | 1,00 | | | | |
| O-Rings | 9,00 | 1,20 | | | 9-082 | |
| O-Rings | 9,00 | 1,50 | | | 6-010 | |
| O-Rings | 9,00 | 1,80 | | | 6-120 | |
| O-Rings | 9,00 | 2,00 | | | 6-470 | |
| O-Rings | 9,00 | 2,20 | | | | R7BIS |
| O-Rings | 9,00 | 2,50 | | | 6-161 | |
| O-Rings | 9,00 | 3,00 | | | 9-086 | |
| O-Rings | 9,00 | 3,50 | | | | |
| O-Rings | 9,00 | 4,00 | | | | |
| O-Rings | 9,00 | 4,50 | | | | |
| O-Rings | 9,00 | 5,00 | | | | |
| O-Rings | 9,00 | 6,00 | | | | |
| O-Rings | 9,02 | 2,59 | | | 6-450 | |
| O-Rings | 9,10 | 1,60 | | | | |
| O-Rings | 9,12 | 3,53 | 4036 | 204 | 2-204 | |
| O-Rings | 9,13 | 2,62 | 109 | | 2-110 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-------|
| O-Rings | 9,17 | 2,62 | | | 6-310 | |
| O-Rings | 9,19 | 2,62 | 3037 | 110 | 2-110 | |
| O-Rings | 9,25 | 1,78 | 2037 | 012 | 2-12 | |
| O-Rings | 9,30 | 2,40 | | | 6-012 | |
| O-Rings | 9,30 | 2,62 | | | 6-127 | |
| O-Rings | 9,35 | 1,60 | | | 6-395 | |
| O-Rings | 9,40 | 2,10 | | | 6-346 | |
| O-Rings | 9,50 | 1,00 | | | | |
| O-Rings | 9,50 | 1,50 | | | | |
| O-Rings | 9,50 | 1,80 | | | | |
| O-Rings | 9,50 | 2,00 | | | | |
| O-Rings | 9,50 | 2,50 | | | | |
| O-Rings | 9,50 | 3,00 | | | | |
| O-Rings | 9,50 | 4,50 | | | | |
| O-Rings | 9,52 | 1,78 | | | | R8BIS |
| O-Rings | 9,53 | 1,60 | | | 6-373 | |
| O-Rings | 9,60 | 2,40 | | | | |
| O-Rings | 9,65 | 1,09 | | | 6-327 | |
| O-Rings | 9,75 | 1,78 | | | 5-212 | |
| O-Rings | 9,80 | 1,40 | | | 6-419 | |
| O-Rings | 9,80 | 1,90 | | | | |
| O-Rings | 9,80 | 2,40 | | | | |
| O-Rings | 9,80 | 2,62 | | | 6-506 | |
| O-Rings | 9,92 | 2,62 | 112 | 613 | 5-614 | |
| O-Rings | 10,00 | 1,00 | | | 6-116 | |
| O-Rings | 10,00 | 1,50 | | | 6-083 | |
| O-Rings | 10,00 | 1,80 | | | | |
| O-Rings | 10,00 | 2,00 | | | 6-003 | |
| O-Rings | 10,00 | 2,20 | | | 6-532 | |
| O-Rings | 10,00 | 2,50 | | | 6-105 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|----|
| O-Rings | 10,00 | 3,00 | | | 9-094 | |
| O-Rings | 10,00 | 3,50 | | | | |
| O-Rings | 10,00 | 4,00 | | | 9-095 | |
| O-Rings | 10,00 | 4,50 | | | | |
| O-Rings | 10,00 | 5,00 | | | | |
| O-Rings | 10,00 | 6,00 | | | | |
| O-Rings | 10,10 | 1,00 | | | 9-096 | |
| O-Rings | 10,10 | 1,60 | | | | |
| O-Rings | 10,15 | 1,40 | | | 6-571 | |
| O-Rings | 10,25 | 1,40 | | | 6-375 | |
| O-Rings | 10,30 | 2,40 | | | 6-475 | |
| O-Rings | 10,46 | 5,33 | | 309 | 2-309 | |
| O-Rings | 10,50 | 1,00 | | | | |
| O-Rings | 10,50 | 1,50 | | | 9-098 | |
| O-Rings | 10,50 | 2,00 | | | | |
| O-Rings | 10,50 | 2,40 | | | | |
| O-Rings | 10,50 | 2,50 | | | | |
| O-Rings | 10,50 | 2,70 | | | 5-588 | R9 |
| O-Rings | 10,50 | 3,00 | | | | |
| O-Rings | 10,50 | 4,50 | | | | |
| O-Rings | 10,52 | 1,83 | | | 3-905 | |
| O-Rings | 10,60 | 1,20 | | | 6-218 | |
| O-Rings | 10,60 | 1,80 | | | | |
| O-Rings | 10,60 | 2,40 | | | | |
| O-Rings | 10,69 | 3,53 | | 205 | 2-205 | |
| O-Rings | 10,78 | 2,62 | 3043 | 111 | 2-111 | |
| O-Rings | 10,80 | 1,50 | | | 6-551 | |
| O-Rings | 10,80 | 2,40 | | | | |
| O-Rings | 10,82 | 1,78 | 2043 | 013 | 2-13 | |
| O-Rings | 11,00 | 1,00 | | | | |

| | | | | | |
|---------|-------|------|-----|-----|-------|
| O-Rings | 11,00 | 1,50 | | | 6-084 |
| O-Rings | 11,00 | 2,00 | | | 6-086 |
| O-Rings | 11,00 | 2,40 | | | |
| O-Rings | 11,00 | 2,50 | | | 9-103 |
| O-Rings | 11,00 | 2,75 | | | 9-104 |
| O-Rings | 11,00 | 3,00 | | | 9-105 |
| O-Rings | 11,00 | 3,50 | | | |
| O-Rings | 11,00 | 4,00 | | | |
| O-Rings | 11,00 | 4,50 | | | |
| O-Rings | 11,00 | 5,00 | | | |
| O-Rings | 11,00 | 6,00 | | | |
| O-Rings | 11,10 | 1,60 | | | |
| O-Rings | 11,11 | 1,78 | 114 | 806 | 5-613 |
| O-Rings | 11,20 | 1,80 | | | |
| O-Rings | 11,30 | 2,40 | | | 6-471 |
| O-Rings | 11,40 | 2,10 | | | 6-347 |
| O-Rings | 11,50 | 1,00 | | | |
| O-Rings | 11,50 | 1,50 | | | 9-107 |
| O-Rings | 11,50 | 2,00 | | | |
| O-Rings | 11,50 | 2,40 | | | |
| O-Rings | 11,50 | 2,50 | | | 9-108 |
| O-Rings | 11,50 | 3,00 | | | |
| O-Rings | 11,60 | 2,40 | | | |
| O-Rings | 11,80 | 1,80 | | | |
| O-Rings | 11,89 | 1,78 | | | 6-366 |
| O-Rings | 11,89 | 1,98 | | | 3-906 |
| O-Rings | 11,91 | 2,62 | 115 | 614 | 5-615 |
| O-Rings | 12,00 | 1,00 | | | 6-438 |
| O-Rings | 12,00 | 1,50 | | | 6-053 |
| O-Rings | 12,00 | 1,70 | | | 9-112 |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 12,00 | 2,00 | | | 6-065 | |
| O-Rings | 12,00 | 2,50 | | | 9-114 | |
| O-Rings | 12,00 | 3,00 | | | 6-124 | |
| O-Rings | 12,00 | 3,50 | | | 9-116 | |
| O-Rings | 12,00 | 4,00 | | | 9-117 | |
| O-Rings | 12,00 | 4,50 | | | | |
| O-Rings | 12,00 | 5,00 | | | 9-118 | |
| O-Rings | 12,00 | 6,00 | | | | |
| O-Rings | 12,07 | 5,33 | | 310 | 2-310 | |
| O-Rings | 12,10 | 1,60 | | | | |
| O-Rings | 12,10 | 2,70 | | | 5-589 | R10 |
| O-Rings | 12,29 | 3,53 | 4050 | 206 | 2-206 | |
| O-Rings | 12,30 | 2,10 | | | 9-120 | |
| O-Rings | 12,30 | 2,40 | | | 6-058 | |
| O-Rings | 12,37 | 2,62 | 3050 | 112 | 2-112 | |
| O-Rings | 12,42 | 1,78 | 2050 | 014 | 2-14 | |
| O-Rings | 12,50 | 1,00 | | | | |
| O-Rings | 12,50 | 1,10 | | | 6-550 | |
| O-Rings | 12,50 | 1,50 | | | | |
| O-Rings | 12,50 | 1,80 | | | | |
| O-Rings | 12,50 | 2,00 | | | 6-198 | |
| O-Rings | 12,50 | 2,50 | | | 9-125 | |
| O-Rings | 12,50 | 3,00 | | | | |
| O-Rings | 12,60 | 2,40 | | | | |
| O-Rings | 12,70 | 2,62 | | 807 | | |
| O-Rings | 13,00 | 1,00 | | | 6-584 | |
| O-Rings | 13,00 | 1,50 | | | 6-033 | |
| O-Rings | 13,00 | 2,00 | | | 6-075 | |
| O-Rings | 13,00 | 2,50 | | | 6-016 | |
| O-Rings | 13,00 | 3,00 | | | 9-130 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 13,00 | 3,50 | | | 6-207 | |
| O-Rings | 13,00 | 3,60 | | | 9-132 | |
| O-Rings | 13,00 | 4,00 | | | | |
| O-Rings | 13,00 | 4,50 | | | | |
| O-Rings | 13,00 | 5,00 | | | | |
| O-Rings | 13,00 | 6,00 | | | | |
| O-Rings | 13,10 | 1,60 | | | 6-163 | |
| O-Rings | 13,10 | 2,62 | 117 | 615 | 5-616 | |
| O-Rings | 13,20 | 1,80 | | | | |
| O-Rings | 13,23 | 1,78 | | | 6-129 | |
| O-Rings | 13,30 | 2,40 | | | 9-135 | |
| O-Rings | 13,40 | 2,10 | | | 6-348 | |
| O-Rings | 13,46 | 2,08 | | | 3-907 | |
| O-Rings | 13,50 | 1,00 | | | | |
| O-Rings | 13,50 | 1,50 | | | | |
| O-Rings | 13,50 | 2,00 | | | | |
| O-Rings | 13,50 | 2,40 | | | | |
| O-Rings | 13,50 | 2,50 | | | | |
| O-Rings | 13,50 | 2,75 | | | 6-096 | |
| O-Rings | 13,50 | 3,00 | | | | |
| O-Rings | 13,59 | 2,69 | | | 5-590 | |
| O-Rings | 13,60 | 2,40 | | | | |
| O-Rings | 13,60 | 2,50 | | | 6-473 | |
| O-Rings | 13,60 | 2,70 | | | | R11 |
| O-Rings | 13,64 | 5,33 | | 311 | 2-311 | |
| O-Rings | 13,75 | 2,80 | | | 6-160 | |
| O-Rings | 13,80 | 2,40 | | | | |
| O-Rings | 13,87 | 3,53 | 4055 | 207 | 2-207 | |
| O-Rings | 13,94 | 2,62 | 3056 | 113 | 2-113 | |
| O-Rings | 14,00 | 1,00 | | | | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 14,00 | 1,10 | | | 9-139 |
| O-Rings | 14,00 | 1,50 | | | 6-143 |
| O-Rings | 14,00 | 1,60 | | | 9-141 |
| O-Rings | 14,00 | 1,78 | 2056 | 015 | 2-15 |
| O-Rings | 14,00 | 1,80 | | | |
| O-Rings | 14,00 | 2,00 | | | 6-090 |
| O-Rings | 14,00 | 2,50 | | | 6-067 |
| O-Rings | 14,00 | 2,65 | | | 9-145 |
| O-Rings | 14,00 | 3,00 | | | 9-146 |
| O-Rings | 14,00 | 3,50 | | | |
| O-Rings | 14,00 | 4,00 | | | |
| O-Rings | 14,00 | 5,00 | | | 9-147 |
| O-Rings | 14,00 | 6,00 | | | |
| O-Rings | 14,10 | 1,60 | | | |
| O-Rings | 14,20 | 2,60 | | | 9-148 |
| O-Rings | 14,20 | 2,80 | | | 9-149 |
| O-Rings | 14,30 | 2,40 | | | 6-135 |
| O-Rings | 14,48 | 2,69 | | | 5-239 |
| O-Rings | 14,50 | 1,00 | | | |
| O-Rings | 14,50 | 1,50 | | | |
| O-Rings | 14,50 | 1,60 | | | 6-397 |
| O-Rings | 14,50 | 1,80 | | | 9-151 |
| O-Rings | 14,50 | 2,00 | | | |
| O-Rings | 14,50 | 2,40 | | | |
| O-Rings | 14,50 | 2,50 | | | |
| O-Rings | 14,50 | 3,00 | | | |
| O-Rings | 14,60 | 2,40 | | | 6-340 |
| O-Rings | 14,80 | 2,40 | | | |
| O-Rings | 15,00 | 1,00 | | | |
| O-Rings | 15,00 | 1,50 | | | 6-118 |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 15,00 | 1,60 | | | 6-040 | |
| O-Rings | 15,00 | 1,80 | | | 6-085 | |
| O-Rings | 15,00 | 2,00 | | | 6-005 | |
| O-Rings | 15,00 | 2,50 | | | 6-106 | |
| O-Rings | 15,00 | 2,65 | | | | |
| O-Rings | 15,00 | 3,00 | | | 6-043 | |
| O-Rings | 15,00 | 3,20 | | | 6-072 | |
| O-Rings | 15,00 | 3,50 | | | | |
| O-Rings | 15,00 | 4,00 | | | | |
| O-Rings | 15,00 | 4,50 | | | | |
| O-Rings | 15,00 | 5,00 | | | 6-128 | |
| O-Rings | 15,00 | 6,00 | | | | |
| O-Rings | 15,08 | 2,62 | 119 | 616 | 5-243 | |
| O-Rings | 15,10 | 1,60 | | | | |
| O-Rings | 15,10 | 2,70 | | | 5-591 | R12 |
| O-Rings | 15,24 | 5,33 | | 312 | 2-312 | |
| O-Rings | 15,30 | 2,40 | | | 6-206 | |
| O-Rings | 15,30 | 2,70 | | | 9-158 | |
| O-Rings | 15,34 | 2,62 | | | 5-243 | |
| O-Rings | 15,40 | 2,10 | | | 6-349 | |
| O-Rings | 15,47 | 3,53 | 4061 | 208 | 2-208 | |
| O-Rings | 15,50 | 1,00 | | | | |
| O-Rings | 15,50 | 1,50 | | | | |
| O-Rings | 15,50 | 2,00 | | | | |
| O-Rings | 15,50 | 2,40 | | | | |
| O-Rings | 15,50 | 2,50 | | | | |
| O-Rings | 15,50 | 3,00 | | | | |
| O-Rings | 15,50 | 4,50 | | | | |
| O-Rings | 15,54 | 2,62 | 3062 | 114 | 2-114 | |
| O-Rings | 15,60 | 1,78 | 2062 | 016 | 2-16 | |

| | | | | | | |
|---------|-------|------|-----|-----|-------|--------|
| O-Rings | 15,60 | 2,40 | | | | |
| O-Rings | 15,88 | 2,62 | 121 | 809 | 5-617 | |
| O-Rings | 16,00 | 1,00 | | | 6-439 | |
| O-Rings | 16,00 | 1,25 | | | 9-161 | |
| O-Rings | 16,00 | 1,50 | | | 6-528 | |
| O-Rings | 16,00 | 1,80 | | | | |
| O-Rings | 16,00 | 1,90 | | | | R12BIS |
| O-Rings | 16,00 | 2,00 | | | 6-146 | |
| O-Rings | 16,00 | 2,50 | | | 6-562 | |
| O-Rings | 16,00 | 2,65 | | | | |
| O-Rings | 16,00 | 3,00 | | | 6-042 | |
| O-Rings | 16,00 | 3,50 | | | 9-166 | |
| O-Rings | 16,00 | 4,00 | | | 9-167 | |
| O-Rings | 16,00 | 4,50 | | | | |
| O-Rings | 16,00 | 5,00 | | | | |
| O-Rings | 16,00 | 6,00 | | | 6-358 | |
| O-Rings | 16,10 | 1,60 | | | | |
| O-Rings | 16,30 | 2,40 | | | 9-168 | |
| O-Rings | 16,36 | 2,21 | | | 3-908 | |
| O-Rings | 16,50 | 1,00 | | | | |
| O-Rings | 16,50 | 1,50 | | | | |
| O-Rings | 16,50 | 2,00 | | | | |
| O-Rings | 16,50 | 2,50 | | | | |
| O-Rings | 16,50 | 2,70 | | | 6-313 | |
| O-Rings | 16,50 | 3,00 | | | | |
| O-Rings | 16,54 | 2,62 | | | 9-169 | |
| O-Rings | 16,56 | 1,78 | | | 9-170 | |
| O-Rings | 16,58 | 1,50 | | | 6-297 | |
| O-Rings | 16,60 | 2,40 | | | | |
| O-Rings | 16,70 | 1,45 | | | 6-006 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 16,81 | 5,33 | | 313 | 2-313 | |
| O-Rings | 16,90 | 2,70 | | | 5-592 | R13 |
| O-Rings | 17,00 | 1,00 | | | | |
| O-Rings | 17,00 | 1,10 | | | 6-524 | |
| O-Rings | 17,00 | 1,50 | | | 6-476 | |
| O-Rings | 17,00 | 1,80 | | | | |
| O-Rings | 17,00 | 2,00 | | | 6-044 | |
| O-Rings | 17,00 | 2,50 | | | 9-175 | |
| O-Rings | 17,00 | 2,65 | | | | |
| O-Rings | 17,00 | 3,00 | | | 9-176 | |
| O-Rings | 17,00 | 3,50 | | | | |
| O-Rings | 17,00 | 4,00 | | | | |
| O-Rings | 17,00 | 4,50 | | | | |
| O-Rings | 17,00 | 5,00 | | | | |
| O-Rings | 17,04 | 3,53 | 4067 | 209 | 2-209 | |
| O-Rings | 17,10 | 1,60 | | | | |
| O-Rings | 17,12 | 2,62 | 3068 | 115 | 2-115 | |
| O-Rings | 17,17 | 1,78 | 2068 | 017 | 2-17 | |
| O-Rings | 17,30 | 2,40 | | | 9-179 | |
| O-Rings | 17,40 | 2,10 | | | 6-554 | |
| O-Rings | 17,40 | 2,50 | | | 6-388 | |
| O-Rings | 17,46 | 2,62 | | 810 | | |
| O-Rings | 17,50 | 1,00 | | | | |
| O-Rings | 17,50 | 1,50 | | | | |
| O-Rings | 17,50 | 2,00 | | | | |
| O-Rings | 17,50 | 2,40 | | | | |
| O-Rings | 17,50 | 2,50 | | | | |
| O-Rings | 17,50 | 3,00 | | | | |
| O-Rings | 17,60 | 2,40 | | | | |
| O-Rings | 17,80 | 2,40 | | | | |

| | | | | | | |
|---------|-------|------|-----|-----|-------------|-----|
| O-Rings | 17,80 | 2,50 | | | 9-180 | |
| O-Rings | 17,81 | 1,02 | | | 6-367 | |
| O-Rings | 17,86 | 2,62 | 123 | 617 | 5-256 | |
| O-Rings | 17,90 | 1,25 | | | 6-041 | |
| O-Rings | 17,93 | 2,46 | | | 3-909 | |
| O-Rings | 17,96 | 2,62 | | | 5-256/6-258 | |
| O-Rings | 18,00 | 1,00 | | | | |
| O-Rings | 18,00 | 1,50 | | | 6-087 | |
| O-Rings | 18,00 | 2,00 | | | 6-076 | |
| O-Rings | 18,00 | 2,20 | | | 9-183 | |
| O-Rings | 18,00 | 2,50 | | | 6-132 | |
| O-Rings | 18,00 | 2,65 | | | | |
| O-Rings | 18,00 | 3,00 | | | 6-425 | |
| O-Rings | 18,00 | 3,15 | | | 6-007 | |
| O-Rings | 18,00 | 3,50 | | | | |
| O-Rings | 18,00 | 3,55 | | | | |
| O-Rings | 18,00 | 4,00 | | | 6-125 | |
| O-Rings | 18,00 | 4,50 | | | | |
| O-Rings | 18,00 | 5,00 | | | | |
| O-Rings | 18,00 | 6,00 | | | | |
| O-Rings | 18,10 | 1,60 | | | | |
| O-Rings | 18,14 | 1,78 | | | 9-189 | |
| O-Rings | 18,20 | 3,00 | | | 6,396 | |
| O-Rings | 18,30 | 2,40 | | | 6-177 | |
| O-Rings | 18,30 | 3,60 | | | 5-594 | R15 |
| O-Rings | 18,40 | 2,70 | | | 5-593 | R14 |
| O-Rings | 18,42 | 5,33 | | 314 | 2-314 | |
| O-Rings | 18,50 | 1,00 | | | | |
| O-Rings | 18,50 | 1,50 | | | 6-308 | |
| O-Rings | 18,50 | 2,00 | | | | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 18,50 | 2,50 | | | 9-192 |
| O-Rings | 18,50 | 3,00 | | | |
| O-Rings | 18,60 | 2,00 | | | 6-499 |
| O-Rings | 18,60 | 2,40 | | | |
| O-Rings | 18,60 | 3,50 | | | 6-557 |
| O-Rings | 18,64 | 3,53 | 4075 | 210 | 2-210 |
| O-Rings | 18,72 | 2,62 | 3075 | 116 | 2-116 |
| O-Rings | 18,77 | 1,78 | 2075 | 018 | 2-18 |
| O-Rings | 18,80 | 2,40 | | | 6-223 |
| O-Rings | 19,00 | 0,80 | | | 6-295 |
| O-Rings | 19,00 | 1,00 | | | |
| O-Rings | 19,00 | 1,50 | | | 6-573 |
| O-Rings | 19,00 | 2,00 | | | 6-360 |
| O-Rings | 19,00 | 2,40 | | | 9-198 |
| O-Rings | 19,00 | 2,50 | | | 6-039 |
| O-Rings | 19,00 | 2,65 | | | |
| O-Rings | 19,00 | 3,00 | | | 9-200 |
| O-Rings | 19,00 | 3,50 | | | |
| O-Rings | 19,00 | 3,55 | | | |
| O-Rings | 19,00 | 4,00 | | | |
| O-Rings | 19,00 | 4,50 | | | |
| O-Rings | 19,00 | 5,00 | | | 6-404 |
| O-Rings | 19,00 | 6,00 | | | |
| O-Rings | 19,10 | 1,60 | | | |
| O-Rings | 19,18 | 2,46 | | | 3-910 |
| O-Rings | 19,20 | 3,00 | | | 6-593 |
| O-Rings | 19,30 | 2,40 | | | 6-503 |
| O-Rings | 19,40 | 2,10 | | | 6-350 |
| O-Rings | 19,50 | 1,00 | | | |
| O-Rings | 19,50 | 1,50 | | | 6-119 |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 19,50 | 2,00 | | | | |
| O-Rings | 19,50 | 2,50 | | | | |
| O-Rings | 19,50 | 3,00 | | | | |
| O-Rings | 19,50 | 6,00 | | | | |
| O-Rings | 19,60 | 2,40 | | | | |
| O-Rings | 19,80 | 2,40 | | | 6-300 | |
| O-Rings | 19,80 | 3,60 | | | 5-595 | R16 |
| O-Rings | 20,00 | 1,00 | | | | |
| O-Rings | 20,00 | 1,30 | | | 6-099 | |
| O-Rings | 20,00 | 1,50 | | | 6-078 | |
| O-Rings | 20,00 | 2,00 | | | 9-205 | |
| O-Rings | 20,00 | 2,50 | | | 6-017 | |
| O-Rings | 20,00 | 2,65 | | | | |
| O-Rings | 20,00 | 3,00 | | | 6-130 | |
| O-Rings | 20,00 | 3,50 | | | | |
| O-Rings | 20,00 | 3,55 | | | | |
| O-Rings | 20,00 | 4,00 | | | 9-208 | |
| O-Rings | 20,00 | 4,50 | | | | |
| O-Rings | 20,00 | 5,00 | | | 9-209 | |
| O-Rings | 20,00 | 5,33 | | 316 | 2-315 | |
| O-Rings | 20,00 | 6,00 | | | | |
| O-Rings | 20,20 | 3,00 | | | 6-382 | |
| O-Rings | 20,22 | 3,53 | 4081 | 211 | 2-211 | |
| O-Rings | 20,29 | 2,62 | 3081 | 117 | 2-117 | |
| O-Rings | 20,30 | 2,40 | | | 6-275 | |
| O-Rings | 20,34 | 4,25 | | | 6-212 | |
| O-Rings | 20,35 | 1,78 | 2081 | 019 | 2-19 | |
| O-Rings | 20,50 | 1,00 | | | | |
| O-Rings | 20,50 | 1,50 | | | | |
| O-Rings | 20,50 | 2,00 | | | 9-214 | |

| | | | | | | |
|---------|-------|------|-----|-----|-------|-----|
| O-Rings | 20,50 | 2,40 | | | | |
| O-Rings | 20,50 | 2,50 | | | | |
| O-Rings | 20,50 | 3,00 | | | | |
| O-Rings | 20,64 | 2,62 | 128 | 812 | | |
| O-Rings | 20,80 | 2,40 | | | | |
| O-Rings | 21,00 | 1,00 | | | | |
| O-Rings | 21,00 | 1,50 | | | 9-215 | |
| O-Rings | 21,00 | 2,00 | | | 6-008 | |
| O-Rings | 21,00 | 2,40 | | | 6-430 | |
| O-Rings | 21,00 | 2,50 | | | 9-218 | |
| O-Rings | 21,00 | 3,00 | | | 9-219 | |
| O-Rings | 21,00 | 3,50 | | | 6-089 | |
| O-Rings | 21,00 | 3,55 | | | | |
| O-Rings | 21,00 | 4,00 | | | 9-221 | |
| O-Rings | 21,00 | 4,50 | | | | |
| O-Rings | 21,00 | 5,00 | | | | |
| O-Rings | 21,00 | 6,00 | | | 6-489 | |
| O-Rings | 21,20 | 2,65 | | | | |
| O-Rings | 21,20 | 3,55 | | | | |
| O-Rings | 21,30 | 3,60 | | | 5-596 | R17 |
| O-Rings | 21,50 | 1,00 | | | | |
| O-Rings | 21,50 | 1,50 | | | 9-222 | |
| O-Rings | 21,50 | 1,78 | | | 6-343 | |
| O-Rings | 21,50 | 2,00 | | | | |
| O-Rings | 21,50 | 2,40 | | | | |
| O-Rings | 21,50 | 2,50 | | | | |
| O-Rings | 21,50 | 3,00 | | | | |
| O-Rings | 21,50 | 3,50 | | | 9-223 | |
| O-Rings | 21,50 | 4,50 | | | | |
| O-Rings | 21,59 | 5,33 | | 316 | 2-316 | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 21,60 | 2,40 | | | |
| O-Rings | 21,70 | 0,73 | | | 6-285 |
| O-Rings | 21,70 | 3,50 | | | |
| O-Rings | 21,80 | 2,40 | | | |
| O-Rings | 21,82 | 1,00 | | | 6-286 |
| O-Rings | 21,82 | 3,53 | 4087 | 212 | 2-212 |
| O-Rings | 21,89 | 2,62 | 3087 | 118 | 2-118 |
| O-Rings | 21,92 | 2,95 | | 911 | 3-911 |
| O-Rings | 21,95 | 1,78 | 2087 | 020 | 2-020 |
| O-Rings | 22,00 | 1,00 | | | |
| O-Rings | 22,00 | 1,30 | | | 9-227 |
| O-Rings | 22,00 | 1,40 | | | 6-493 |
| O-Rings | 22,00 | 1,50 | | | 6-088 |
| O-Rings | 22,00 | 2,00 | | | 6-139 |
| O-Rings | 22,00 | 2,50 | | | 6-036 |
| O-Rings | 22,00 | 3,00 | | | 9-231 |
| O-Rings | 22,00 | 3,50 | | | 9-232 |
| O-Rings | 22,00 | 3,55 | | | |
| O-Rings | 22,00 | 4,00 | | | 9-233 |
| O-Rings | 22,00 | 4,50 | | | |
| O-Rings | 22,00 | 5,00 | | | |
| O-Rings | 22,00 | 6,00 | | | |
| O-Rings | 22,10 | 1,60 | | | 6-356 |
| O-Rings | 22,10 | 3,50 | | | |
| O-Rings | 22,20 | 3,00 | | | 9-234 |
| O-Rings | 22,23 | 2,62 | 130 | 813 | |
| O-Rings | 22,30 | 2,40 | | | 9-235 |
| O-Rings | 22,40 | 2,65 | | | |
| O-Rings | 22,40 | 3,15 | | | 9-236 |
| O-Rings | 22,40 | 3,55 | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 22,50 | 1,00 | | | | |
| O-Rings | 22,50 | 1,50 | | | | |
| O-Rings | 22,50 | 2,00 | | | | |
| O-Rings | 22,50 | 2,50 | | | | |
| O-Rings | 22,50 | 3,00 | | | | |
| O-Rings | 22,50 | 4,50 | | | | |
| O-Rings | 22,70 | 1,50 | | | 6-263 | |
| O-Rings | 22,89 | 1,00 | | | 6-287 | |
| O-Rings | 23,00 | 1,00 | | | | |
| O-Rings | 23,00 | 1,50 | | | 9-237 | |
| O-Rings | 23,00 | 2,00 | | | 9-238 | |
| O-Rings | 23,00 | 2,50 | | | 6-066 | |
| O-Rings | 23,00 | 3,00 | | | 9-240 | |
| O-Rings | 23,00 | 3,50 | | | | |
| O-Rings | 23,00 | 3,55 | | | | |
| O-Rings | 23,00 | 3,60 | | | 5-597 | R18 |
| O-Rings | 23,00 | 4,00 | | | | |
| O-Rings | 23,00 | 4,50 | | | | |
| O-Rings | 23,00 | 5,00 | | | | |
| O-Rings | 23,00 | 6,00 | | | | |
| O-Rings | 23,16 | 5,33 | | 317 | 2-317 | |
| O-Rings | 23,39 | 3,53 | 4093 | 213 | 2-213 | |
| O-Rings | 23,47 | 2,62 | 3093 | 119 | 2-119 | |
| O-Rings | 23,47 | 2,95 | | | 3-912 | |
| O-Rings | 23,50 | 1,00 | | | | |
| O-Rings | 23,50 | 1,50 | | | | |
| O-Rings | 23,50 | 2,00 | | | | |
| O-Rings | 23,50 | 2,40 | | | | |
| O-Rings | 23,50 | 2,50 | | | | |
| O-Rings | 23,50 | 3,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 23,50 | 6,00 | | | | |
| O-Rings | 23,52 | 1,78 | 2093 | 021 | 2-21 | |
| O-Rings | 23,60 | 1,02 | | | 6-298 | |
| O-Rings | 23,60 | 2,65 | | | | |
| O-Rings | 23,60 | 3,55 | | | | |
| O-Rings | 23,70 | 3,50 | | | | |
| O-Rings | 23,81 | 2,62 | 132 | 814 | | |
| O-Rings | 24,00 | 1,00 | | | | |
| O-Rings | 24,00 | 1,50 | | | 6-544 | |
| O-Rings | 24,00 | 2,00 | | | 6-022 | |
| O-Rings | 24,00 | 2,50 | | | 6-595 | |
| O-Rings | 24,00 | 3,00 | | | 9-246 | |
| O-Rings | 24,00 | 3,50 | | | 9-247 | |
| O-Rings | 24,00 | 4,00 | | | 6-453 | |
| O-Rings | 24,00 | 4,50 | | | | |
| O-Rings | 24,00 | 5,00 | | | | |
| O-Rings | 24,00 | 6,00 | | | 6-443 | |
| O-Rings | 24,20 | 3,00 | | | 6-050 | |
| O-Rings | 24,32 | 1,00 | | | 6-288 | |
| O-Rings | 24,40 | 3,10 | | | | |
| O-Rings | 24,50 | 1,00 | | | | |
| O-Rings | 24,50 | 1,50 | | | | |
| O-Rings | 24,50 | 2,00 | | | | |
| O-Rings | 24,50 | 2,40 | | | | |
| O-Rings | 24,50 | 2,50 | | | | |
| O-Rings | 24,50 | 3,00 | | | | |
| O-Rings | 24,50 | 4,50 | | | | |
| O-Rings | 24,60 | 2,40 | | | | |
| O-Rings | 24,60 | 3,60 | | | 5-598 | R19 |
| O-Rings | 24,70 | 3,50 | | | | |

| | | | | | | |
|---------|-------|------|------|-------|-------|--------|
| O-Rings | 24,77 | 5,33 | | 318 | 2-318 | |
| O-Rings | 24,80 | 1,50 | | 6-092 | | |
| O-Rings | 25,00 | 1,00 | | | | |
| O-Rings | 25,00 | 1,50 | | | 9-249 | |
| O-Rings | 25,00 | 2,00 | | | 6-312 | |
| O-Rings | 25,00 | 2,20 | | | 9-251 | |
| O-Rings | 25,00 | 2,40 | | | | R19BIS |
| O-Rings | 25,00 | 2,50 | | | 9-252 | |
| O-Rings | 25,00 | 2,65 | | | | |
| O-Rings | 25,00 | 2,70 | | | 9-253 | |
| O-Rings | 25,00 | 3,00 | | | 9-254 | |
| O-Rings | 25,00 | 3,50 | | | | |
| O-Rings | 25,00 | 3,53 | 4100 | 214 | 2-214 | |
| O-Rings | 25,00 | 3,55 | | | | |
| O-Rings | 25,00 | 4,00 | | | 6-426 | |
| O-Rings | 25,00 | 4,50 | | | | |
| O-Rings | 25,00 | 5,00 | | | 6-376 | |
| O-Rings | 25,00 | 6,00 | | | | |
| O-Rings | 25,04 | 2,95 | | | 3-913 | |
| O-Rings | 25,07 | 2,62 | 3100 | 120 | 2-12 | |
| O-Rings | 25,10 | 1,60 | | | | |
| O-Rings | 25,12 | 1,78 | 2100 | 022 | 2-22 | |
| O-Rings | 25,20 | 3,50 | | | | |
| O-Rings | 25,30 | 1,60 | | | 6-126 | |
| O-Rings | 25,30 | 2,40 | | | 9-259 | |
| O-Rings | 25,50 | 1,50 | | | | |
| O-Rings | 25,50 | 2,00 | | | 6-189 | |
| O-Rings | 25,50 | 2,50 | | | | |
| O-Rings | 25,50 | 3,00 | | | | |
| O-Rings | 25,70 | 3,50 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 25,79 | 1,00 | | | 6-289 | |
| O-Rings | 25,80 | 2,65 | | | | |
| O-Rings | 25,80 | 3,30 | | | 6-387 | |
| O-Rings | 25,80 | 3,53 | 134 | 618 | 5-618 | |
| O-Rings | 25,80 | 3,55 | | | | |
| O-Rings | 26,00 | 1,00 | | | 9-260 | |
| O-Rings | 26,00 | 1,50 | | | 9-261 | |
| O-Rings | 26,00 | 2,00 | | | 9-262 | |
| O-Rings | 26,00 | 2,50 | | | 9-263 | |
| O-Rings | 26,00 | 3,00 | | | 9-264 | |
| O-Rings | 26,00 | 3,50 | | | 9-265 | |
| O-Rings | 26,00 | 4,00 | | | 9-266 | |
| O-Rings | 26,00 | 4,50 | | | | |
| O-Rings | 26,00 | 5,00 | | | 9-267 | |
| O-Rings | 26,00 | 6,00 | | | | |
| O-Rings | 26,20 | 3,00 | | | 9-268 | |
| O-Rings | 26,20 | 3,60 | | | 5-599 | R20 |
| O-Rings | 26,34 | 5,33 | | 319 | 2-319 | |
| O-Rings | 26,50 | 1,50 | | | | |
| O-Rings | 26,50 | 2,00 | | | | |
| O-Rings | 26,50 | 2,50 | | | | |
| O-Rings | 26,50 | 2,65 | | | | |
| O-Rings | 26,50 | 3,00 | | | | |
| O-Rings | 26,50 | 3,55 | | | | |
| O-Rings | 26,57 | 3,53 | 4106 | 215 | 2-215 | |
| O-Rings | 26,59 | 2,95 | | | 3-914 | |
| O-Rings | 26,64 | 2,62 | 3106 | 121 | 2-121 | |
| O-Rings | 26,70 | 1,78 | 2106 | 023 | 2-23 | |
| O-Rings | 26,70 | 2,50 | | | 6-208 | |
| O-Rings | 27,00 | 1,00 | | | | |

| | | | | | | |
|---------|-------|------|--|-----|-------|--------|
| O-Rings | 27,00 | 1,50 | | | 6-400 | |
| O-Rings | 27,00 | 2,00 | | | 6-049 | |
| O-Rings | 27,00 | 2,50 | | | 9-271 | |
| O-Rings | 27,00 | 3,00 | | | 6-147 | |
| O-Rings | 27,00 | 3,50 | | | 9-273 | |
| O-Rings | 27,00 | 4,00 | | | | |
| O-Rings | 27,00 | 4,50 | | | | |
| O-Rings | 27,00 | 5,00 | | | 9-274 | |
| O-Rings | 27,00 | 6,00 | | | | |
| O-Rings | 27,10 | 1,60 | | | | |
| O-Rings | 27,30 | 2,40 | | | 6-023 | |
| O-Rings | 27,30 | 2,70 | | | | R20TER |
| O-Rings | 27,50 | 1,50 | | | 6-497 | |
| O-Rings | 27,50 | 2,00 | | | | |
| O-Rings | 27,50 | 2,40 | | | | |
| O-Rings | 27,50 | 2,50 | | | | |
| O-Rings | 27,50 | 3,00 | | | | |
| O-Rings | 27,50 | 4,50 | | | | |
| O-Rings | 27,60 | 2,40 | | | | |
| O-Rings | 27,70 | 3,50 | | | | |
| O-Rings | 27,71 | 1,02 | | | 6-296 | |
| O-Rings | 27,80 | 3,60 | | | 5-600 | R21 |
| O-Rings | 27,94 | 5,33 | | 320 | 2-320 | |
| O-Rings | 28,00 | 1,00 | | | | |
| O-Rings | 28,00 | 1,50 | | | 6-101 | |
| O-Rings | 28,00 | 2,00 | | | 6-140 | |
| O-Rings | 28,00 | 2,20 | | | 6-180 | |
| O-Rings | 28,00 | 2,50 | | | 9-277 | |
| O-Rings | 28,00 | 2,65 | | | | |
| O-Rings | 28,00 | 3,00 | | | 9-278 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|--------|
| O-Rings | 28,00 | 3,50 | | | 9-279 | |
| O-Rings | 28,00 | 3,55 | | | | |
| O-Rings | 28,00 | 4,00 | | | 9-280 | |
| O-Rings | 28,00 | 4,50 | | | | |
| O-Rings | 28,00 | 5,00 | | | 9-281 | |
| O-Rings | 28,00 | 6,00 | | | | |
| O-Rings | 28,17 | 3,53 | 4112 | 216 | 2-216 | |
| O-Rings | 28,20 | 1,00 | | | 9-282 | |
| O-Rings | 28,24 | 2,62 | 3112 | 122 | 2-122 | |
| O-Rings | 28,30 | 1,78 | 2112 | 024 | 2-24 | |
| O-Rings | 28,50 | 1,50 | | | | |
| O-Rings | 28,50 | 2,00 | | | | |
| O-Rings | 28,50 | 2,50 | | | | |
| O-Rings | 28,50 | 3,00 | | | 9-283 | |
| O-Rings | 28,50 | 4,50 | | | | |
| O-Rings | 28,70 | 3,50 | | | | |
| O-Rings | 29,00 | 1,00 | | | | |
| O-Rings | 29,00 | 1,50 | | | | |
| O-Rings | 29,00 | 2,00 | | | | |
| O-Rings | 29,00 | 2,50 | | | | |
| O-Rings | 29,00 | 3,00 | | | 9-285 | |
| O-Rings | 29,00 | 3,50 | | | | |
| O-Rings | 29,00 | 4,00 | | | 9-286 | |
| O-Rings | 29,00 | 4,50 | | | | |
| O-Rings | 29,00 | 5,00 | | | | |
| O-Rings | 29,00 | 6,00 | | | | |
| O-Rings | 29,10 | 1,60 | | | | |
| O-Rings | 29,10 | 2,55 | | | | R20BIS |
| O-Rings | 29,20 | 3,00 | | | | |
| O-Rings | 29,20 | 3,50 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 29,30 | 3,60 | | | 5-601 | R22 |
| O-Rings | 29,40 | 3,10 | | | | |
| O-Rings | 29,50 | 1,50 | | | 6-034 | |
| O-Rings | 29,50 | 2,00 | | | | |
| O-Rings | 29,50 | 2,50 | | | | |
| O-Rings | 29,50 | 3,00 | | | | |
| O-Rings | 29,50 | 4,50 | | | 9-287 | |
| O-Rings | 29,51 | 5,33 | | 321 | 2-321 | |
| O-Rings | 29,60 | 2,40 | | | | |
| O-Rings | 29,70 | 2,80 | | | 6-352 | |
| O-Rings | 29,70 | 3,50 | | | | |
| O-Rings | 29,74 | 2,95 | | | 3-916 | |
| O-Rings | 29,74 | 3,53 | 4118 | 217 | 2-217 | |
| O-Rings | 29,82 | 2,62 | 3118 | 123 | 2-123 | |
| O-Rings | 29,87 | 1,78 | 2118 | 025 | 2-25 | |
| O-Rings | 30,00 | 1,00 | | | | |
| O-Rings | 30,00 | 1,50 | | | | |
| O-Rings | 30,00 | 2,00 | | | 6-048 | |
| O-Rings | 30,00 | 2,50 | | | 6-156 | |
| O-Rings | 30,00 | 2,65 | | | | |
| O-Rings | 30,00 | 3,00 | | | 6-056 | |
| O-Rings | 30,00 | 3,15 | | | 6-037 | |
| O-Rings | 30,00 | 3,50 | | | 9-292 | |
| O-Rings | 30,00 | 3,55 | | | | |
| O-Rings | 30,00 | 4,00 | | | 6-454 | |
| O-Rings | 30,00 | 4,50 | | | | |
| O-Rings | 30,00 | 5,00 | | | | |
| O-Rings | 30,00 | 6,00 | | | | |
| O-Rings | 30,30 | 2,40 | | | 6-290 | |
| O-Rings | 30,50 | 1,50 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 30,50 | 2,00 | | | | |
| O-Rings | 30,50 | 2,50 | | | | |
| O-Rings | 30,50 | 3,00 | | | | |
| O-Rings | 30,70 | 2,00 | | | 6-142 | |
| O-Rings | 30,70 | 3,50 | | | | |
| O-Rings | 30,80 | 3,60 | | | 5-602 | R23 |
| O-Rings | 31,00 | 1,00 | | | | |
| O-Rings | 31,00 | 1,50 | | | | |
| O-Rings | 31,00 | 2,00 | | | 9-295 | |
| O-Rings | 31,00 | 2,50 | | | 6-324 | |
| O-Rings | 31,00 | 3,00 | | | 9-296 | |
| O-Rings | 31,00 | 3,50 | | | | |
| O-Rings | 31,00 | 4,00 | | | | |
| O-Rings | 31,00 | 4,50 | | | 6-097 | |
| O-Rings | 31,00 | 5,00 | | | 6-315 | |
| O-Rings | 31,00 | 6,00 | | | | |
| O-Rings | 31,02 | 3,00 | | | 6-314 | |
| O-Rings | 31,12 | 5,33 | | 322 | 2-322 | |
| O-Rings | 31,20 | 3,50 | | | | |
| O-Rings | 31,34 | 3,53 | 4125 | 218 | 2-218 | |
| O-Rings | 31,42 | 2,62 | 3125 | 124 | 2-124 | |
| O-Rings | 31,47 | 1,78 | 2125 | 026 | 2-26 | |
| O-Rings | 31,50 | 1,50 | | | | |
| O-Rings | 31,50 | 2,00 | | | | |
| O-Rings | 31,50 | 2,50 | | | | |
| O-Rings | 31,50 | 2,65 | | | | |
| O-Rings | 31,50 | 3,00 | | | | |
| O-Rings | 31,50 | 3,15 | | | 9-298 | |
| O-Rings | 31,50 | 3,55 | | | | |
| O-Rings | 31,50 | 4,50 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 31,60 | 2,40 | | | | |
| O-Rings | 31,70 | 3,50 | | | | |
| O-Rings | 32,00 | 1,00 | | | | |
| O-Rings | 32,00 | 1,50 | | | | |
| O-Rings | 32,00 | 2,00 | | | 9-299 | |
| O-Rings | 32,00 | 2,50 | | | 9-300 | |
| O-Rings | 32,00 | 2,70 | | | 9-301 | |
| O-Rings | 32,00 | 3,00 | | | 9-302 | |
| O-Rings | 32,00 | 3,50 | | | | |
| O-Rings | 32,00 | 4,00 | | | 9-303 | |
| O-Rings | 32,00 | 4,50 | | | | |
| O-Rings | 32,00 | 5,00 | | | | |
| O-Rings | 32,00 | 6,00 | | | | |
| O-Rings | 32,10 | 1,60 | | | | |
| O-Rings | 32,20 | 3,00 | | | | |
| O-Rings | 32,50 | 1,50 | | | | |
| O-Rings | 32,50 | 2,00 | | | | |
| O-Rings | 32,50 | 2,20 | | | 6-131 | |
| O-Rings | 32,50 | 2,50 | | | | |
| O-Rings | 32,50 | 2,65 | | | | |
| O-Rings | 32,50 | 3,00 | | | | |
| O-Rings | 32,50 | 3,55 | | | | |
| O-Rings | 32,50 | 3,60 | | | 5-603 | R24 |
| O-Rings | 32,70 | 5,33 | | 323 | 2-323 | |
| O-Rings | 32,92 | 3,53 | 4131 | 219 | 2-219 | |
| O-Rings | 33,00 | 1,00 | | | | |
| O-Rings | 33,00 | 1,50 | | | | |
| O-Rings | 33,00 | 2,00 | | | | |
| O-Rings | 33,00 | 2,50 | | | 6-540 | |
| O-Rings | 33,00 | 2,62 | 3131 | 125 | 2-125 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 33,00 | 3,00 | | | 9-308 | |
| O-Rings | 33,00 | 3,50 | | | 9-309 | |
| O-Rings | 33,00 | 4,00 | | | | |
| O-Rings | 33,00 | 4,50 | | | | |
| O-Rings | 33,00 | 5,00 | | | | |
| O-Rings | 33,00 | 6,00 | | | | |
| O-Rings | 33,05 | 1,78 | 2131 | 027 | 2-27 | |
| O-Rings | 33,30 | 2,40 | | | 6-472 | |
| O-Rings | 33,50 | 1,50 | | | | |
| O-Rings | 33,50 | 2,00 | | | | |
| O-Rings | 33,50 | 2,50 | | | | |
| O-Rings | 33,50 | 2,65 | | | | |
| O-Rings | 33,50 | 3,00 | | | | |
| O-Rings | 33,50 | 3,55 | | | | |
| O-Rings | 33,70 | 3,50 | | | | |
| O-Rings | 34,00 | 1,00 | | | | |
| O-Rings | 34,00 | 1,50 | | | | |
| O-Rings | 34,00 | 2,00 | | | 9-311 | |
| O-Rings | 34,00 | 2,50 | | | 9-312 | |
| O-Rings | 34,00 | 3,00 | | | 9-313 | |
| O-Rings | 34,00 | 3,50 | | | | |
| O-Rings | 34,00 | 4,00 | | | | |
| O-Rings | 34,00 | 4,50 | | | | |
| O-Rings | 34,00 | 5,00 | | | 9-314 | |
| O-Rings | 34,00 | 6,00 | | | | |
| O-Rings | 34,10 | 3,60 | | | 5-604 | R25 |
| O-Rings | 34,20 | 3,00 | | | | |
| O-Rings | 34,29 | 5,33 | | 324 | 2-324 | |
| O-Rings | 34,40 | 3,10 | | | 6-585 | |
| O-Rings | 34,42 | 2,95 | | | 3-918 | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 34,50 | 1,50 | | | |
| O-Rings | 34,50 | 2,00 | | | |
| O-Rings | 34,50 | 2,50 | | | |
| O-Rings | 34,50 | 2,65 | | | |
| O-Rings | 34,50 | 3,00 | | | |
| O-Rings | 34,50 | 3,55 | | | |
| O-Rings | 34,50 | 4,50 | | | |
| O-Rings | 34,52 | 3,53 | 4137 | 220 | 2-220 |
| O-Rings | 34,60 | 2,40 | | | |
| O-Rings | 34,60 | 2,62 | 3137 | 126 | 2-126 |
| O-Rings | 34,65 | 1,78 | 2137 | 028 | 2-28 |
| O-Rings | 34,70 | 3,50 | | | |
| O-Rings | 35,00 | 1,00 | | | |
| O-Rings | 35,00 | 1,50 | | | |
| O-Rings | 35,00 | 2,00 | | | 6-047 |
| O-Rings | 35,00 | 2,50 | | | 9-318 |
| O-Rings | 35,00 | 2,60 | | | 9-319 |
| O-Rings | 35,00 | 3,00 | | | 9-320 |
| O-Rings | 35,00 | 3,20 | | | 9-321 |
| O-Rings | 35,00 | 3,50 | | | |
| O-Rings | 35,00 | 4,00 | | | 9-322 |
| O-Rings | 35,00 | 4,50 | | | 6-545 |
| O-Rings | 35,00 | 5,00 | | | 9-323 |
| O-Rings | 35,00 | 5,30 | | | 6-377 |
| O-Rings | 35,00 | 6,00 | | | |
| O-Rings | 35,10 | 1,60 | | | |
| O-Rings | 35,15 | 3,15 | | | 9-325 |
| O-Rings | 35,20 | 3,50 | | | |
| O-Rings | 35,50 | 1,50 | | | |
| O-Rings | 35,50 | 2,00 | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 35,50 | 2,50 | | | | |
| O-Rings | 35,50 | 2,65 | | | | |
| O-Rings | 35,50 | 3,00 | | | | |
| O-Rings | 35,50 | 3,55 | | | | |
| O-Rings | 35,50 | 4,50 | | | | |
| O-Rings | 35,60 | 3,60 | | | 5-605 | R26 |
| O-Rings | 35,70 | 3,50 | | | | |
| O-Rings | 36,00 | 1,00 | | | | |
| O-Rings | 36,00 | 1,50 | | | | |
| O-Rings | 36,00 | 2,00 | | | 9-326 | |
| O-Rings | 36,00 | 2,50 | | | 6-329 | |
| O-Rings | 36,00 | 3,00 | | | 9-327 | |
| O-Rings | 36,00 | 3,50 | | | | |
| O-Rings | 36,00 | 4,00 | | | 9-328 | |
| O-Rings | 36,00 | 4,50 | | | | |
| O-Rings | 36,00 | 5,00 | | | | |
| O-Rings | 36,00 | 6,00 | | | | |
| O-Rings | 36,10 | 3,53 | 4143 | 221 | 2-221 | |
| O-Rings | 36,17 | 2,62 | 3143 | 127 | 2-127 | |
| O-Rings | 36,20 | 3,00 | | | 9-331 | |
| O-Rings | 36,27 | 1,78 | | 517 | 6-154 | |
| O-Rings | 36,50 | 1,50 | | | | |
| O-Rings | 36,50 | 2,00 | | | | |
| O-Rings | 36,50 | 2,50 | | | | |
| O-Rings | 36,50 | 2,65 | | | | |
| O-Rings | 36,50 | 3,00 | | | | |
| O-Rings | 36,50 | 3,55 | | | | |
| O-Rings | 37,00 | 1,00 | | | | |
| O-Rings | 37,00 | 1,50 | | | | |
| O-Rings | 37,00 | 2,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 37,00 | 2,50 | | | 6-291 | |
| O-Rings | 37,00 | 2,60 | | | 9-332 | |
| O-Rings | 37,00 | 3,00 | | | 9-333 | |
| O-Rings | 37,00 | 3,50 | | | 9-334 | |
| O-Rings | 37,00 | 4,00 | | | 9-335 | |
| O-Rings | 37,00 | 4,50 | | | | |
| O-Rings | 37,00 | 5,00 | | | 6-555 | |
| O-Rings | 37,00 | 6,00 | | | | |
| O-Rings | 37,10 | 1,60 | | | 9-337 | |
| O-Rings | 37,30 | 3,60 | | | 5-606 | R27 |
| O-Rings | 37,47 | 3,00 | | | 3-920 | |
| O-Rings | 37,47 | 5,33 | 6150 | 325 | 2-325 | R28 |
| O-Rings | 37,50 | 1,50 | | | | |
| O-Rings | 37,50 | 2,00 | | | | |
| O-Rings | 37,50 | 2,50 | | | | |
| O-Rings | 37,50 | 2,65 | | | | |
| O-Rings | 37,50 | 3,00 | | | | |
| O-Rings | 37,50 | 3,55 | | | | |
| O-Rings | 37,50 | 4,50 | | | | |
| O-Rings | 37,56 | 2,60 | | | 6-459 | |
| O-Rings | 37,60 | 2,40 | | | | |
| O-Rings | 37,69 | 3,53 | 4150 | 222 | 2-222 | |
| O-Rings | 37,70 | 3,50 | | | 9-338 | |
| O-Rings | 37,77 | 2,62 | 3150 | 128 | 2-128 | |
| O-Rings | 37,82 | 1,78 | 2150 | 029 | 2-29 | |
| O-Rings | 38,00 | 1,00 | | | | |
| O-Rings | 38,00 | 1,50 | | | | |
| O-Rings | 38,00 | 2,00 | | | 6-046 | |
| O-Rings | 38,00 | 2,50 | | | 6-433 | |
| O-Rings | 38,00 | 3,00 | | | 9-342 | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 38,00 | 3,50 | | | 9-343 |
| O-Rings | 38,00 | 4,00 | | | |
| O-Rings | 38,00 | 4,50 | | | |
| O-Rings | 38,00 | 5,00 | | | 6-221 |
| O-Rings | 38,00 | 6,00 | | | |
| O-Rings | 38,50 | 1,50 | | | |
| O-Rings | 38,50 | 2,00 | | | |
| O-Rings | 38,50 | 2,50 | | | |
| O-Rings | 38,50 | 2,65 | | | |
| O-Rings | 38,50 | 3,00 | | | |
| O-Rings | 38,70 | 2,65 | | | |
| O-Rings | 38,70 | 2,80 | | | 6-353 |
| O-Rings | 38,70 | 3,55 | | | |
| O-Rings | 39,00 | 1,00 | | | |
| O-Rings | 39,00 | 1,50 | | | |
| O-Rings | 39,00 | 2,00 | | | 6-575 |
| O-Rings | 39,00 | 2,50 | | | |
| O-Rings | 39,00 | 3,00 | | | 9-345 |
| O-Rings | 39,00 | 3,50 | | | |
| O-Rings | 39,00 | 4,00 | | | |
| O-Rings | 39,00 | 4,50 | | | |
| O-Rings | 39,00 | 5,00 | | | |
| O-Rings | 39,00 | 6,00 | | | |
| O-Rings | 39,20 | 3,00 | | | 6-205 |
| O-Rings | 39,34 | 2,62 | 3156 | 129 | 2-129 |
| O-Rings | 39,40 | 3,10 | | | 6-586 |
| O-Rings | 39,45 | 1,78 | | 519 | |
| O-Rings | 39,50 | 1,50 | | | |
| O-Rings | 39,50 | 2,00 | | | |
| O-Rings | 39,50 | 2,50 | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 39,50 | 3,00 | | | | |
| O-Rings | 39,50 | 6,00 | | | | |
| O-Rings | 39,60 | 2,40 | | | | |
| O-Rings | 39,60 | 3,53 | | | 5-321 | |
| O-Rings | 39,70 | 3,50 | | | | |
| O-Rings | 39,70 | 3,53 | 144 | 824 | 5-321 | |
| O-Rings | 40,00 | 1,00 | | | | |
| O-Rings | 40,00 | 1,50 | | | | |
| O-Rings | 40,00 | 2,00 | | | 6-027 | |
| O-Rings | 40,00 | 2,50 | | | 6-566 | |
| O-Rings | 40,00 | 3,00 | | | 6-292 | |
| O-Rings | 40,00 | 3,15 | | | 9-349 | |
| O-Rings | 40,00 | 3,50 | | | | |
| O-Rings | 40,00 | 3,55 | | | | |
| O-Rings | 40,00 | 4,00 | | | 9-350 | |
| O-Rings | 40,00 | 4,50 | | | | |
| O-Rings | 40,00 | 5,00 | | | 9-351 | |
| O-Rings | 40,00 | 5,30 | | | | |
| O-Rings | 40,00 | 6,00 | | | 9-352 | |
| O-Rings | 40,50 | 4,50 | | | | |
| O-Rings | 40,60 | 4,00 | | | 6-102 | |
| O-Rings | 40,65 | 5,33 | 6162 | 326 | 2-326 | R29 |
| O-Rings | 40,87 | 3,53 | 4162 | 223 | 2-223 | |
| O-Rings | 40,94 | 2,62 | 3162 | 130 | 2-130 | |
| O-Rings | 41,00 | 1,00 | | | | |
| O-Rings | 41,00 | 1,50 | | | | |
| O-Rings | 41,00 | 1,78 | 2162 | 030 | 2-30 | |
| O-Rings | 41,00 | 2,00 | | | | |
| O-Rings | 41,00 | 2,50 | | | 6-541 | |
| O-Rings | 41,00 | 3,00 | | | 6-449 | |

| | | | | | | |
|---------|-------|------|-----|-----|-------|--------|
| O-Rings | 41,00 | 3,50 | | | | |
| O-Rings | 41,00 | 4,00 | | | | |
| O-Rings | 41,00 | 4,50 | | | | |
| O-Rings | 41,00 | 5,00 | | | | |
| O-Rings | 41,00 | 6,00 | | | | |
| O-Rings | 41,20 | 3,55 | | | | |
| O-Rings | 41,20 | 5,30 | | | | |
| O-Rings | 41,28 | 3,53 | 146 | 825 | 6-525 | |
| O-Rings | 41,40 | 2,62 | | | 6-337 | |
| O-Rings | 41,40 | 5,30 | | | | |
| O-Rings | 41,40 | 5,33 | | | | R29BIS |
| O-Rings | 41,50 | 1,50 | | | 6-434 | |
| O-Rings | 41,50 | 3,00 | | | | |
| O-Rings | 41,50 | 6,00 | | | | |
| O-Rings | 41,60 | 2,40 | | | | |
| O-Rings | 41,70 | 3,50 | | | | |
| O-Rings | 41,85 | 2,62 | | | 6-414 | |
| O-Rings | 42,00 | 1,00 | | | | |
| O-Rings | 42,00 | 1,50 | | | 6-015 | |
| O-Rings | 42,00 | 2,00 | | | | |
| O-Rings | 42,00 | 2,50 | | | 6-594 | |
| O-Rings | 42,00 | 2,70 | | | 9-357 | |
| O-Rings | 42,00 | 3,00 | | | 6-227 | |
| O-Rings | 42,00 | 3,50 | | | 9-359 | |
| O-Rings | 42,00 | 4,00 | | | | |
| O-Rings | 42,00 | 4,50 | | | | |
| O-Rings | 42,00 | 5,00 | | | | |
| O-Rings | 42,00 | 6,00 | | | | |
| O-Rings | 42,06 | 2,62 | | | 6-414 | |
| O-Rings | 42,20 | 3,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|--------|
| O-Rings | 42,50 | 3,00 | | | | |
| O-Rings | 42,50 | 3,55 | | | | |
| O-Rings | 42,50 | 5,30 | | | | |
| O-Rings | 42,50 | 8,00 | | | 6-225 | |
| O-Rings | 42,52 | 2,62 | 3168 | 131 | 2-131 | |
| O-Rings | 42,52 | 5,33 | | | 5-330 | |
| O-Rings | 42,86 | 3,53 | 147 | 826 | 5-332 | |
| O-Rings | 43,00 | 1,00 | | | | |
| O-Rings | 43,00 | 1,50 | | | | |
| O-Rings | 43,00 | 2,00 | | | | |
| O-Rings | 43,00 | 2,50 | | | | |
| O-Rings | 43,00 | 3,00 | | | 9-360 | |
| O-Rings | 43,00 | 3,50 | | | 9-361 | |
| O-Rings | 43,00 | 4,00 | | | 9-362 | |
| O-Rings | 43,00 | 4,50 | | | | |
| O-Rings | 43,00 | 5,00 | | | 9-363 | |
| O-Rings | 43,00 | 6,00 | | | | |
| O-Rings | 43,40 | 3,60 | | | | R29TER |
| O-Rings | 43,69 | 3,00 | | | 3-924 | |
| O-Rings | 43,70 | 3,50 | | | | |
| O-Rings | 43,70 | 3,55 | | | | |
| O-Rings | 43,70 | 5,30 | | | | |
| O-Rings | 43,82 | 5,33 | 6175 | 327 | 2-327 | R30 |
| O-Rings | 44,00 | 1,00 | | | | |
| O-Rings | 44,00 | 1,50 | | | | |
| O-Rings | 44,00 | 2,00 | | | 6-431 | |
| O-Rings | 44,00 | 2,50 | | | | |
| O-Rings | 44,00 | 3,00 | | | 9-364 | |
| O-Rings | 44,00 | 3,50 | | | 9-365 | |
| O-Rings | 44,00 | 4,00 | | | 9-366 | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 44,00 | 4,50 | | | |
| O-Rings | 44,00 | 5,00 | | | |
| O-Rings | 44,00 | 6,00 | | | |
| O-Rings | 44,04 | 3,53 | 4175 | 224 | 2-224 |
| O-Rings | 44,17 | 1,78 | 2175 | 031 | 2-31 |
| O-Rings | 44,20 | 2,50 | | | 6-542 |
| O-Rings | 44,20 | 3,00 | | | |
| O-Rings | 44,20 | 5,70 | | | |
| O-Rings | 44,30 | 5,70 | | | |
| O-Rings | 44,35 | 3,00 | | | 6-193 |
| O-Rings | 44,40 | 3,10 | | | |
| O-Rings | 44,45 | 3,53 | 149 | 827 | |
| O-Rings | 44,50 | 3,00 | | | |
| O-Rings | 44,50 | 6,00 | | | |
| O-Rings | 44,60 | 2,40 | | | |
| O-Rings | 44,70 | 3,50 | | | |
| O-Rings | 45,00 | 1,00 | | | |
| O-Rings | 45,00 | 1,50 | | | 6-082 |
| O-Rings | 45,00 | 2,00 | | | 6-054 |
| O-Rings | 45,00 | 2,50 | | | 6-323 |
| O-Rings | 45,00 | 3,00 | | | 9-370 |
| O-Rings | 45,00 | 3,50 | | | |
| O-Rings | 45,00 | 3,55 | | | |
| O-Rings | 45,00 | 4,00 | | | 9-371 |
| O-Rings | 45,00 | 4,50 | | | 9-372 |
| O-Rings | 45,00 | 5,00 | | | |
| O-Rings | 45,00 | 5,30 | | | |
| O-Rings | 45,00 | 6,00 | | | |
| O-Rings | 45,30 | 5,70 | | | |
| O-Rings | 45,36 | 3,53 | | | 5-035 |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 45,70 | 2,62 | 3181 | 133 | 2-133 | |
| O-Rings | 45,70 | 3,50 | | | | |
| O-Rings | 46,00 | 1,00 | | | | |
| O-Rings | 46,00 | 1,50 | | | | |
| O-Rings | 46,00 | 2,00 | | | 9-374 | |
| O-Rings | 46,00 | 2,50 | | | | |
| O-Rings | 46,00 | 3,00 | | | 9-375 | |
| O-Rings | 46,00 | 3,50 | | | 9-376 | |
| O-Rings | 46,00 | 4,00 | | | 9-377 | |
| O-Rings | 46,00 | 4,50 | | | | |
| O-Rings | 46,00 | 5,00 | | | 9-378 | |
| O-Rings | 46,00 | 6,00 | | | | |
| O-Rings | 46,02 | 3,53 | | | 6-159 | |
| O-Rings | 46,04 | 3,53 | 150 | 828 | 5-035 | |
| O-Rings | 46,20 | 3,55 | | | | |
| O-Rings | 46,20 | 5,30 | | | | |
| O-Rings | 46,70 | 2,80 | | | 6-354 | |
| O-Rings | 46,78 | 2,62 | | | 6-423 | |
| O-Rings | 47,00 | 1,00 | | | | |
| O-Rings | 47,00 | 1,50 | | | | |
| O-Rings | 47,00 | 2,00 | | | 6-537 | |
| O-Rings | 47,00 | 2,50 | | | 9-380 | |
| O-Rings | 47,00 | 3,00 | | | 9-381 | |
| O-Rings | 47,00 | 3,50 | | | | |
| O-Rings | 47,00 | 4,00 | | | 9-382 | |
| O-Rings | 47,00 | 4,50 | | | | |
| O-Rings | 47,00 | 5,00 | | | | |
| O-Rings | 47,00 | 5,33 | 6187 | 328 | 2-328 | R31 |
| O-Rings | 47,00 | 6,00 | | | | |
| O-Rings | 47,20 | 2,60 | | | 9-383 | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 47,20 | 5,70 | | | 6-293 |
| O-Rings | 47,22 | 3,53 | 4187 | 225 | 2-225 |
| O-Rings | 47,29 | 2,62 | 3187 | 134 | 2-134 |
| O-Rings | 47,50 | 1,78 | 2187 | 032 | 2-32 |
| O-Rings | 47,50 | 3,55 | | | |
| O-Rings | 47,50 | 4,00 | | | 6-009 |
| O-Rings | 47,50 | 5,30 | | | |
| O-Rings | 47,60 | 2,40 | | | |
| O-Rings | 47,60 | 5,70 | | | |
| O-Rings | 47,62 | 3,53 | 152 | 829 | |
| O-Rings | 47,70 | 3,50 | | | |
| O-Rings | 48,00 | 1,00 | | | |
| O-Rings | 48,00 | 1,50 | | | |
| O-Rings | 48,00 | 2,00 | | | 6-370 |
| O-Rings | 48,00 | 2,50 | | | |
| O-Rings | 48,00 | 3,00 | | | 6-155 |
| O-Rings | 48,00 | 3,50 | | | |
| O-Rings | 48,00 | 4,00 | | | |
| O-Rings | 48,00 | 4,50 | | | |
| O-Rings | 48,00 | 5,00 | | | |
| O-Rings | 48,00 | 6,00 | | | |
| O-Rings | 48,40 | 4,85 | | | 6-435 |
| O-Rings | 48,70 | 3,50 | | | |
| O-Rings | 48,70 | 3,55 | | | |
| O-Rings | 48,70 | 5,30 | | | |
| O-Rings | 48,90 | 2,62 | 3193 | 135 | 2-135 |
| O-Rings | 48,90 | 5,33 | | | 5-338 |
| O-Rings | 49,00 | 1,00 | | | |
| O-Rings | 49,00 | 1,50 | | | |
| O-Rings | 49,00 | 2,00 | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 49,00 | 2,50 | | | 9-390 | |
| O-Rings | 49,00 | 3,00 | | | 9-391 | |
| O-Rings | 49,00 | 3,50 | | | | |
| O-Rings | 49,00 | 4,00 | | | | |
| O-Rings | 49,00 | 4,50 | | | | |
| O-Rings | 49,00 | 5,00 | | | | |
| O-Rings | 49,00 | 6,00 | | | | |
| O-Rings | 49,20 | 3,53 | 153 | 830 | 5-701 | |
| O-Rings | 49,20 | 5,70 | | | | |
| O-Rings | 49,30 | 5,70 | | | | |
| O-Rings | 49,40 | 3,10 | | | | |
| O-Rings | 49,50 | 3,00 | | | 6-194 | |
| O-Rings | 49,60 | 2,40 | | | | |
| O-Rings | 49,60 | 5,70 | | | | |
| O-Rings | 49,70 | 3,50 | | | | |
| O-Rings | 50,00 | 1,00 | | | | |
| O-Rings | 50,00 | 1,50 | | | | |
| O-Rings | 50,00 | 2,00 | | | 6-051 | |
| O-Rings | 50,00 | 2,50 | | | 6-055 | |
| O-Rings | 50,00 | 3,00 | | | 9-394 | |
| O-Rings | 50,00 | 3,50 | | | 9-395 | |
| O-Rings | 50,00 | 3,55 | | | | |
| O-Rings | 50,00 | 4,00 | | | 9-396 | |
| O-Rings | 50,00 | 4,50 | | | | |
| O-Rings | 50,00 | 5,00 | | | | |
| O-Rings | 50,00 | 5,30 | | | | |
| O-Rings | 50,00 | 6,00 | | | 9-397 | |
| O-Rings | 50,17 | 5,33 | 6200 | 329 | 2-329 | R32 |
| O-Rings | 50,39 | 3,53 | 4200 | 226 | 2-226 | |
| O-Rings | 50,47 | 2,62 | 3200 | 136 | 2-136 | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 50,50 | 3,00 | | | |
| O-Rings | 50,52 | 1,78 | 2200 | 033 | 2-33 |
| O-Rings | 50,80 | 3,53 | 155 | 831 | |
| O-Rings | 51,00 | 1,50 | | | |
| O-Rings | 51,00 | 2,00 | | | |
| O-Rings | 51,00 | 2,50 | | | |
| O-Rings | 51,00 | 3,00 | | | 9-398 |
| O-Rings | 51,00 | 3,50 | | | |
| O-Rings | 51,00 | 4,00 | | | |
| O-Rings | 51,00 | 4,50 | | | |
| O-Rings | 51,00 | 5,00 | | | |
| O-Rings | 51,00 | 6,00 | | | |
| O-Rings | 51,50 | 3,55 | | | |
| O-Rings | 51,50 | 5,30 | | | |
| O-Rings | 51,60 | 2,40 | | | |
| O-Rings | 51,60 | 5,70 | | | |
| O-Rings | 51,71 | 3,53 | | | 5-037 |
| O-Rings | 52,00 | 1,50 | | | |
| O-Rings | 52,00 | 2,00 | | | |
| O-Rings | 52,00 | 2,50 | | | 9-399 |
| O-Rings | 52,00 | 3,00 | | | 9-400 |
| O-Rings | 52,00 | 3,50 | | | 9-401 |
| O-Rings | 52,00 | 4,00 | | | 9-402 |
| O-Rings | 52,00 | 5,00 | | | |
| O-Rings | 52,00 | 6,00 | | | |
| O-Rings | 52,07 | 2,62 | 3206 | 137 | 2-137 |
| O-Rings | 52,30 | 5,70 | | | |
| O-Rings | 52,40 | 3,53 | 156 | 832 | 5-037 |
| O-Rings | 52,50 | 5,70 | | | |
| O-Rings | 52,60 | 0,80 | | | 9-403 |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 52,60 | 2,80 | | | 6-284 | |
| O-Rings | 52,60 | 5,70 | | | | |
| O-Rings | 53,00 | 1,50 | | | | |
| O-Rings | 53,00 | 2,00 | | | | |
| O-Rings | 53,00 | 2,50 | | | | |
| O-Rings | 53,00 | 3,00 | | | 9-404 | |
| O-Rings | 53,00 | 3,50 | | | 9-405 | |
| O-Rings | 53,00 | 3,55 | | | | |
| O-Rings | 53,00 | 4,00 | | | 9-406 | |
| O-Rings | 53,00 | 4,50 | | | | |
| O-Rings | 53,00 | 5,00 | | | 6-113 | |
| O-Rings | 53,00 | 5,30 | | | | |
| O-Rings | 53,00 | 6,00 | | | | |
| O-Rings | 53,00 | 6,50 | | | 6-112 | |
| O-Rings | 53,09 | 3,00 | | | 3-928 | |
| O-Rings | 53,34 | 5,33 | 6212 | 330 | 2-330 | R33 |
| O-Rings | 53,57 | 3,53 | 4212 | 227 | 2-227 | |
| O-Rings | 53,64 | 2,62 | 3212 | 138 | 2-138 | |
| O-Rings | 53,70 | 1,78 | 2212 | 034 | 2-34 | |
| O-Rings | 53,97 | 3,53 | 158 | 833 | | |
| O-Rings | 54,00 | 1,50 | | | | |
| O-Rings | 54,00 | 2,00 | | | 9-408 | |
| O-Rings | 54,00 | 2,50 | | | | |
| O-Rings | 54,00 | 3,00 | | | 9-409 | |
| O-Rings | 54,00 | 3,50 | | | | |
| O-Rings | 54,00 | 4,00 | | | 9-410 | |
| O-Rings | 54,00 | 5,00 | | | | |
| O-Rings | 54,00 | 6,00 | | | | |
| O-Rings | 54,20 | 5,70 | | | | |
| O-Rings | 54,30 | 5,70 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|--------|
| O-Rings | 54,40 | 3,10 | | | | |
| O-Rings | 54,40 | 5,30 | | | | R33BIS |
| O-Rings | 54,50 | 3,00 | | | | |
| O-Rings | 54,50 | 3,55 | | | | |
| O-Rings | 54,50 | 5,30 | | | | |
| O-Rings | 54,60 | 2,40 | | | | |
| O-Rings | 54,60 | 5,70 | | | | |
| O-Rings | 55,00 | 1,50 | | | | |
| O-Rings | 55,00 | 2,00 | | | 6-141 | |
| O-Rings | 55,00 | 2,50 | | | 9-412 | |
| O-Rings | 55,00 | 3,00 | | | 9-413 | |
| O-Rings | 55,00 | 3,50 | | | | |
| O-Rings | 55,00 | 4,00 | | | 9-414 | |
| O-Rings | 55,00 | 4,50 | | | | |
| O-Rings | 55,00 | 5,00 | | | | |
| O-Rings | 55,00 | 6,00 | | | | |
| O-Rings | 55,25 | 2,62 | 3218 | 139 | 2-139 | |
| O-Rings | 55,30 | 5,70 | | | | |
| O-Rings | 55,56 | 3,53 | 159 | 834 | | |
| O-Rings | 55,60 | 5,70 | | | | |
| O-Rings | 56,00 | 1,50 | | | | |
| O-Rings | 56,00 | 2,00 | | | 6-568 | |
| O-Rings | 56,00 | 2,20 | | | 6-064 | |
| O-Rings | 56,00 | 2,50 | | | | |
| O-Rings | 56,00 | 3,00 | | | | |
| O-Rings | 56,00 | 3,50 | | | | |
| O-Rings | 56,00 | 3,55 | | | | |
| O-Rings | 56,00 | 4,00 | | | | |
| O-Rings | 56,00 | 4,50 | | | | |
| O-Rings | 56,00 | 5,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 56,00 | 5,30 | | | | |
| O-Rings | 56,00 | 6,00 | | | | |
| O-Rings | 56,20 | 3,00 | | | 9-416 | |
| O-Rings | 56,52 | 5,33 | 6225 | 331 | 2-331 | R34 |
| O-Rings | 56,74 | 3,53 | 4225 | 228 | 2-228 | |
| O-Rings | 56,82 | 2,62 | 3225 | 140 | 2-140 | |
| O-Rings | 56,87 | 1,78 | 2225 | 035 | 2-35 | |
| O-Rings | 57,00 | 1,50 | | | | |
| O-Rings | 57,00 | 2,00 | | | | |
| O-Rings | 57,00 | 2,50 | | | 9-419 | |
| O-Rings | 57,00 | 3,00 | | | 6-427 | |
| O-Rings | 57,00 | 3,50 | | | | |
| O-Rings | 57,00 | 4,00 | | | 9-421 | |
| O-Rings | 57,00 | 4,50 | | | | |
| O-Rings | 57,00 | 5,00 | | | | |
| O-Rings | 57,00 | 6,00 | | | | |
| O-Rings | 57,15 | 3,53 | 161 | 835 | | |
| O-Rings | 57,60 | 2,40 | | | | |
| O-Rings | 57,60 | 5,70 | | | | |
| O-Rings | 58,00 | 1,50 | | | | |
| O-Rings | 58,00 | 2,00 | | | 6-447 | |
| O-Rings | 58,00 | 2,50 | | | | |
| O-Rings | 58,00 | 3,00 | | | | |
| O-Rings | 58,00 | 3,50 | | | 9-423 | |
| O-Rings | 58,00 | 3,55 | | | | |
| O-Rings | 58,00 | 4,00 | | | 6-109 | |
| O-Rings | 58,00 | 5,00 | | | 6-014 | |
| O-Rings | 58,00 | 5,30 | | | | |
| O-Rings | 58,00 | 6,00 | | | | |
| O-Rings | 58,42 | 2,62 | 3231 | 141 | 2-141 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 58,70 | 2,80 | | | 6-355 | |
| O-Rings | 58,74 | 3,53 | 162 | 836 | 5-702 | |
| O-Rings | 59,00 | 1,50 | | | | |
| O-Rings | 59,00 | 2,00 | | | | |
| O-Rings | 59,00 | 2,50 | | | | |
| O-Rings | 59,00 | | | | | |
| O-Rings | 59,00 | 3,50 | | | | |
| O-Rings | 59,00 | 4,00 | | | | |
| O-Rings | 59,00 | 5,00 | | | | |
| O-Rings | 59,00 | 6,00 | | | | |
| O-Rings | 59,20 | 5,70 | | | | |
| O-Rings | 59,30 | 5,70 | | | | |
| O-Rings | 59,36 | | | | | |
| O-Rings | 59,50 | 3,00 | | | | |
| O-Rings | 59,50 | 6,00 | | | | |
| O-Rings | 59,60 | 2,40 | | | | |
| O-Rings | 59,60 | 5,70 | | | | |
| O-Rings | 59,70 | 5,33 | 6237 | 332 | 2-332 | R35 |
| O-Rings | 59,70 | 5,70 | | | | |
| O-Rings | 59,70 | | | | | |
| O-Rings | 59,92 | 3,53 | 4237 | 229 | 2-229 | |
| O-Rings | 60,00 | 1,50 | | | | |
| O-Rings | 60,00 | 2,00 | | | | |
| O-Rings | 60,00 | | | | | |
| O-Rings | 60,00 | 2,62 | 3237 | 142 | 2-142 | |
| O-Rings | 60,00 | | | | | |
| O-Rings | 60,00 | | | | | |
| O-Rings | 60,00 | 3,55 | | | | |
| O-Rings | 60,00 | 4,00 | | | | |
| O-Rings | 60,00 | | | | | |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 60,00 | 4,50 | | | |
| O-Rings | 60,00 | | | | |
| O-Rings | 60,00 | 5,30 | | | |
| O-Rings | 60,00 | 6,00 | | | |
| O-Rings | 60,00 | | | | |
| O-Rings | 60,04 | 1,78 | 2237 | 036 | 2-36 |
| O-Rings | 60,32 | 3,53 | 164 | 837 | |
| O-Rings | 61,00 | 1,50 | | | |
| O-Rings | 61,00 | 2,00 | | | |
| O-Rings | 61,00 | 2,50 | | | |
| O-Rings | 61,00 | 3,00 | | | |
| O-Rings | 61,00 | 3,50 | | | |
| O-Rings | 61,00 | | | | |
| O-Rings | 61,00 | 4,50 | | | |
| O-Rings | 61,00 | 5,00 | | | |
| O-Rings | 61,00 | 6,00 | | | |
| O-Rings | 61,24 | | | | |
| O-Rings | 61,50 | 3,55 | | | |
| O-Rings | 61,50 | 5,30 | | | |
| O-Rings | 61,60 | 2,40 | | | |
| O-Rings | 61,60 | 2,62 | 3243 | 143 | 2-143 |
| O-Rings | 61,60 | | | | |
| O-Rings | 61,60 | 5,70 | | | |
| O-Rings | 61,90 | 3,53 | 165 | 838 | 9-431 |
| O-Rings | 62,00 | 1,50 | | | |
| O-Rings | 62,00 | 2,00 | | | |
| O-Rings | 62,00 | | | | |
| O-Rings | 62,00 | | | | |
| O-Rings | 62,00 | 3,50 | | | |
| O-Rings | 62,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 62,00 | 4,00 | | | | |
| O-Rings | 62,00 | 5,00 | | | | |
| O-Rings | 62,00 | 5,70 | | | | |
| O-Rings | 62,00 | 6,00 | | | | |
| O-Rings | 62,30 | 5,70 | | | | |
| O-Rings | 62,87 | 5,33 | 6250 | 333 | 2-333 | R36 |
| O-Rings | 63,00 | 1,50 | | | | |
| O-Rings | 63,00 | | | | | |
| O-Rings | 63,00 | | | | | |
| O-Rings | 63,00 | | | | | |
| O-Rings | 63,00 | | | | | |
| O-Rings | 63,00 | 3,55 | | | | |
| O-Rings | 63,00 | | | | | |
| O-Rings | 63,00 | | | | | |
| O-Rings | 63,00 | 5,00 | | | | |
| O-Rings | 63,00 | 5,30 | | | | |
| O-Rings | 63,00 | 6,00 | | | | |
| O-Rings | 63,10 | 3,53 | 4250 | 230 | 2-230 | |
| O-Rings | 63,17 | 2,62 | 3250 | 144 | 2-144 | |
| O-Rings | 63,22 | 1,78 | 2250 | 037 | 2-37 | |
| O-Rings | 63,50 | 3,53 | 167 | 839 | | |
| O-Rings | 64,00 | 1,50 | | | | |
| O-Rings | 64,00 | 2,00 | | | | |
| O-Rings | 64,00 | 2,50 | | | | |
| O-Rings | 64,00 | | | | | |
| O-Rings | 64,00 | 3,50 | | | | |
| O-Rings | 64,00 | 4,00 | | | | |
| O-Rings | 64,00 | 4,50 | | | | |
| O-Rings | 64,00 | 5,00 | | | | |
| O-Rings | 64,00 | 5,70 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 64,00 | 6,00 | | | | |
| O-Rings | 64,20 | | | | | |
| O-Rings | 64,30 | 5,70 | | | | |
| O-Rings | 64,40 | 3,10 | | | | |
| O-Rings | 64,50 | 3,00 | | | | |
| O-Rings | 64,60 | 2,40 | | | | |
| O-Rings | 64,60 | 5,70 | | | | |
| O-Rings | 64,77 | 2,62 | 3256 | 145 | 2-145 | |
| O-Rings | 65,00 | 1,50 | | | | |
| O-Rings | 65,00 | | | | | |
| O-Rings | 65,00 | | | | | |
| O-Rings | 65,00 | | | | | |
| O-Rings | 65,00 | 3,50 | | | | |
| O-Rings | 65,00 | 3,55 | | | | |
| O-Rings | 65,00 | | | | | |
| O-Rings | 65,00 | | | | | |
| O-Rings | 65,00 | | | | | |
| O-Rings | 65,00 | | | | | |
| O-Rings | 65,00 | 6,00 | | | | |
| O-Rings | 65,10 | 3,53 | 168 | 840 | 5-703 | |
| O-Rings | 66,00 | 1,50 | | | | |
| O-Rings | 66,00 | | | | | |
| O-Rings | 66,00 | 2,50 | | | | |
| O-Rings | 66,00 | | | | | |
| O-Rings | 66,00 | 3,50 | | | | |
| O-Rings | 66,00 | 4,00 | | | | |
| O-Rings | 66,00 | 4,50 | | | | |
| O-Rings | 66,00 | 5,00 | | | | |
| O-Rings | 66,00 | 6,00 | | | | |
| O-Rings | 66,04 | 5,33 | 6262 | 334 | 2-334 | R37 |

| | | | | | |
|---------|-------|------|------|-----|-------|
| O-Rings | 66,27 | 3,53 | 4262 | 231 | 2-231 |
| O-Rings | 66,34 | 2,62 | 3262 | 146 | 2-146 |
| O-Rings | 66,40 | 1,78 | 2262 | 038 | 2-38 |
| O-Rings | 66,60 | 5,70 | | | |
| O-Rings | 66,67 | 3,53 | 170 | 841 | |
| O-Rings | 67,00 | 1,50 | | | 6-243 |
| O-Rings | 67,00 | 2,00 | | | 6-488 |
| O-Rings | 67,00 | 2,50 | | | 6-316 |
| O-Rings | 67,00 | 3,00 | | | 9-451 |
| O-Rings | 67,00 | 3,50 | | | |
| O-Rings | 67,00 | 3,55 | | | |
| O-Rings | 67,00 | 4,00 | | | 9-452 |
| O-Rings | 67,00 | 5,00 | | | |
| O-Rings | 67,00 | 5,30 | | | |
| O-Rings | 67,00 | 6,00 | | | |
| O-Rings | 67,60 | 2,40 | | | |
| O-Rings | 67,84 | 3,53 | | | 5-361 |
| O-Rings | 67,95 | 2,62 | 3268 | 147 | 2-147 |
| O-Rings | 68,00 | 1,50 | | | |
| O-Rings | 68,00 | 2,00 | | | 6-590 |
| O-Rings | 68,00 | 2,50 | | | |
| O-Rings | 68,00 | 3,00 | | | 9-454 |
| O-Rings | 68,00 | 3,50 | | | |
| O-Rings | 68,00 | 4,00 | | | 9-455 |
| O-Rings | 68,00 | 4,50 | | | |
| O-Rings | 68,00 | 5,00 | | | 9-456 |
| O-Rings | 68,00 | 6,00 | | | |
| O-Rings | 68,20 | 2,00 | | | 6-319 |
| O-Rings | 68,26 | 3,53 | 171 | 842 | 9-457 |
| O-Rings | 69,00 | 1,50 | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 69,00 | 2,00 | | | | |
| O-Rings | 69,00 | 2,50 | | | 9-458 | |
| O-Rings | 69,00 | 3,00 | | | 9-459 | |
| O-Rings | 69,00 | 3,50 | | | | |
| O-Rings | 69,00 | 3,55 | | | | |
| O-Rings | 69,00 | 4,00 | | | 9-460 | |
| O-Rings | 69,00 | 4,50 | | | | |
| O-Rings | 69,00 | 5,00 | | | | |
| O-Rings | 69,00 | 5,30 | | | | |
| O-Rings | 69,00 | 5,70 | | | | |
| O-Rings | 69,00 | 6,00 | | | | |
| O-Rings | 69,20 | 5,70 | | | 9-461 | |
| O-Rings | 69,22 | 5,33 | 6275 | 335 | 2-335 | R38 |
| O-Rings | 69,24 | 2,80 | | | 6-272 | |
| O-Rings | 69,30 | 5,70 | | | | |
| O-Rings | 69,40 | 3,10 | | | | |
| O-Rings | 69,44 | 3,53 | 4275 | 232 | 2-232 | |
| O-Rings | 69,50 | 3,00 | | | | |
| O-Rings | 69,50 | 3,50 | | | 9-463 | |
| O-Rings | 69,52 | 2,62 | 3275 | 148 | 2-148 | |
| O-Rings | 69,57 | 1,78 | 2275 | 039 | 2-39 | |
| O-Rings | 69,60 | 2,40 | | | | |
| O-Rings | 69,60 | 5,70 | | | | |
| O-Rings | 69,85 | 3,53 | 173 | 843 | 2-232 | |
| O-Rings | 70,00 | 1,50 | | | | |
| O-Rings | 70,00 | 2,00 | | | 6-552 | |
| O-Rings | 70,00 | 2,50 | | | 9-465 | |
| O-Rings | 70,00 | 3,00 | | | 6-031 | |
| O-Rings | 70,00 | 3,20 | | | 6-482 | |
| O-Rings | 70,00 | 3,50 | | | 9-467 | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 70,00 | 4,00 | | | 9-468 | |
| O-Rings | 70,00 | 4,50 | | | 6-539 | |
| O-Rings | 70,00 | 5,00 | | | 9-469 | |
| O-Rings | 70,00 | 6,00 | | | | |
| O-Rings | 70,00 | | | | | |
| O-Rings | 70,60 | 5,70 | | | | |
| O-Rings | 71,00 | 1,50 | | | | |
| O-Rings | 71,00 | 2,00 | | | | |
| O-Rings | 71,00 | 2,50 | | | | |
| O-Rings | 71,00 | 3,00 | | | | |
| O-Rings | 71,00 | 3,50 | | | | |
| O-Rings | 71,00 | 3,55 | | | | |
| O-Rings | 71,00 | | | | | |
| O-Rings | 71,00 | 4,50 | | | | |
| O-Rings | 71,00 | 5,00 | | | | |
| O-Rings | 71,00 | 5,30 | | | | |
| O-Rings | 71,00 | 6,00 | | | | |
| O-Rings | 71,12 | 2,62 | 3281 | 149 | 2-149 | |
| O-Rings | 71,44 | 3,53 | 174 | 844 | 5-704 | |
| O-Rings | 71,50 | | | | | |
| O-Rings | 72,00 | 1,50 | | | | |
| O-Rings | 72,00 | 2,00 | | | | |
| O-Rings | 72,00 | 2,50 | | | | |
| O-Rings | 72,00 | | | | | |
| O-Rings | 72,00 | 3,50 | | | | |
| O-Rings | 72,00 | | | | | |
| O-Rings | 72,00 | 5,00 | | | | |
| O-Rings | 72,00 | 6,00 | | | | |
| O-Rings | 72,40 | 5,33 | 6287 | 336 | 2-336 | R39 |
| O-Rings | 72,62 | 3,53 | 4287 | 233 | 2-233 | |

| | | | | | |
|---------|-------|------|------|-----|--------|
| O-Rings | 72,69 | 2,62 | 3287 | 150 | 2-150 |
| O-Rings | 72,75 | 1,78 | 2287 | 40 | feb-40 |
| O-Rings | 73,00 | 1,50 | | | |
| O-Rings | 73,00 | 2,00 | | | |
| O-Rings | 73,00 | 2,50 | | | |
| O-Rings | 73,00 | | | | |
| O-Rings | 73,00 | 3,50 | | | |
| O-Rings | 73,00 | 3,55 | | | |
| O-Rings | 73,00 | | | | |
| O-Rings | 73,00 | 4,50 | | | |
| O-Rings | 73,00 | 5,00 | | | |
| O-Rings | 73,00 | 5,30 | | | |
| O-Rings | 73,00 | | | | |
| O-Rings | 73,02 | 3,53 | 176 | 845 | |
| O-Rings | 74,00 | 1,50 | | | |
| O-Rings | 74,00 | | | | |
| O-Rings | 74,00 | 2,50 | | | |
| O-Rings | 74,00 | | | | |
| O-Rings | 74,00 | 3,50 | | | |
| O-Rings | 74,00 | | | | |
| O-Rings | 74,00 | 4,50 | | | |
| O-Rings | 74,00 | 5,00 | | | |
| O-Rings | 74,00 | 5,70 | | | |
| O-Rings | 74,00 | 6,00 | | | |
| O-Rings | 74,20 | | | | |
| O-Rings | 74,30 | 2,62 | | 640 | |
| O-Rings | 74,30 | 5,70 | | | |
| O-Rings | 74,40 | | | | |
| O-Rings | 74,50 | 3,00 | | | |
| O-Rings | 74,60 | 3,53 | 177 | 846 | 5-705 |

| | | | | | | |
|---------|-------|------|------|-----|--------|-----|
| O-Rings | 74,60 | 5,70 | | | | |
| O-Rings | 74,63 | 5,33 | 178 | 619 | | |
| O-Rings | 75,00 | 1,50 | | | | |
| O-Rings | 75,00 | 2,00 | | | | |
| O-Rings | 75,00 | | | | | |
| O-Rings | 75,00 | | | | | |
| O-Rings | 75,00 | 3,50 | | | | |
| O-Rings | 75,00 | 3,55 | | | | |
| O-Rings | 75,00 | | | | | |
| O-Rings | 75,00 | 4,50 | | | | |
| O-Rings | 75,00 | 5,00 | | | | |
| O-Rings | 75,00 | 5,30 | | | | |
| O-Rings | 75,00 | 6,00 | | | | |
| O-Rings | 75,57 | 5,33 | 6300 | 337 | 2-337 | R40 |
| O-Rings | 75,79 | 3,53 | 4300 | 234 | 2-234 | |
| O-Rings | 75,87 | 2,62 | 3300 | 151 | 2-151 | |
| O-Rings | 75,92 | 1,78 | 2300 | 41 | feb-41 | |
| O-Rings | 76,00 | 1,50 | | | | |
| O-Rings | 76,00 | | | | | |
| O-Rings | 76,00 | | | | | |
| O-Rings | 76,00 | 3,00 | | | | |
| O-Rings | 76,00 | 3,50 | | | | |
| O-Rings | 76,00 | 4,00 | | | | |
| O-Rings | 76,00 | | | | | |
| O-Rings | 76,00 | 5,00 | | | | |
| O-Rings | 76,00 | 6,00 | | | | |
| O-Rings | 77,00 | 1,50 | | | | |
| O-Rings | 77,00 | 2,00 | | | | |
| O-Rings | 77,00 | 2,50 | | | | |
| O-Rings | 77,00 | 3,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 77,00 | 3,50 | | | | |
| O-Rings | 77,00 | 4,00 | | | | |
| O-Rings | 77,00 | 5,00 | | | | |
| O-Rings | 77,00 | 6,00 | | | | |
| O-Rings | 77,20 | | | | | |
| O-Rings | 77,50 | 2,62 | | 641 | | |
| O-Rings | 77,50 | 3,55 | | | | |
| O-Rings | 77,50 | 5,30 | | | | |
| O-Rings | 78,00 | 1,50 | | | | |
| O-Rings | 78,00 | 2,00 | | | | |
| O-Rings | 78,00 | 2,50 | | | | |
| O-Rings | 78,00 | | | | | |
| O-Rings | 78,00 | | | | | |
| O-Rings | 78,00 | 4,00 | | | | |
| O-Rings | 78,00 | | | | | |
| O-Rings | 78,00 | | | | | |
| O-Rings | 78,00 | 6,00 | | | | |
| O-Rings | 78,50 | 6,00 | | | | |
| O-Rings | 78,74 | 5,33 | 6312 | 338 | 2-338 | R41 |
| O-Rings | 78,97 | 3,53 | 4312 | 235 | 2-235 | |
| O-Rings | 79,00 | 1,50 | | | | |
| O-Rings | 79,00 | 1,78 | 2312 | 532 | | |
| O-Rings | 79,00 | 2,00 | | | | |
| O-Rings | 79,00 | 2,50 | | | | |
| O-Rings | 79,00 | 3,00 | | | | |
| O-Rings | 79,00 | 3,50 | | | | |
| O-Rings | 79,00 | | | | | |
| O-Rings | 79,00 | 5,00 | | | | |
| O-Rings | 79,00 | 5,70 | | | | |

| | | | | | |
|---------|-------|------|-----|-----|-------|
| O-Rings | 79,00 | 6,00 | | | |
| O-Rings | 79,20 | | | | |
| O-Rings | 79,30 | 5,70 | | | |
| O-Rings | 79,40 | 3,10 | | | |
| O-Rings | 79,50 | | | | |
| O-Rings | 79,60 | | | | |
| O-Rings | 79,60 | 5,70 | | | |
| O-Rings | 79,77 | 5,33 | 181 | 620 | 9-504 |
| O-Rings | 80,00 | 1,50 | | | |
| O-Rings | 80,00 | | | | |
| O-Rings | 80,00 | 2,50 | | | |
| O-Rings | 80,00 | | | | |
| O-Rings | 80,00 | | | | |
| O-Rings | 80,00 | 3,55 | | | |
| O-Rings | 80,00 | | | | |
| O-Rings | 80,00 | 4,50 | | | |
| O-Rings | 80,00 | | | | |
| O-Rings | 80,00 | 5,30 | | | |
| O-Rings | 80,00 | 6,00 | | | |
| O-Rings | 80,60 | 2,62 | | 642 | |
| O-Rings | 81,00 | 1,50 | | | |
| O-Rings | 81,00 | 2,00 | | | |
| O-Rings | 81,00 | 2,50 | | | |
| O-Rings | 81,00 | | | | |
| O-Rings | 81,00 | 3,50 | | | |
| O-Rings | 81,00 | | | | |
| O-Rings | 81,00 | 4,50 | | | |
| O-Rings | 81,00 | 5,00 | | | |
| O-Rings | 81,00 | 6,00 | | | |
| O-Rings | 81,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|--------|-----|
| O-Rings | 81,50 | 6,00 | | | | |
| O-Rings | 81,92 | 5,33 | 6325 | 339 | 2-339 | R42 |
| O-Rings | 82,00 | 1,50 | | | | |
| O-Rings | 82,00 | | | | | |
| O-Rings | 82,00 | 2,50 | | | | |
| O-Rings | 82,00 | | | | | |
| O-Rings | 82,00 | | | | | |
| O-Rings | 82,00 | 5,00 | | | | |
| O-Rings | 82,00 | | | | | |
| O-Rings | 82,00 | 6,00 | | | | |
| O-Rings | 82,14 | 3,53 | 4325 | 236 | 2-236 | |
| O-Rings | 82,20 | | | | | |
| O-Rings | 82,22 | 2,62 | 3325 | 152 | 2-152 | |
| O-Rings | 82,27 | 1,78 | 2325 | 42 | feb-42 | |
| O-Rings | 82,50 | 3,55 | | | | |
| O-Rings | 82,50 | 5,30 | | | | |
| O-Rings | 82,85 | | | | | |
| O-Rings | 83,00 | 1,50 | | | | |
| O-Rings | 83,00 | 2,00 | | | | |
| O-Rings | 83,00 | 2,50 | | | | |
| O-Rings | 83,00 | | | | | |
| O-Rings | 83,00 | 3,50 | | | | |
| O-Rings | 83,00 | 4,00 | | | | |
| O-Rings | 83,00 | 4,50 | | | | |
| O-Rings | 83,00 | 5,00 | | | | |
| O-Rings | 83,00 | 6,00 | | | | |
| O-Rings | 83,80 | 2,62 | | 643 | 6,184 | |
| O-Rings | 84,00 | 1,50 | | | | |
| O-Rings | 84,00 | | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 84,00 | | | | | |
| O-Rings | 84,00 | | | | | |
| O-Rings | 84,00 | 3,50 | | | | |
| O-Rings | 84,00 | | | | | |
| O-Rings | 84,00 | 5,00 | | | | |
| O-Rings | 84,00 | 5,70 | | | | |
| O-Rings | 84,00 | 6,00 | | | | |
| O-Rings | 84,10 | 5,70 | | | | |
| O-Rings | 84,30 | 5,70 | | | | |
| O-Rings | 84,30 | 5,70 | | | | |
| O-Rings | 84,40 | | | | | |
| O-Rings | 84,50 | 3,00 | | | | |
| O-Rings | 84,60 | 5,70 | | | | |
| O-Rings | 85,00 | 1,50 | | | | |
| O-Rings | 85,00 | | | | | |
| O-Rings | 85,00 | 2,50 | | | | |
| O-Rings | 85,00 | | | | | |
| O-Rings | 85,00 | | | | | |
| O-Rings | 85,00 | 3,55 | | | | |
| O-Rings | 85,00 | | | | | |
| O-Rings | 85,00 | 4,50 | | | | |
| O-Rings | 85,00 | | | | | |
| O-Rings | 85,00 | 5,30 | | | | |
| O-Rings | 85,00 | | | | | |
| O-Rings | 85,09 | 5,33 | 6337 | 340 | 2-340 | R43 |
| O-Rings | 85,20 | | | | | |
| O-Rings | 85,32 | 3,53 | 4337 | 237 | 2-237 | |
| O-Rings | 85,50 | | | | | |
| O-Rings | 86,00 | 1,50 | | | | |
| O-Rings | 86,00 | | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 86,00 | 2,50 | | | | |
| O-Rings | 86,00 | | | | | |
| O-Rings | 86,00 | 3,50 | | | | |
| O-Rings | 86,00 | | | | | |
| O-Rings | 86,00 | 4,50 | | | | |
| O-Rings | 86,00 | | | | | |
| O-Rings | 86,00 | 6,00 | | | | |
| O-Rings | 86,12 | | | | | |
| O-Rings | 86,84 | | | | | |
| O-Rings | 87,00 | 1,50 | | | | |
| O-Rings | 87,00 | 2,00 | | | | |
| O-Rings | 87,00 | 2,50 | | | | |
| O-Rings | 87,00 | | | | | |
| O-Rings | 87,00 | 3,50 | | | | |
| O-Rings | 87,00 | 4,00 | | | | |
| O-Rings | 87,00 | 5,00 | | | | |
| O-Rings | 87,00 | 6,00 | | | | |
| O-Rings | 87,20 | | | | | |
| O-Rings | 87,30 | | | | | |
| O-Rings | 87,50 | 3,55 | | | | |
| O-Rings | 87,50 | 5,30 | | | | |
| O-Rings | 88,00 | 1,50 | | | | |
| O-Rings | 88,00 | | | | | |
| O-Rings | 88,00 | 2,50 | | | | |
| O-Rings | 88,00 | | | | | |
| O-Rings | 88,00 | | | | | |
| O-Rings | 88,00 | 5,00 | | | | |
| O-Rings | 88,00 | | | | | |
| O-Rings | 88,27 | 5,33 | 6350 | 341 | 2-341 | R44 |

| | | | | | |
|---------|-------|------|------|-----|--------|
| O-Rings | 88,30 | | | | |
| O-Rings | 88,50 | 3,53 | 4350 | 238 | 2-238 |
| O-Rings | 88,57 | 2,62 | 3350 | 153 | 2-153 |
| O-Rings | 88,62 | 1,78 | 2350 | 43 | feb-43 |
| O-Rings | 89,00 | 1,50 | | | |
| O-Rings | 89,00 | 2,00 | | | |
| O-Rings | 89,00 | 2,50 | | | |
| O-Rings | 89,00 | 3,00 | | | |
| O-Rings | 89,00 | 3,50 | | | |
| O-Rings | 89,00 | 4,00 | | | |
| O-Rings | 89,00 | | | | |
| O-Rings | 89,00 | 5,00 | | | |
| O-Rings | 89,00 | 5,70 | | | |
| O-Rings | 89,00 | 6,00 | | | |
| O-Rings | 89,10 | 5,70 | | | |
| O-Rings | 89,20 | 5,70 | | | |
| O-Rings | 89,30 | | | | |
| O-Rings | 89,40 | 3,10 | | | |
| O-Rings | 89,50 | | | | |
| O-Rings | 89,60 | 5,70 | | | |
| O-Rings | 89,69 | 5,33 | 185 | 621 | |
| O-Rings | 90,00 | 1,50 | | | |
| O-Rings | 90,00 | | | | |
| O-Rings | 90,00 | | | | |
| O-Rings | 90,00 | | | | |
| O-Rings | 90,00 | | | | |
| O-Rings | 90,00 | 3,55 | | | |
| O-Rings | 90,00 | | | | |
| O-Rings | 90,00 | 4,50 | | | |
| O-Rings | 90,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 90,00 | 5,00 | | | | |
| O-Rings | 90,00 | 5,30 | | | | |
| O-Rings | 90,00 | 6,00 | | | | |
| O-Rings | 91,00 | 1,50 | | | | |
| O-Rings | 91,00 | 2,00 | | | | |
| O-Rings | 91,00 | 2,50 | | | | |
| O-Rings | 91,00 | | | | | |
| O-Rings | 91,00 | 3,50 | | | | |
| O-Rings | 91,00 | 4,00 | | | | |
| O-Rings | 91,00 | 5,00 | | | | |
| O-Rings | 91,00 | | | | | |
| O-Rings | 91,00 | 6,00 | | | | |
| O-Rings | 91,44 | 5,33 | 6362 | 342 | 2-342 | R45 |
| O-Rings | 91,67 | 3,53 | 4362 | 239 | 2-239 | |
| O-Rings | 91,70 | 1,78 | 2362 | 536 | | |
| O-Rings | 92,00 | 1,50 | | | | |
| O-Rings | 92,00 | 2,00 | | | | |
| O-Rings | 92,00 | 2,50 | | | | |
| O-Rings | 92,00 | | | | | |
| O-Rings | 92,00 | 3,50 | | | | |
| O-Rings | 92,00 | | | | | |
| O-Rings | 92,00 | 4,50 | | | | |
| O-Rings | 92,00 | | | | | |
| O-Rings | 92,00 | 6,00 | | | | |
| O-Rings | 92,50 | 3,55 | | | | |
| O-Rings | 92,50 | 5,30 | | | | |
| O-Rings | 93,00 | 1,50 | | | | |
| O-Rings | 93,00 | | | | | |
| O-Rings | 93,00 | 2,50 | | | | |
| O-Rings | 93,00 | | | | | |

| | | | | | | |
|---------|-------|------|------|-----|--------|-----|
| O-Rings | 93,00 | 3,50 | | | | |
| O-Rings | 93,00 | | | | | |
| O-Rings | 93,00 | | | | | |
| O-Rings | 93,00 | 6,00 | | | | |
| O-Rings | 93,39 | | | | | |
| O-Rings | 93,50 | 4,50 | | | | |
| O-Rings | 93,50 | | | | | |
| O-Rings | 94,00 | 1,50 | | | | |
| O-Rings | 94,00 | | | | | |
| O-Rings | 94,00 | | | | | |
| O-Rings | 94,00 | 3,50 | | | | |
| O-Rings | 94,00 | | | | | |
| O-Rings | 94,00 | 5,00 | | | | |
| O-Rings | 94,00 | 5,70 | | | | |
| O-Rings | 94,00 | 6,00 | | | | |
| O-Rings | 94,10 | 5,70 | | | | |
| O-Rings | 94,20 | | | | | |
| O-Rings | 94,30 | 5,70 | | | | |
| O-Rings | 94,40 | 3,10 | | | | |
| O-Rings | 94,50 | | | | | |
| O-Rings | 94,60 | 5,70 | | | | |
| O-Rings | 94,62 | 5,33 | 6375 | 343 | 2-343 | R46 |
| O-Rings | 94,84 | 3,53 | 4375 | 240 | 2-240 | |
| O-Rings | 94,92 | 2,62 | 3375 | 154 | 2-154 | |
| O-Rings | 94,97 | 1,78 | 2375 | 44 | feb-44 | |
| O-Rings | 95,00 | 1,50 | | | | |
| O-Rings | 95,00 | 2,00 | | | | |
| O-Rings | 95,00 | | | | | |
| O-Rings | 95,00 | 3,00 | | | | |

| | | | | | | |
|---------|-------|------|------|-----|-------|-----|
| O-Rings | 95,00 | 3,50 | | | | |
| O-Rings | 95,00 | 3,55 | | | | |
| O-Rings | 95,00 | | | | | |
| O-Rings | 95,00 | | | | | |
| O-Rings | 95,00 | | | | | |
| O-Rings | 95,00 | 5,30 | | | | |
| O-Rings | 95,00 | 6,00 | | | | |
| O-Rings | 95,00 | | | | | |
| O-Rings | 95,50 | | | | | |
| O-Rings | 96,00 | 1,50 | | | | |
| O-Rings | 96,00 | | | | | |
| O-Rings | 96,00 | 2,50 | | | | |
| O-Rings | 96,00 | | | | | |
| O-Rings | 96,00 | 3,50 | | | | |
| O-Rings | 96,00 | 4,00 | | | | |
| O-Rings | 96,00 | 5,00 | | | | |
| O-Rings | 96,00 | 6,00 | | | | |
| O-Rings | 97,00 | 1,50 | | | | |
| O-Rings | 97,00 | 2,00 | | | | |
| O-Rings | 97,00 | 2,50 | | | | |
| O-Rings | 97,00 | 3,00 | | | | |
| O-Rings | 97,00 | 3,50 | | | | |
| O-Rings | 97,00 | | | | | |
| O-Rings | 97,00 | | | | | |
| O-Rings | 97,00 | 6,00 | | | | |
| O-Rings | 97,50 | 3,55 | | | | |
| O-Rings | 97,50 | 4,50 | | | | |
| O-Rings | 97,50 | 5,30 | | | | |
| O-Rings | 97,79 | 5,33 | 6387 | 344 | 2-344 | R47 |
| O-Rings | 98,00 | 1,50 | | | | |

| | | | | | |
|---------|--------|------|------|-----|-------|
| O-Rings | 98,00 | 2,00 | | | |
| O-Rings | 98,00 | 2,50 | | | |
| O-Rings | 98,00 | | | | |
| O-Rings | 98,00 | 3,50 | | | |
| O-Rings | 98,00 | 4,00 | | | |
| O-Rings | 98,00 | 4,50 | | | |
| O-Rings | 98,00 | 5,00 | | | |
| O-Rings | 98,00 | 6,00 | | | |
| O-Rings | 98,02 | 3,53 | 4387 | 241 | 2-241 |
| O-Rings | 98,05 | 1,78 | 2387 | 538 | |
| O-Rings | 99,00 | 1,50 | | | |
| O-Rings | 99,00 | 2,00 | | | |
| O-Rings | 99,00 | 2,50 | | | |
| O-Rings | 99,00 | | | | |
| O-Rings | 99,00 | 3,50 | | | |
| O-Rings | 99,00 | 4,00 | | | |
| O-Rings | 99,00 | 5,00 | | | |
| O-Rings | 99,00 | 5,70 | | | |
| O-Rings | 99,00 | 6,00 | | | |
| O-Rings | 99,00 | | | | |
| O-Rings | 99,10 | 5,70 | | | |
| O-Rings | 99,20 | | | | |
| O-Rings | 99,30 | 5,70 | | | |
| O-Rings | 99,40 | 3,10 | | | |
| O-Rings | 99,50 | 3,00 | | | |
| O-Rings | 99,50 | 4,50 | | | |
| O-Rings | 99,60 | 5,70 | | | |
| O-Rings | 100,00 | 1,50 | | | |
| O-Rings | 100,00 | | | | |
| O-Rings | 100,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|--------|-----|
| O-Rings | 100,00 | | | | | |
| O-Rings | 100,00 | | | | | |
| O-Rings | 100,00 | 3,55 | | | | |
| O-Rings | 100,00 | | | | | |
| O-Rings | 100,00 | 4,50 | | | | |
| O-Rings | 100,00 | | | | | |
| O-Rings | 100,00 | 5,30 | | | | |
| O-Rings | 100,00 | 5,33 | 189 | 622 | 9-591 | |
| O-Rings | 100,00 | 6,00 | | | | |
| O-Rings | 100,50 | 4,50 | | | | |
| O-Rings | 100,97 | 5,33 | 6400 | 345 | 2-345 | R48 |
| O-Rings | 101,00 | 2,00 | | | | |
| O-Rings | 101,00 | 2,50 | | | | |
| O-Rings | 101,00 | | | | | |
| O-Rings | 101,00 | 3,50 | | | | |
| O-Rings | 101,00 | 4,00 | | | | |
| O-Rings | 101,00 | | | | | |
| O-Rings | 101,00 | 5,00 | | | | |
| O-Rings | 101,00 | | | | | |
| O-Rings | 101,19 | 3,53 | 4400 | 242 | 2-242 | |
| O-Rings | 101,27 | 2,62 | 3400 | 155 | 2-155 | |
| O-Rings | 101,32 | 1,78 | 2400 | 45 | feb-45 | |
| O-Rings | 101,60 | 5,70 | | | | |
| O-Rings | 102,00 | 2,00 | | | | |
| O-Rings | 102,00 | 2,50 | | | | |
| O-Rings | 102,00 | | | | | |
| O-Rings | 102,00 | 3,50 | | | | |
| O-Rings | 102,00 | | | | | |
| O-Rings | 102,00 | | | | | |
| O-Rings | 102,00 | | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 102,50 | | | | | |
| O-Rings | 103,00 | | | | | |
| O-Rings | 103,00 | 2,50 | | | | |
| O-Rings | 103,00 | 3,00 | | | | |
| O-Rings | 103,00 | | | | | |
| O-Rings | 103,00 | 3,55 | | | | |
| O-Rings | 103,00 | 4,00 | | | | |
| O-Rings | 103,00 | | | | | |
| O-Rings | 103,00 | 5,30 | | | | |
| O-Rings | 103,00 | 6,00 | | | | |
| O-Rings | 103,00 | | | | | |
| O-Rings | 103,50 | 4,50 | | | | |
| O-Rings | 104,00 | | | | | |
| O-Rings | 104,00 | 2,50 | | | | |
| O-Rings | 104,00 | 3,00 | | | | |
| O-Rings | 104,00 | 3,50 | | | | |
| O-Rings | 104,00 | 4,00 | | | | |
| O-Rings | 104,00 | 5,00 | | | | |
| O-Rings | 104,00 | 5,70 | | | | |
| O-Rings | 104,00 | 6,00 | | | | |
| O-Rings | 104,10 | 5,70 | | | | |
| O-Rings | 104,14 | 5,33 | 6412 | 346 | 2-346 | R49 |
| O-Rings | 104,30 | 5,70 | | | | |
| O-Rings | 104,37 | 3,53 | 4412 | 243 | 2-243 | |
| O-Rings | 104,40 | 1,78 | 2412 | 540 | | |
| O-Rings | 104,40 | 3,10 | | | | |
| O-Rings | 104,50 | | | | | |
| O-Rings | 104,50 | 6,00 | | | | |
| O-Rings | 104,60 | 5,70 | | | | |
| O-Rings | 105,00 | | | | | |

| | | | | | | |
|---------|--------|------|------|-----|--------|-----|
| O-Rings | 105,00 | 2,50 | | | | |
| O-Rings | 105,00 | 3,00 | | | | |
| O-Rings | 105,00 | | | | | |
| O-Rings | 105,00 | | | | | |
| O-Rings | 105,00 | 4,50 | | | | |
| O-Rings | 105,00 | | | | | |
| O-Rings | 105,00 | 6,00 | | | | |
| O-Rings | 106,00 | 2,00 | | | | |
| O-Rings | 106,00 | 2,50 | | | | |
| O-Rings | 106,00 | | | | | |
| O-Rings | 106,00 | 3,50 | | | | |
| O-Rings | 106,00 | 3,55 | | | | |
| O-Rings | 106,00 | 4,00 | | | | |
| O-Rings | 106,00 | 4,50 | | | | |
| O-Rings | 106,00 | 5,00 | | | | |
| O-Rings | 106,00 | 5,30 | | | | |
| O-Rings | 106,00 | 6,00 | | | | |
| O-Rings | 106,80 | | | | | |
| O-Rings | 107,00 | 2,00 | | | | |
| O-Rings | 107,00 | | | | | |
| O-Rings | 107,00 | 3,00 | | | | |
| O-Rings | 107,00 | 3,50 | | | | |
| O-Rings | 107,00 | 4,00 | | | | |
| O-Rings | 107,00 | 5,00 | | | | |
| O-Rings | 107,00 | 6,00 | | | | |
| O-Rings | 107,32 | 5,33 | 6425 | 347 | 2-347 | R50 |
| O-Rings | 107,41 | | | | | |
| O-Rings | 107,54 | 3,53 | 4425 | 244 | 2-244 | |
| O-Rings | 107,62 | 2,62 | 3425 | 156 | 2-156 | |
| O-Rings | 107,70 | 1,78 | 2425 | 46 | feb-46 | |

| | | | | | | |
|---------|--------|------|-----|-----|--|--|
| O-Rings | 108,00 | 2,00 | | | | |
| O-Rings | 108,00 | 2,50 | | | | |
| O-Rings | 108,00 | 3,00 | | | | |
| O-Rings | 108,00 | 3,50 | | | | |
| O-Rings | 108,00 | 4,00 | | | | |
| O-Rings | 108,00 | 5,00 | | | | |
| O-Rings | 108,00 | 6,00 | | | | |
| O-Rings | 108,00 | | | | | |
| O-Rings | 109,00 | 2,00 | | | | |
| O-Rings | 109,00 | 2,50 | | | | |
| O-Rings | 109,00 | | | | | |
| O-Rings | 109,00 | | | | | |
| O-Rings | 109,00 | 3,50 | | | | |
| O-Rings | 109,00 | 3,55 | | | | |
| O-Rings | 109,00 | 4,00 | | | | |
| O-Rings | 109,00 | 5,00 | | | | |
| O-Rings | 109,00 | 5,30 | | | | |
| O-Rings | 109,00 | 5,70 | | | | |
| O-Rings | 109,00 | 6,00 | | | | |
| O-Rings | 109,10 | 5,70 | | | | |
| O-Rings | 109,30 | 5,70 | | | | |
| O-Rings | 109,40 | 3,10 | | | | |
| O-Rings | 109,50 | 3,00 | | | | |
| O-Rings | 109,54 | 5,33 | 193 | 623 | | |
| O-Rings | 109,60 | 5,70 | | | | |
| O-Rings | 110,00 | 2,00 | | | | |
| O-Rings | 110,00 | 2,50 | | | | |
| O-Rings | 110,00 | | | | | |
| O-Rings | 110,00 | | | | | |
| O-Rings | 110,00 | | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 110,00 | | | | | |
| O-Rings | 110,00 | | | | | |
| O-Rings | 110,00 | 6,00 | | | | |
| O-Rings | 110,50 | 5,33 | 6437 | 348 | 2-348 | R51 |
| O-Rings | 110,72 | 3,53 | 4437 | 245 | 2-245 | |
| O-Rings | 111,00 | 2,00 | | | | |
| O-Rings | 111,00 | 2,50 | | | | |
| O-Rings | 111,00 | 3,00 | | | | |
| O-Rings | 111,00 | 3,50 | | | | |
| O-Rings | 111,00 | 4,00 | | | | |
| O-Rings | 111,00 | 5,00 | | | | |
| O-Rings | 111,00 | 6,00 | | | | |
| O-Rings | 111,60 | 5,70 | | | | |
| O-Rings | 112,00 | 2,00 | | | | |
| O-Rings | 112,00 | 2,50 | | | | |
| O-Rings | 112,00 | | | | | |
| O-Rings | 112,00 | 3,50 | | | | |
| O-Rings | 112,00 | 3,55 | | | | |
| O-Rings | 112,00 | | | | | |
| O-Rings | 112,00 | | | | | |
| O-Rings | 112,00 | 5,30 | | | | |
| O-Rings | 112,00 | 6,00 | | | | |
| O-Rings | 112,00 | | | | | |
| O-Rings | 113,00 | 2,00 | | | | |
| O-Rings | 113,00 | 2,50 | | | | |
| O-Rings | 113,00 | 3,00 | | | | |
| O-Rings | 113,00 | | | | | |
| O-Rings | 113,00 | 4,00 | | | | |
| O-Rings | 113,00 | 5,00 | | | | |
| O-Rings | 113,00 | 6,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|--------|-----|
| O-Rings | 113,67 | 5,33 | 6450 | 349 | 2-349 | R52 |
| O-Rings | 113,67 | 6,99 | 8450 | 425 | 2-425 | R53 |
| O-Rings | 113,89 | 3,53 | 4450 | 246 | 2-246 | |
| O-Rings | 113,97 | 2,62 | 3450 | 157 | 2-157 | |
| O-Rings | 114,00 | 1,78 | 2450 | 47 | feb-47 | |
| O-Rings | 114,00 | 2,00 | | | | |
| O-Rings | 114,00 | 2,50 | | | | |
| O-Rings | 114,00 | | | | | |
| O-Rings | 114,00 | | | | | |
| O-Rings | 114,00 | 4,00 | | | | |
| O-Rings | 114,00 | 5,00 | | | | |
| O-Rings | 114,00 | 5,70 | | | | |
| O-Rings | 114,00 | | | | | |
| O-Rings | 114,20 | | | | | |
| O-Rings | 114,30 | 5,70 | | | | |
| O-Rings | 114,40 | 3,10 | | | | |
| O-Rings | 114,50 | 3,00 | | | | |
| O-Rings | 114,60 | 5,70 | | | | |
| O-Rings | 114,70 | 6,99 | 197 | 624 | | |
| O-Rings | 115,00 | | | | | |
| O-Rings | 115,00 | | | | | |
| O-Rings | 115,00 | | | | | |
| O-Rings | 115,00 | 3,50 | | | | |
| O-Rings | 115,00 | 3,55 | | | | |
| O-Rings | 115,00 | | | | | |
| O-Rings | 115,00 | | | | | |
| O-Rings | 115,00 | | | | | |
| O-Rings | 115,00 | 5,30 | | | | |
| O-Rings | 115,00 | | | | | |
| O-Rings | 115,00 | | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 116,00 | 2,00 | | | | |
| O-Rings | 116,00 | 2,50 | | | | |
| O-Rings | 116,00 | 3,00 | | | | |
| O-Rings | 116,00 | | | | | |
| O-Rings | 116,00 | | | | | |
| O-Rings | 116,00 | 5,00 | | | | |
| O-Rings | 116,00 | 6,00 | | | | |
| O-Rings | 116,84 | 5,33 | | 350 | | |
| O-Rings | 116,84 | 6,99 | 8462 | 426 | 2-426 | R54 |
| O-Rings | 117,00 | 2,00 | | | | |
| O-Rings | 117,00 | 2,50 | | | | |
| O-Rings | 117,00 | 3,00 | | | | |
| O-Rings | 117,00 | 3,50 | | | | |
| O-Rings | 117,00 | | | | | |
| O-Rings | 117,00 | | | | | |
| O-Rings | 117,00 | 6,00 | | | | |
| O-Rings | 117,07 | 3,53 | 4462 | 247 | 2-247 | |
| O-Rings | 117,10 | 1,78 | 2462 | 544 | | |
| O-Rings | 117,48 | 5,33 | 199 | 860 | | |
| O-Rings | 118,00 | | | | | |
| O-Rings | 118,00 | 2,50 | | | | |
| O-Rings | 118,00 | 3,00 | | | | |
| O-Rings | 118,00 | 3,50 | | | | |
| O-Rings | 118,00 | 3,55 | | | | |
| O-Rings | 118,00 | | | | | |
| O-Rings | 118,00 | 4,50 | | | | |
| O-Rings | 118,00 | 5,00 | | | | |
| O-Rings | 118,00 | 5,30 | | | | |
| O-Rings | 118,00 | | | | | |
| O-Rings | 118,31 | | | | | |

| | | | | | | |
|---------|--------|------|------|-----|--------|-----|
| O-Rings | 118,50 | | | | | |
| O-Rings | 119,00 | 2,00 | | | | |
| O-Rings | 119,00 | 2,50 | | | | |
| O-Rings | 119,00 | | | | | |
| O-Rings | 119,00 | 3,50 | | | | |
| O-Rings | 119,00 | 4,00 | | | | |
| O-Rings | 119,00 | 5,00 | | | | |
| O-Rings | 119,00 | 5,70 | | | | |
| O-Rings | 119,00 | 6,00 | | | | |
| O-Rings | 119,20 | | | | | |
| O-Rings | 119,30 | 5,70 | | | | |
| O-Rings | 119,40 | 3,10 | | | | |
| O-Rings | 119,50 | 3,00 | | | | |
| O-Rings | 119,54 | | | | | |
| O-Rings | 119,60 | 5,70 | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,00 | | | | | |
| O-Rings | 120,02 | 5,33 | | 351 | 2-351 | |
| O-Rings | 120,02 | 6,99 | 8475 | 427 | 2-427 | R55 |
| O-Rings | 120,24 | 3,53 | 4475 | 148 | 2-248 | |
| O-Rings | 120,32 | 2,62 | 3475 | 158 | 2-158 | |
| O-Rings | 120,37 | 1,78 | 2475 | 48 | feb-48 | |
| O-Rings | 120,65 | 5,33 | 201 | 861 | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 121,00 | 2,00 | | | | |
| O-Rings | 121,00 | 2,50 | | | | |
| O-Rings | 121,00 | 3,00 | | | | |
| O-Rings | 121,00 | 3,50 | | | | |
| O-Rings | 121,00 | 4,00 | | | | |
| O-Rings | 121,00 | 5,00 | | | | |
| O-Rings | 121,00 | 6,00 | | | | |
| O-Rings | 122,00 | 2,00 | | | | |
| O-Rings | 122,00 | 2,50 | | | | |
| O-Rings | 122,00 | | | | | |
| O-Rings | 122,00 | 3,50 | | | | |
| O-Rings | 122,00 | 3,55 | | | | |
| O-Rings | 122,00 | | | | | |
| O-Rings | 122,00 | | | | | |
| O-Rings | 122,00 | 5,00 | | | | |
| O-Rings | 122,00 | 5,30 | | | | |
| O-Rings | 122,00 | 6,00 | | | | |
| O-Rings | 123,00 | 2,00 | | | | |
| O-Rings | 123,00 | | | | | |
| O-Rings | 123,00 | 2,50 | | | | |
| O-Rings | 123,00 | 3,00 | | | | |
| O-Rings | 123,00 | 3,50 | | | | |
| O-Rings | 123,00 | 4,00 | | | | |
| O-Rings | 123,00 | 5,00 | | | | |
| O-Rings | 123,00 | 6,00 | | | | |
| O-Rings | 123,20 | 5,33 | | 352 | 2-352 | |
| O-Rings | 123,20 | 6,99 | 8487 | 428 | 2-428 | R56 |
| O-Rings | 123,42 | 3,53 | 4487 | 149 | 2-249 | |
| O-Rings | 123,83 | 5,33 | 203 | 862 | | |
| O-Rings | 124,00 | 2,00 | | | | |

| | | | | | | |
|---------|--------|------|-----|-----|-------|--|
| O-Rings | 124,00 | 2,50 | | | | |
| O-Rings | 124,00 | | | | | |
| O-Rings | 124,00 | | | | | |
| O-Rings | 124,00 | 3,50 | | | | |
| O-Rings | 124,00 | | | | | |
| O-Rings | 124,00 | 4,50 | | | | |
| O-Rings | 124,00 | 5,00 | | | | |
| O-Rings | 124,00 | 5,70 | | | | |
| O-Rings | 124,00 | 6,00 | | | | |
| O-Rings | 124,20 | | | | | |
| O-Rings | 124,30 | 5,70 | | | | |
| O-Rings | 124,40 | 3,10 | | | | |
| O-Rings | 124,50 | 3,00 | | | | |
| O-Rings | 124,60 | 5,70 | | | | |
| O-Rings | 124,60 | 6,99 | 204 | 625 | | |
| O-Rings | 125,00 | 2,00 | | | | |
| O-Rings | 125,00 | | | | | |
| O-Rings | 125,00 | | | | | |
| O-Rings | 125,00 | | | | | |
| O-Rings | 125,00 | 3,55 | | | | |
| O-Rings | 125,00 | | | | | |
| O-Rings | 125,00 | | | | | |
| O-Rings | 125,00 | 5,30 | | | | |
| O-Rings | 125,00 | | | | | |
| O-Rings | 125,00 | 8,00 | | | 6-115 | |
| O-Rings | 125,50 | | | | | |
| O-Rings | 126,00 | 2,00 | | | | |
| O-Rings | 126,00 | 2,50 | | | | |
| O-Rings | 126,00 | | | | | |
| O-Rings | 126,00 | | | | | |

| | | | | | | |
|---------|--------|------|------|-----|--------|-----|
| O-Rings | 126,00 | | | | | |
| O-Rings | 126,00 | | | | | |
| O-Rings | 126,00 | | | | | |
| O-Rings | 126,00 | | | | | |
| O-Rings | 126,00 | 6,00 | | | | |
| O-Rings | 126,30 | | | | | |
| O-Rings | 126,37 | 5,33 | | 353 | 2-353 | |
| O-Rings | 126,37 | 6,99 | 8500 | 429 | 2-429 | R57 |
| O-Rings | 126,60 | 3,53 | 4500 | 250 | 2-250 | |
| O-Rings | 126,67 | 2,62 | 3500 | 159 | 2-159 | |
| O-Rings | 126,72 | 1,78 | 2500 | 49 | feb-49 | |
| O-Rings | 127,00 | 2,00 | | | | |
| O-Rings | 127,00 | 2,50 | | | | |
| O-Rings | 127,00 | 3,00 | | | | |
| O-Rings | 127,00 | 3,50 | | | | |
| O-Rings | 127,00 | 4,00 | | | | |
| O-Rings | 127,00 | | | | | |
| O-Rings | 127,00 | 5,33 | 206 | 863 | | |
| O-Rings | 127,00 | 6,00 | | | | |
| O-Rings | 128,00 | 2,00 | | | | |
| O-Rings | 128,00 | 2,50 | | | | |
| O-Rings | 128,00 | | | | | |
| O-Rings | 128,00 | 3,50 | | | | |
| O-Rings | 128,00 | 3,55 | | | | |
| O-Rings | 128,00 | 4,00 | | | | |
| O-Rings | 128,00 | | | | | |
| O-Rings | 128,00 | | | | | |
| O-Rings | 128,00 | 5,30 | | | | |
| O-Rings | 128,00 | | | | | |
| O-Rings | 129,00 | 2,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 129,00 | 2,50 | | | | |
| O-Rings | 129,00 | 3,00 | | | | |
| O-Rings | 129,00 | 3,50 | | | | |
| O-Rings | 129,00 | | | | | |
| O-Rings | 129,00 | 5,00 | | | | |
| O-Rings | 129,00 | 6,00 | | | | |
| O-Rings | 129,20 | | | | | |
| O-Rings | 129,30 | 5,70 | | | | |
| O-Rings | 129,40 | 3,10 | | | | |
| O-Rings | 129,50 | 3,00 | | | | |
| O-Rings | 129,54 | 5,33 | | 354 | 2-354 | |
| O-Rings | 129,54 | 6,99 | 8512 | 430 | 2-430 | R58 |
| O-Rings | 129,60 | 5,70 | | | | |
| O-Rings | 129,77 | 3,53 | 4512 | 215 | 2-251 | |
| O-Rings | 130,00 | 2,00 | | | | |
| O-Rings | 130,00 | | | | | |
| O-Rings | 130,00 | 3,00 | | | | |
| O-Rings | 130,00 | 3,50 | | | | |
| O-Rings | 130,00 | | | | | |
| O-Rings | 130,00 | 4,50 | | | | |
| O-Rings | 130,00 | 5,00 | | | | |
| O-Rings | 130,00 | | | | | |
| O-Rings | 130,00 | | | | | |
| O-Rings | 130,00 | | | | | |
| O-Rings | 130,18 | 5,33 | 208 | 864 | | |
| O-Rings | 131,00 | 2,00 | | | | |
| O-Rings | 131,00 | 2,50 | | | | |
| O-Rings | 131,00 | 3,00 | | | | |
| O-Rings | 131,00 | 3,50 | | | | |
| O-Rings | 131,00 | 4,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|--------|-----|
| O-Rings | 131,00 | 5,00 | | | | |
| O-Rings | 131,00 | 6,00 | | | | |
| O-Rings | 131,50 | 4,50 | | | | |
| O-Rings | 131,60 | 5,70 | | | | |
| O-Rings | 132,00 | 2,00 | | | | |
| O-Rings | 132,00 | | | | | |
| O-Rings | 132,00 | | | | | |
| O-Rings | 132,00 | 3,50 | | | | |
| O-Rings | 132,00 | 3,55 | | | | |
| O-Rings | 132,00 | | | | | |
| O-Rings | 132,00 | 5,00 | | | | |
| O-Rings | 132,00 | 5,30 | | | | |
| O-Rings | 132,00 | 6,00 | | | | |
| O-Rings | 132,72 | 5,33 | | 355 | 2-355 | |
| O-Rings | 132,72 | 6,99 | 8525 | 431 | 2-431 | R59 |
| O-Rings | 132,94 | 3,53 | 4525 | 252 | 2-252 | |
| O-Rings | 133,00 | 2,00 | | | | |
| O-Rings | 133,00 | 2,50 | | | | |
| O-Rings | 133,00 | 3,00 | | | | |
| O-Rings | 133,00 | | | | | |
| O-Rings | 133,00 | 4,00 | | | | |
| O-Rings | 133,00 | 5,00 | | | | |
| O-Rings | 133,00 | 6,00 | | | | |
| O-Rings | 133,02 | 2,62 | 3525 | 160 | 2-160 | |
| O-Rings | 133,07 | 1,78 | 2525 | 50 | feb-50 | |
| O-Rings | 133,35 | 5,33 | 210 | 865 | | |
| O-Rings | 134,00 | 2,00 | | | | |
| O-Rings | 134,00 | 2,50 | | | | |
| O-Rings | 134,00 | | | | | |
| O-Rings | 134,00 | 3,50 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 134,00 | 4,00 | | | | |
| O-Rings | 134,00 | 5,00 | | | | |
| O-Rings | 134,00 | 6,00 | | | | |
| O-Rings | 134,20 | | | | | |
| O-Rings | 134,30 | 5,70 | | | | |
| O-Rings | 134,40 | 3,10 | | | | |
| O-Rings | 134,50 | 3,00 | | | | |
| O-Rings | 134,50 | 4,50 | | | | |
| O-Rings | 134,50 | 6,99 | 211 | 626 | | |
| O-Rings | 134,60 | 5,70 | | | | |
| O-Rings | 135,00 | 2,00 | | | | |
| O-Rings | 135,00 | | | | | |
| O-Rings | 135,00 | 3,00 | | | | |
| O-Rings | 135,00 | | | | | |
| O-Rings | 135,00 | | | | | |
| O-Rings | 135,00 | 3,50 | | | | |
| O-Rings | 135,00 | | | | | |
| O-Rings | 135,00 | | | | | |
| O-Rings | 135,00 | 6,00 | | | | |
| O-Rings | 135,90 | 5,33 | | 356 | 2-356 | |
| O-Rings | 135,90 | 6,99 | 8537 | 432 | 2-432 | R60 |
| O-Rings | 136,00 | 2,00 | | | | |
| O-Rings | 136,00 | 2,50 | | | | |
| O-Rings | 136,00 | | | | | |
| O-Rings | 136,00 | 3,50 | | | | |
| O-Rings | 136,00 | 3,55 | | | | |
| O-Rings | 136,00 | | | | | |
| O-Rings | 136,00 | 5,00 | | | | |
| O-Rings | 136,00 | 5,30 | | | | |
| O-Rings | 136,00 | 6,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 136,00 | | | | | |
| O-Rings | 136,12 | 3,53 | 4537 | 253 | 2-253 | |
| O-Rings | 136,53 | 5,33 | 213 | 866 | | |
| O-Rings | 137,00 | 2,00 | | | | |
| O-Rings | 137,00 | 2,50 | | | | |
| O-Rings | 137,00 | | | | | |
| O-Rings | 137,00 | 3,50 | | | | |
| O-Rings | 137,00 | | | | | |
| O-Rings | 137,00 | 4,50 | | | | |
| O-Rings | 137,00 | 5,00 | | | | |
| O-Rings | 137,00 | 6,00 | | | | |
| O-Rings | 137,00 | | | | | |
| O-Rings | 137,30 | | | | | |
| O-Rings | 138,00 | | | | | |
| O-Rings | 138,00 | | | | | |
| O-Rings | 138,00 | 2,50 | | | | |
| O-Rings | 138,00 | | | | | |
| O-Rings | 138,00 | 3,50 | | | | |
| O-Rings | 138,00 | 4,00 | | | | |
| O-Rings | 138,00 | 5,00 | | | | |
| O-Rings | 138,00 | | | | | |
| O-Rings | 139,00 | 2,00 | | | | |
| O-Rings | 139,00 | 2,50 | | | | |
| O-Rings | 139,00 | 3,00 | | | | |
| O-Rings | 139,00 | 3,50 | | | | |
| O-Rings | 139,00 | 4,00 | | | | |
| O-Rings | 139,00 | 5,00 | | | | |
| O-Rings | 139,00 | 6,00 | | | | |
| O-Rings | 139,07 | 5,33 | | 357 | | |
| O-Rings | 139,07 | 6,99 | 8550 | 433 | 2-433 | R61 |

| | | | | | |
|---------|--------|------|------|-----|-------|
| O-Rings | 139,29 | 3,53 | 4550 | 254 | 2-254 |
| O-Rings | 139,30 | 5,70 | | | |
| O-Rings | 139,37 | 2,62 | 3550 | 161 | 2-161 |
| O-Rings | 139,40 | 3,10 | | | |
| O-Rings | 139,50 | 3,00 | | | |
| O-Rings | 139,50 | | | | |
| O-Rings | 139,60 | 5,70 | | | |
| O-Rings | 139,70 | 5,33 | 215 | 867 | |
| O-Rings | 140,00 | | | | |
| O-Rings | 140,00 | 2,50 | | | |
| O-Rings | 140,00 | | | | |
| O-Rings | 140,00 | 3,50 | | | |
| O-Rings | 140,00 | 3,55 | | | |
| O-Rings | 140,00 | | | | |
| O-Rings | 140,00 | 4,50 | | | |
| O-Rings | 140,00 | | | | |
| O-Rings | 140,00 | 5,30 | | | |
| O-Rings | 140,00 | 6,00 | | | |
| O-Rings | 140,50 | 4,50 | | | |
| O-Rings | 141,00 | 2,00 | | | |
| O-Rings | 141,00 | 2,50 | | | |
| O-Rings | 141,00 | 3,00 | | | |
| O-Rings | 141,00 | 3,50 | | | |
| O-Rings | 141,00 | 4,00 | | | |
| O-Rings | 141,00 | 5,00 | | | |
| O-Rings | 141,00 | 6,00 | | | |
| O-Rings | 142,00 | 2,00 | | | |
| O-Rings | 142,00 | 2,50 | | | |
| O-Rings | 142,00 | 3,00 | | | |
| O-Rings | 142,00 | 3,50 | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 142,00 | | | | | |
| O-Rings | 142,00 | 5,00 | | | | |
| O-Rings | 142,00 | 6,00 | | | | |
| O-Rings | 142,11 | 1,78 | 2562 | 552 | | |
| O-Rings | 142,24 | 5,33 | | 358 | 2-358 | |
| O-Rings | 142,24 | 6,99 | 8562 | 434 | 2-434 | R62 |
| O-Rings | 142,47 | 3,53 | 4562 | 255 | 2-255 | |
| O-Rings | 142,88 | 5,33 | 217 | 868 | | |
| O-Rings | 143,00 | 2,00 | | | | |
| O-Rings | 143,00 | 2,50 | | | | |
| O-Rings | 143,00 | 3,00 | | | | |
| O-Rings | 143,00 | 3,50 | | | | |
| O-Rings | 143,00 | 4,00 | | | | |
| O-Rings | 143,00 | 5,00 | | | | |
| O-Rings | 143,00 | 6,00 | | | | |
| O-Rings | 144,00 | 2,00 | | | | |
| O-Rings | 144,00 | 2,50 | | | | |
| O-Rings | 144,00 | 3,00 | | | | |
| O-Rings | 144,00 | 3,50 | | | | |
| O-Rings | 144,00 | | | | | |
| O-Rings | 144,00 | 4,00 | | | | |
| O-Rings | 144,00 | 5,00 | | | | |
| O-Rings | 144,00 | 6,00 | | | | |
| O-Rings | 144,10 | 8,40 | | | | |
| O-Rings | 144,22 | | | | | |
| O-Rings | 144,30 | 5,70 | | | | |
| O-Rings | 144,40 | 3,10 | | | | |
| O-Rings | 144,50 | 3,00 | | | | |
| O-Rings | 144,60 | 5,70 | | | | |
| O-Rings | 145,00 | 2,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 145,00 | | | | | |
| O-Rings | 145,00 | 3,00 | | | | |
| O-Rings | 145,00 | 3,50 | | | | |
| O-Rings | 145,00 | 3,55 | | | | |
| O-Rings | 145,00 | | | | | |
| O-Rings | 145,00 | | | | | |
| O-Rings | 145,00 | 5,30 | | | | |
| O-Rings | 145,00 | 6,00 | | | | |
| O-Rings | 145,42 | 5,33 | | 359 | 2-359 | |
| O-Rings | 145,42 | 6,99 | 8575 | 435 | 2-435 | R63 |
| O-Rings | 145,65 | 3,53 | 4575 | 256 | 2-256 | |
| O-Rings | 145,72 | 2,62 | 3575 | 162 | 2-162 | |
| O-Rings | 146,00 | 2,00 | | | | |
| O-Rings | 146,00 | 2,50 | | | | |
| O-Rings | 146,00 | | | | | |
| O-Rings | 146,00 | | | | | |
| O-Rings | 146,00 | | | | | |
| O-Rings | 146,00 | 3,50 | | | | |
| O-Rings | 146,00 | | | | | |
| O-Rings | 146,00 | 5,00 | | | | |
| O-Rings | 146,00 | 6,00 | | | | |
| O-Rings | 146,05 | 5,33 | 219 | 869 | | |
| O-Rings | 147,00 | 2,00 | | | | |
| O-Rings | 147,00 | 2,50 | | | | |
| O-Rings | 147,00 | 3,00 | | | | |
| O-Rings | 147,00 | 3,50 | | | | |
| O-Rings | 147,00 | 4,00 | | | | |
| O-Rings | 147,00 | 5,00 | | | | |
| O-Rings | 147,00 | 6,00 | | | | |
| O-Rings | 148,00 | 2,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 148,00 | 2,50 | | | | |
| O-Rings | 148,00 | 3,00 | | | | |
| O-Rings | 148,00 | 3,50 | | | | |
| O-Rings | 148,00 | 4,00 | | | | |
| O-Rings | 148,00 | 5,00 | | | | |
| O-Rings | 148,00 | 6,00 | | | | |
| O-Rings | 148,60 | 5,33 | | 360 | 2-360 | |
| O-Rings | 148,60 | 6,99 | 8587 | 436 | 2-436 | R64 |
| O-Rings | 148,82 | 3,53 | 4587 | 257 | 2-257 | |
| O-Rings | 149,00 | 2,00 | | | | |
| O-Rings | 149,00 | 2,50 | | | | |
| O-Rings | 149,00 | 3,00 | | | | |
| O-Rings | 149,00 | 3,50 | | | | |
| O-Rings | 149,00 | 4,00 | | | | |
| O-Rings | 149,00 | 5,00 | | | | |
| O-Rings | 149,00 | 6,00 | | | | |
| O-Rings | 149,10 | 8,40 | | | | |
| O-Rings | 149,20 | | | | | |
| O-Rings | 149,23 | 5,33 | 221 | 870 | | |
| O-Rings | 149,30 | 5,70 | | | | |
| O-Rings | 149,50 | 3,00 | | | | |
| O-Rings | 149,50 | 8,40 | | | | |
| O-Rings | 149,60 | 5,70 | | | | |
| O-Rings | 150,00 | 2,00 | | | | |
| O-Rings | 150,00 | 2,50 | | | | |
| O-Rings | 150,00 | | | | | |
| O-Rings | 150,00 | 3,50 | | | | |
| O-Rings | 150,00 | 3,55 | | | | |
| O-Rings | 150,00 | | | | | |
| O-Rings | 150,00 | 4,50 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 150,00 | 5,00 | | | | |
| O-Rings | 150,00 | 5,30 | | | | |
| O-Rings | 150,00 | | | | | |
| O-Rings | 150,00 | | | | | |
| O-Rings | 150,20 | | | | | |
| O-Rings | 151,00 | | | | | |
| O-Rings | 151,00 | 3,50 | | | | |
| O-Rings | 151,00 | | | | | |
| O-Rings | 151,00 | 5,00 | | | | |
| O-Rings | 151,00 | 6,00 | | | | |
| O-Rings | 151,70 | | | | | |
| O-Rings | 151,77 | 5,33 | 6600 | 361 | 2-361 | R65 |
| O-Rings | 151,77 | 6,99 | 8600 | 437 | 2-437 | |
| O-Rings | 152,00 | 3,00 | | | | |
| O-Rings | 152,00 | 3,50 | | | | |
| O-Rings | 152,00 | 3,53 | 4600 | 258 | 2-258 | |
| O-Rings | 152,00 | 4,00 | | | | |
| O-Rings | 152,00 | 5,00 | | | | |
| O-Rings | 152,00 | 6,00 | | | | |
| O-Rings | 152,07 | 2,62 | 3600 | 163 | 2-163 | |
| O-Rings | 153,00 | | | | | |
| O-Rings | 153,00 | 3,50 | | | | |
| O-Rings | 153,00 | 4,00 | | | | |
| O-Rings | 153,00 | 4,50 | | | | |
| O-Rings | 153,00 | 5,00 | | | | |
| O-Rings | 153,00 | 6,00 | | | | |
| O-Rings | 154,00 | 3,00 | | | | |
| O-Rings | 154,00 | 3,50 | | | | |
| O-Rings | 154,00 | 4,00 | | | | |
| O-Rings | 154,00 | 5,00 | | | | |

| | | | | | |
|---------|--------|------|-----|-----|--|
| O-Rings | 154,00 | 6,00 | | | |
| O-Rings | 154,10 | 8,40 | | | |
| O-Rings | 154,20 | | | | |
| O-Rings | 154,30 | 5,70 | | | |
| O-Rings | 154,50 | | | | |
| O-Rings | 154,50 | 3,00 | | | |
| O-Rings | 154,50 | 8,40 | | | |
| O-Rings | 155,00 | | | | |
| O-Rings | 155,00 | | | | |
| O-Rings | 155,00 | 3,50 | | | |
| O-Rings | 155,00 | 3,55 | | | |
| O-Rings | 155,00 | | | | |
| O-Rings | 155,00 | 4,50 | | | |
| O-Rings | 155,00 | | | | |
| O-Rings | 155,00 | 5,30 | | | |
| O-Rings | 155,00 | 5,33 | | 644 | |
| O-Rings | 155,00 | 6,00 | | | |
| O-Rings | 155,00 | | | | |
| O-Rings | 155,50 | 6,00 | | | |
| O-Rings | 155,60 | 6,99 | 223 | 872 | |
| O-Rings | 156,00 | 3,00 | | | |
| O-Rings | 156,00 | 3,50 | | | |
| O-Rings | 156,00 | 4,00 | | | |
| O-Rings | 156,00 | 5,00 | | | |
| O-Rings | 156,00 | 6,00 | | | |
| O-Rings | 157,00 | 3,00 | | | |
| O-Rings | 157,00 | 3,50 | | | |
| O-Rings | 157,00 | 4,00 | | | |
| O-Rings | 157,00 | 4,50 | | | |
| O-Rings | 157,00 | 5,00 | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 157,00 | 6,00 | | | | |
| O-Rings | 158,00 | 3,00 | | | | |
| O-Rings | 158,00 | 3,50 | | | | |
| O-Rings | 158,00 | 4,00 | | | | |
| O-Rings | 158,00 | | | | | |
| O-Rings | 158,00 | 6,00 | | | | |
| O-Rings | 158,12 | 5,33 | 6625 | 362 | 2-362 | |
| O-Rings | 158,12 | 6,99 | 8625 | 438 | 2-438 | R66 |
| O-Rings | 158,34 | 3,53 | 4625 | 259 | 2-259 | |
| O-Rings | 158,42 | 2,62 | 3625 | 164 | 2-164 | |
| O-Rings | 159,00 | 3,00 | | | | |
| O-Rings | 159,00 | 3,50 | | | | |
| O-Rings | 159,00 | | | | | |
| O-Rings | 159,00 | 5,00 | | | | |
| O-Rings | 159,00 | 6,00 | | | | |
| O-Rings | 159,10 | 8,40 | | | | |
| O-Rings | 159,20 | | | | | |
| O-Rings | 159,30 | 5,70 | | | | |
| O-Rings | 159,50 | 3,00 | | | | |
| O-Rings | 159,50 | 6,99 | 225 | 627 | | |
| O-Rings | 159,50 | 8,40 | | | | |
| O-Rings | 160,00 | | | | | |
| O-Rings | 160,00 | 3,50 | | | | |
| O-Rings | 160,00 | 3,55 | | | | |
| O-Rings | 160,00 | | | | | |
| O-Rings | 160,00 | 4,50 | | | | |
| O-Rings | 160,00 | | | | | |
| O-Rings | 160,00 | 5,30 | | | | |
| O-Rings | 160,00 | | | | | |
| O-Rings | 161,00 | | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 161,00 | 3,50 | | | | |
| O-Rings | 161,00 | 4,00 | | | | |
| O-Rings | 161,00 | 5,00 | | | | |
| O-Rings | 161,00 | 6,00 | | | | |
| O-Rings | 161,16 | 1,78 | 2637 | 558 | | |
| O-Rings | 161,29 | | | | | |
| O-Rings | 161,30 | 5,33 | | 645 | | |
| O-Rings | 161,31 | | | | | |
| O-Rings | 161,90 | 6,99 | 226 | 874 | | |
| O-Rings | 162,00 | | | | | |
| O-Rings | 162,00 | 3,00 | | | | |
| O-Rings | 162,00 | 3,50 | | | | |
| O-Rings | 162,00 | 4,00 | | | | |
| O-Rings | 162,00 | 5,00 | | | | |
| O-Rings | 162,00 | 6,00 | | | | |
| O-Rings | 163,00 | 3,00 | | | | |
| O-Rings | 163,00 | 3,50 | | | | |
| O-Rings | 163,00 | 4,00 | | | | |
| O-Rings | 163,00 | 5,00 | | | | |
| O-Rings | 163,00 | 6,00 | | | | |
| O-Rings | 164,00 | 3,00 | | | | |
| O-Rings | 164,00 | 3,50 | | | | |
| O-Rings | 164,00 | 4,00 | | | | |
| O-Rings | 164,00 | 5,00 | | | | |
| O-Rings | 164,00 | 6,00 | | | | |
| O-Rings | 164,10 | 8,40 | | | | |
| O-Rings | 164,30 | 5,70 | | | | |
| O-Rings | 164,34 | 1,78 | 2652 | 559 | | |
| O-Rings | 164,47 | 5,33 | 6645 | 363 | 2-363 | |
| O-Rings | 164,47 | 6,99 | 8650 | 439 | 2-439 | R67 |

| | | | | | |
|---------|--------|------|------|-----|-------|
| O-Rings | 164,50 | 3,00 | | | |
| O-Rings | 164,50 | 8,40 | | | |
| O-Rings | 164,70 | 3,53 | 4650 | 260 | 2-260 |
| O-Rings | 164,77 | 2,62 | 3650 | 165 | 2-165 |
| O-Rings | 165,00 | 3,00 | | | |
| O-Rings | 165,00 | 3,50 | | | |
| O-Rings | 165,00 | 3,55 | | | |
| O-Rings | 165,00 | 4,00 | | | |
| O-Rings | 165,00 | 4,50 | | | |
| O-Rings | 165,00 | 5,00 | | | |
| O-Rings | 165,00 | 5,30 | | | |
| O-Rings | 165,00 | 6,00 | | | |
| O-Rings | 166,00 | 3,00 | | | |
| O-Rings | 166,00 | 3,50 | | | |
| O-Rings | 166,00 | 4,00 | | | |
| O-Rings | 166,00 | 5,00 | | | |
| O-Rings | 166,00 | 6,00 | | | |
| O-Rings | 166,70 | 6,99 | 228 | 628 | |
| O-Rings | 167,00 | 3,00 | | | |
| O-Rings | 167,00 | 3,50 | | | |
| O-Rings | 167,00 | 4,00 | | | |
| O-Rings | 167,00 | 5,00 | | | |
| O-Rings | 167,00 | 6,00 | | | |
| O-Rings | 167,51 | 1,78 | 2662 | 560 | |
| O-Rings | 167,70 | 5,33 | | 646 | |
| O-Rings | 168,00 | 3,00 | | | |
| O-Rings | 168,00 | 3,50 | | | |
| O-Rings | 168,00 | 4,00 | | | |
| O-Rings | 168,00 | 5,00 | | | |
| O-Rings | 168,00 | 6,00 | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 168,30 | 6,99 | 229 | 876 | | |
| O-Rings | 169,00 | 3,00 | | | | |
| O-Rings | 169,00 | 3,50 | | | | |
| O-Rings | 169,00 | 4,00 | | | | |
| O-Rings | 169,00 | 5,00 | | | | |
| O-Rings | 169,00 | 6,00 | | | | |
| O-Rings | 169,10 | 8,40 | | | | |
| O-Rings | 169,30 | 5,70 | | | | |
| O-Rings | 169,50 | 3,00 | | | | |
| O-Rings | 170,00 | 3,00 | | | | |
| O-Rings | 170,00 | 3,50 | | | | |
| O-Rings | 170,00 | 3,55 | | | | |
| O-Rings | 170,00 | 4,00 | | | | |
| O-Rings | 170,00 | 5,00 | | | | |
| O-Rings | 170,00 | 5,30 | | | | |
| O-Rings | 170,00 | 6,00 | | | | |
| O-Rings | 170,69 | 1,78 | 2675 | 561 | | |
| O-Rings | 170,82 | 5,33 | 6670 | 364 | 2-364 | |
| O-Rings | 170,82 | 6,99 | 8675 | 440 | 2-440 | R68 |
| O-Rings | 171,00 | 3,00 | | | | |
| O-Rings | 171,00 | 3,50 | | | | |
| O-Rings | 171,00 | 4,00 | | | | |
| O-Rings | 171,00 | 5,00 | | | | |
| O-Rings | 171,00 | 6,00 | | | | |
| O-Rings | 171,04 | 3,53 | 4675 | 261 | 2-261 | |
| O-Rings | 171,12 | 2,62 | 3675 | 166 | 2-166 | |
| O-Rings | 172,00 | 3,00 | | | | |
| O-Rings | 172,00 | 3,50 | | | | |
| O-Rings | 172,00 | 4,00 | | | | |
| O-Rings | 172,00 | 4,50 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|--|--|
| O-Rings | 172,00 | 5,00 | | | | |
| O-Rings | 172,00 | 6,00 | | | | |
| O-Rings | 173,00 | 3,00 | | | | |
| O-Rings | 173,00 | 3,50 | | | | |
| O-Rings | 173,00 | 4,00 | | | | |
| O-Rings | 173,00 | 5,00 | | | | |
| O-Rings | 173,00 | 6,00 | | | | |
| O-Rings | 173,87 | 1,78 | 2687 | 562 | | |
| O-Rings | 174,00 | 3,00 | | | | |
| O-Rings | 174,00 | 3,50 | | | | |
| O-Rings | 174,00 | 4,00 | | | | |
| O-Rings | 174,00 | 5,00 | | | | |
| O-Rings | 174,00 | 5,33 | | 647 | | |
| O-Rings | 174,00 | 6,00 | | | | |
| O-Rings | 174,10 | 8,40 | | | | |
| O-Rings | 174,30 | 5,70 | | | | |
| O-Rings | 174,50 | 3,00 | | | | |
| O-Rings | 174,50 | 8,40 | | | | |
| O-Rings | 174,60 | 6,99 | 231 | 878 | | |
| O-Rings | 175,00 | 3,00 | | | | |
| O-Rings | 175,00 | 3,50 | | | | |
| O-Rings | 175,00 | 3,55 | | | | |
| O-Rings | 175,00 | 4,00 | | | | |
| O-Rings | 175,00 | 5,00 | | | | |
| O-Rings | 175,00 | 5,30 | | | | |
| O-Rings | 175,00 | 6,00 | | | | |
| O-Rings | 176,00 | 3,00 | | | | |
| O-Rings | 176,00 | 3,50 | | | | |
| O-Rings | 176,00 | 4,00 | | | | |
| O-Rings | 176,00 | 5,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 176,00 | 6,00 | | | | |
| O-Rings | 177,00 | 3,00 | | | | |
| O-Rings | 177,00 | 3,50 | | | | |
| O-Rings | 177,00 | 4,00 | | | | |
| O-Rings | 177,00 | 5,00 | | | | |
| O-Rings | 177,00 | 6,00 | | | | |
| O-Rings | 177,17 | 5,33 | 6700 | 365 | 2-365 | |
| O-Rings | 177,17 | 6,99 | 8700 | 441 | 2-441 | R69 |
| O-Rings | 177,40 | 3,53 | 4700 | 262 | 2-262 | |
| O-Rings | 177,47 | 2,62 | 3700 | 167 | 2-167 | |
| O-Rings | 178,00 | 3,00 | | | | |
| O-Rings | 178,00 | 3,50 | | | | |
| O-Rings | 178,00 | 4,00 | | | | |
| O-Rings | 178,00 | 4,50 | | | | |
| O-Rings | 178,00 | 5,00 | | | | |
| O-Rings | 178,00 | 6,00 | | | | |
| O-Rings | 179,00 | 3,00 | | | | |
| O-Rings | 179,00 | 3,50 | | | | |
| O-Rings | 179,00 | 4,00 | | | | |
| O-Rings | 179,00 | 5,00 | | | | |
| O-Rings | 179,00 | 6,00 | | | | |
| O-Rings | 179,10 | 8,40 | | | | |
| O-Rings | 179,30 | 5,70 | | | | |
| O-Rings | 179,50 | 3,00 | | | | |
| O-Rings | 179,50 | 8,40 | | | | |
| O-Rings | 180,00 | 3,00 | | | | |
| O-Rings | 180,00 | 3,50 | | | | |
| O-Rings | 180,00 | 4,00 | | | | |
| O-Rings | 180,00 | 4,50 | | | | |
| O-Rings | 180,00 | 5,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 180,00 | 5,30 | | | | |
| O-Rings | 180,00 | 6,00 | | | | |
| O-Rings | 181,00 | 3,00 | | | | |
| O-Rings | 181,00 | 3,50 | | | | |
| O-Rings | 181,00 | 4,00 | | | | |
| O-Rings | 181,00 | 5,00 | | | | |
| O-Rings | 181,00 | 6,00 | | | | |
| O-Rings | 181,00 | 6,99 | 233 | 880 | | |
| O-Rings | 182,00 | 3,00 | | | | |
| O-Rings | 182,00 | 3,50 | | | | |
| O-Rings | 182,00 | 4,00 | | | | |
| O-Rings | 182,00 | 5,00 | | | | |
| O-Rings | 182,00 | 6,00 | | | | |
| O-Rings | 183,00 | 3,00 | | | | |
| O-Rings | 183,00 | 3,50 | | | | |
| O-Rings | 183,00 | 4,00 | | | | |
| O-Rings | 183,00 | 5,00 | | | | |
| O-Rings | 183,00 | 6,00 | | | | |
| O-Rings | 183,52 | 5,33 | 6720 | 366 | 2-366 | |
| O-Rings | 183,52 | 6,99 | 8725 | 442 | 2-442 | R70 |
| O-Rings | 183,74 | 3,53 | 4725 | 263 | 2-263 | |
| O-Rings | 183,82 | 2,62 | 3725 | 168 | 2-168 | |
| O-Rings | 184,00 | 3,00 | | | | |
| O-Rings | 184,00 | 3,50 | | | | |
| O-Rings | 184,00 | 4,00 | | | | |
| O-Rings | 184,00 | 5,00 | | | | |
| O-Rings | 184,00 | 6,00 | | | | |
| O-Rings | 184,10 | 8,40 | | | | |
| O-Rings | 184,30 | 5,70 | | | | |
| O-Rings | 184,50 | 3,00 | | | | |

| | | | | | |
|---------|--------|------|-----|-----|--|
| O-Rings | 184,50 | 8,40 | | | |
| O-Rings | 185,00 | 3,00 | | | |
| O-Rings | 185,00 | 3,50 | | | |
| O-Rings | 185,00 | 3,55 | | | |
| O-Rings | 185,00 | 4,00 | | | |
| O-Rings | 185,00 | 4,50 | | | |
| O-Rings | 185,00 | 5,00 | | | |
| O-Rings | 185,00 | 5,30 | | | |
| O-Rings | 185,00 | 6,00 | | | |
| O-Rings | 186,00 | 3,00 | | | |
| O-Rings | 186,00 | 3,50 | | | |
| O-Rings | 186,00 | 4,00 | | | |
| O-Rings | 186,00 | 4,50 | | | |
| O-Rings | 186,00 | 5,00 | | | |
| O-Rings | 186,00 | 6,00 | | | |
| O-Rings | 187,00 | 3,00 | | | |
| O-Rings | 187,00 | 3,50 | | | |
| O-Rings | 187,00 | 4,00 | | | |
| O-Rings | 187,00 | 5,00 | | | |
| O-Rings | 187,00 | 6,00 | | | |
| O-Rings | 187,30 | 6,99 | 235 | 882 | |
| O-Rings | 188,00 | 3,00 | | | |
| O-Rings | 188,00 | 3,50 | | | |
| O-Rings | 188,00 | 4,00 | | | |
| O-Rings | 188,00 | 5,00 | | | |
| O-Rings | 188,00 | 6,00 | | | |
| O-Rings | 189,00 | 3,00 | | | |
| O-Rings | 189,00 | 3,50 | | | |
| O-Rings | 189,00 | 4,00 | | | |
| O-Rings | 189,00 | 5,00 | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 189,00 | 6,00 | | | | |
| O-Rings | 189,10 | 8,40 | | | | |
| O-Rings | 189,30 | 5,70 | | | | |
| O-Rings | 189,50 | 3,00 | | | | |
| O-Rings | 189,50 | 4,50 | | | | |
| O-Rings | 189,50 | 8,40 | | | | |
| O-Rings | 189,87 | 5,33 | 6745 | 367 | 2-367 | |
| O-Rings | 189,87 | 6,99 | 8750 | 443 | 2-443 | R71 |
| O-Rings | 190,00 | 3,00 | | | | |
| O-Rings | 190,00 | 3,50 | | | | |
| O-Rings | 190,00 | 4,00 | | | | |
| O-Rings | 190,00 | 5,00 | | | | |
| O-Rings | 190,00 | 5,30 | | | | |
| O-Rings | 190,00 | 6,00 | | | | |
| O-Rings | 190,10 | 3,53 | 4750 | 264 | 2-264 | |
| O-Rings | 190,17 | 2,62 | 3750 | 169 | 2-169 | |
| O-Rings | 191,00 | 3,00 | | | | |
| O-Rings | 191,00 | 3,50 | | | | |
| O-Rings | 191,00 | 4,00 | | | | |
| O-Rings | 191,00 | 5,00 | | | | |
| O-Rings | 191,00 | 6,00 | | | | |
| O-Rings | 192,00 | 3,00 | | | | |
| O-Rings | 192,00 | 3,50 | | | | |
| O-Rings | 192,00 | 4,00 | | | | |
| O-Rings | 192,00 | 4,50 | | | | |
| O-Rings | 192,00 | 5,00 | | | | |
| O-Rings | 192,00 | 6,00 | | | | |
| O-Rings | 193,00 | 3,00 | | | | |
| O-Rings | 193,00 | 3,50 | | | | |
| O-Rings | 193,00 | 4,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 193,00 | 5,00 | | | | |
| O-Rings | 193,00 | 6,00 | | | | |
| O-Rings | 193,70 | 6,99 | 237 | 884 | | |
| O-Rings | 194,00 | 3,00 | | | | |
| O-Rings | 194,00 | 3,50 | | | | |
| O-Rings | 194,00 | 4,00 | | | | |
| O-Rings | 194,00 | 5,00 | | | | |
| O-Rings | 194,00 | 6,00 | | | | |
| O-Rings | 194,10 | 8,40 | | | | |
| O-Rings | 194,30 | 5,70 | | | | |
| O-Rings | 194,50 | 3,00 | | | | |
| O-Rings | 194,50 | 8,40 | | | | |
| O-Rings | 195,00 | 3,00 | | | | |
| O-Rings | 195,00 | 3,50 | | | | |
| O-Rings | 195,00 | 3,55 | | | | |
| O-Rings | 195,00 | 4,00 | | | | |
| O-Rings | 195,00 | 5,00 | | | | |
| O-Rings | 195,00 | 5,30 | | | | |
| O-Rings | 195,00 | 6,00 | | | | |
| O-Rings | 196,00 | 3,00 | | | | |
| O-Rings | 196,00 | 3,50 | | | | |
| O-Rings | 196,00 | 4,00 | | | | |
| O-Rings | 196,00 | 5,00 | | | | |
| O-Rings | 196,00 | 6,00 | | | | |
| O-Rings | 196,22 | 5,33 | 6775 | 368 | 2-368 | |
| O-Rings | 196,22 | 6,99 | 8775 | 444 | 2-444 | R72 |
| O-Rings | 196,44 | 3,53 | 4775 | 265 | 2-265 | |
| O-Rings | 196,52 | 2,62 | 3775 | 170 | 2-170 | |
| O-Rings | 197,00 | 3,00 | | | | |
| O-Rings | 197,00 | 3,50 | | | | |

| | | | | | | |
|---------|--------|------|-----|-----|--|--|
| O-Rings | 197,00 | 4,00 | | | | |
| O-Rings | 197,00 | 5,00 | | | | |
| O-Rings | 197,00 | 6,00 | | | | |
| O-Rings | 198,00 | 3,00 | | | | |
| O-Rings | 198,00 | 3,50 | | | | |
| O-Rings | 198,00 | 4,00 | | | | |
| O-Rings | 198,00 | 5,00 | | | | |
| O-Rings | 198,00 | 6,00 | | | | |
| O-Rings | 199,00 | 3,00 | | | | |
| O-Rings | 199,00 | 3,50 | | | | |
| O-Rings | 199,00 | 4,00 | | | | |
| O-Rings | 199,00 | 5,00 | | | | |
| O-Rings | 199,00 | 6,00 | | | | |
| O-Rings | 199,10 | 8,40 | | | | |
| O-Rings | 199,30 | 5,70 | | | | |
| O-Rings | 199,50 | 3,00 | | | | |
| O-Rings | 199,50 | 8,40 | | | | |
| O-Rings | 200,00 | 3,00 | | | | |
| O-Rings | 200,00 | 3,50 | | | | |
| O-Rings | 200,00 | 3,55 | | | | |
| O-Rings | 200,00 | 4,00 | | | | |
| O-Rings | 200,00 | 5,00 | | | | |
| O-Rings | 200,00 | 5,30 | | | | |
| O-Rings | 200,00 | 6,00 | | | | |
| O-Rings | 200,00 | 6,99 | 239 | 886 | | |
| O-Rings | 201,00 | 3,00 | | | | |
| O-Rings | 201,00 | 3,50 | | | | |
| O-Rings | 201,00 | 4,00 | | | | |
| O-Rings | 201,00 | 5,00 | | | | |
| O-Rings | 201,00 | 6,00 | | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 202,00 | 3,00 | | | | |
| O-Rings | 202,00 | 3,50 | | | | |
| O-Rings | 202,00 | 4,00 | | | | |
| O-Rings | 202,00 | 5,00 | | | | |
| O-Rings | 202,00 | 6,00 | | | | |
| O-Rings | 202,57 | 5,33 | 6795 | 369 | 2-369 | |
| O-Rings | 202,57 | 6,99 | 8800 | 445 | 2-445 | R73 |
| O-Rings | 202,80 | 3,53 | 4800 | 266 | 2-266 | |
| O-Rings | 202,87 | 2,62 | 3800 | 171 | 2-171 | |
| O-Rings | 203,00 | 3,00 | | | | |
| O-Rings | 203,00 | 3,50 | | | | |
| O-Rings | 203,00 | 4,00 | | | | |
| O-Rings | 203,00 | 5,00 | | | | |
| O-Rings | 203,00 | 6,00 | | | | |
| O-Rings | 204,00 | 3,00 | | | | |
| O-Rings | 204,00 | 3,50 | | | | |
| O-Rings | 204,00 | 4,00 | | | | |
| O-Rings | 204,00 | 5,00 | | | | |
| O-Rings | 204,00 | 6,00 | | | | |
| O-Rings | 204,10 | 8,40 | | | | |
| O-Rings | 204,50 | 3,00 | | | | |
| O-Rings | 204,50 | 8,40 | | | | |
| O-Rings | 205,00 | 3,00 | | | | |
| O-Rings | 205,00 | 3,50 | | | | |
| O-Rings | 205,00 | 4,00 | | | | |
| O-Rings | 205,00 | 5,00 | | | | |
| O-Rings | 205,00 | 6,00 | | | | |
| O-Rings | 206,00 | 3,00 | | | | |
| O-Rings | 206,00 | 3,50 | | | | |
| O-Rings | 206,00 | 4,00 | | | | |

| | | | | | |
|---------|--------|------|------|-----|-------|
| O-Rings | 206,00 | 5,00 | | | |
| O-Rings | 206,00 | 6,00 | | | |
| O-Rings | 206,00 | 7,00 | | | |
| O-Rings | 207,00 | 3,00 | | | |
| O-Rings | 207,00 | 3,50 | | | |
| O-Rings | 207,00 | 4,00 | | | |
| O-Rings | 207,00 | 5,00 | | | |
| O-Rings | 207,00 | 6,00 | | | |
| O-Rings | 208,00 | 3,00 | | | |
| O-Rings | 208,00 | 3,50 | | | |
| O-Rings | 208,00 | 4,00 | | | |
| O-Rings | 208,00 | 4,50 | | | |
| O-Rings | 208,00 | 5,00 | | | |
| O-Rings | 208,00 | 6,00 | | | |
| O-Rings | 208,50 | 8,40 | | | |
| O-Rings | 208,92 | 5,33 | 6820 | 370 | 2-370 |
| O-Rings | 208,92 | 6,99 | 8825 | 674 | |
| O-Rings | 209,00 | 3,00 | | | |
| O-Rings | 209,00 | 3,50 | | | |
| O-Rings | 209,00 | 4,00 | | | |
| O-Rings | 209,00 | 5,00 | | | |
| O-Rings | 209,00 | 6,00 | | | |
| O-Rings | 209,10 | 8,40 | | | |
| O-Rings | 209,14 | 3,53 | 4825 | 267 | 2-267 |
| O-Rings | 209,22 | 2,62 | 3825 | 172 | 2-172 |
| O-Rings | 209,30 | 5,70 | | | |
| O-Rings | 209,50 | 3,00 | | | |
| O-Rings | 209,50 | 8,40 | | | |
| O-Rings | 210,00 | 3,00 | | | |
| O-Rings | 210,00 | 3,50 | | | |

| | | |
|---------|--------|------|
| O-Rings | 210,00 | 4,00 |
| O-Rings | 210,00 | 5,00 |
| O-Rings | 210,00 | 6,00 |
| O-Rings | 211,00 | 3,00 |
| O-Rings | 211,00 | 3,50 |
| O-Rings | 211,00 | 4,00 |
| O-Rings | 211,00 | 5,00 |
| O-Rings | 211,00 | 6,00 |
| O-Rings | 212,00 | 3,00 |
| O-Rings | 212,00 | 3,50 |
| O-Rings | 212,00 | 4,00 |
| O-Rings | 212,00 | 5,00 |
| O-Rings | 212,00 | 6,00 |
| O-Rings | 212,00 | 7,00 |
| O-Rings | 213,00 | 3,00 |
| O-Rings | 213,00 | 3,50 |
| O-Rings | 213,00 | 4,00 |
| O-Rings | 213,00 | 5,00 |
| O-Rings | 213,00 | 6,00 |
| O-Rings | 214,00 | 3,00 |
| O-Rings | 214,00 | 3,50 |
| O-Rings | 214,00 | 4,00 |
| O-Rings | 214,00 | 5,00 |
| O-Rings | 214,00 | 6,00 |
| O-Rings | 214,50 | 8,40 |
| O-Rings | 215,00 | 3,00 |
| O-Rings | 215,00 | 3,50 |
| O-Rings | 215,00 | 4,00 |
| O-Rings | 215,00 | 4,50 |
| O-Rings | 215,00 | 5,00 |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 215,00 | 6,00 | | | | |
| O-Rings | 215,27 | 5,33 | 6850 | 371 | 2-371 | |
| O-Rings | 215,27 | 6,99 | 8850 | 446 | 2-446 | R74 |
| O-Rings | 215,50 | 3,53 | 4850 | 268 | 2-268 | |
| O-Rings | 215,57 | 2,62 | 3850 | 173 | 2-173 | |
| O-Rings | 216,00 | 3,00 | | | | |
| O-Rings | 216,00 | 3,50 | | | | |
| O-Rings | 216,00 | 4,00 | | | | |
| O-Rings | 216,00 | 5,00 | | | | |
| O-Rings | 216,00 | 6,00 | | | | |
| O-Rings | 217,00 | 3,00 | | | | |
| O-Rings | 217,00 | 3,50 | | | | |
| O-Rings | 217,00 | 4,00 | | | | |
| O-Rings | 217,00 | 5,00 | | | | |
| O-Rings | 217,00 | 6,00 | | | | |
| O-Rings | 218,00 | 3,00 | | | | |
| O-Rings | 218,00 | 3,50 | | | | |
| O-Rings | 218,00 | 4,00 | | | | |
| O-Rings | 218,00 | 4,50 | | | | |
| O-Rings | 218,00 | 5,00 | | | | |
| O-Rings | 218,00 | 6,00 | | | | |
| O-Rings | 218,00 | 7,00 | | | | |
| O-Rings | 218,50 | 4,50 | | | | |
| O-Rings | 219,00 | 3,00 | | | | |
| O-Rings | 219,00 | 3,50 | | | | |
| O-Rings | 219,00 | 4,00 | | | | |
| O-Rings | 219,00 | 5,00 | | | | |
| O-Rings | 219,00 | 6,00 | | | | |
| O-Rings | 219,10 | 8,40 | | | | |
| O-Rings | 219,30 | 5,70 | | | | |

| | | | | | |
|---------|--------|------|------|-----|-------|
| O-Rings | 219,50 | 3,00 | | | |
| O-Rings | 219,50 | 8,40 | | | |
| O-Rings | 220,00 | 3,00 | | | |
| O-Rings | 220,00 | 3,50 | | | |
| O-Rings | 220,00 | 4,00 | | | |
| O-Rings | 220,00 | 5,00 | | | |
| O-Rings | 220,00 | 6,00 | | | |
| O-Rings | 221,00 | 3,00 | | | |
| O-Rings | 221,00 | 3,50 | | | |
| O-Rings | 221,00 | 4,00 | | | |
| O-Rings | 221,00 | 5,00 | | | |
| O-Rings | 221,00 | 6,00 | | | |
| O-Rings | 221,62 | 5,33 | 6870 | 372 | 2-372 |
| O-Rings | 221,62 | 6,99 | 8875 | 676 | |
| O-Rings | 221,84 | 3,53 | 4875 | 269 | 2-269 |
| O-Rings | 221,92 | 2,62 | 3875 | 174 | 2-174 |
| O-Rings | 222,00 | 3,00 | | | |
| O-Rings | 222,00 | 3,50 | | | |
| O-Rings | 222,00 | 4,00 | | | |
| O-Rings | 222,00 | 5,00 | | | |
| O-Rings | 222,00 | 6,00 | | | |
| O-Rings | 223,00 | 3,00 | | | |
| O-Rings | 223,00 | 3,50 | | | |
| O-Rings | 223,00 | 4,00 | | | |
| O-Rings | 223,00 | 5,00 | | | |
| O-Rings | 223,00 | 6,00 | | | |
| O-Rings | 224,00 | 3,00 | | | |
| O-Rings | 224,00 | 3,50 | | | |
| O-Rings | 224,00 | 4,00 | | | |
| O-Rings | 224,00 | 5,00 | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 224,00 | 6,00 | | | | |
| O-Rings | 224,00 | 7,00 | | | | |
| O-Rings | 224,50 | 8,40 | | | | |
| O-Rings | 225,00 | 3,00 | | | | |
| O-Rings | 225,00 | 3,50 | | | | |
| O-Rings | 225,00 | 4,00 | | | | |
| O-Rings | 225,00 | 4,50 | | | | |
| O-Rings | 225,00 | 5,00 | | | | |
| O-Rings | 225,00 | 6,00 | | | | |
| O-Rings | 226,00 | 3,00 | | | | |
| O-Rings | 226,00 | 3,50 | | | | |
| O-Rings | 226,00 | 4,00 | | | | |
| O-Rings | 226,00 | 5,00 | | | | |
| O-Rings | 226,00 | 6,00 | | | | |
| O-Rings | 227,00 | 3,00 | | | | |
| O-Rings | 227,00 | 3,50 | | | | |
| O-Rings | 227,00 | 4,00 | | | | |
| O-Rings | 227,00 | 4,50 | | | | |
| O-Rings | 227,00 | 5,00 | | | | |
| O-Rings | 227,00 | 6,00 | | | | |
| O-Rings | 227,97 | 5,33 | 6895 | 373 | 2-373 | |
| O-Rings | 227,97 | 6,99 | 8900 | 447 | 2-447 | R75 |
| O-Rings | 228,00 | 3,00 | | | | |
| O-Rings | 228,00 | 3,50 | | | | |
| O-Rings | 228,00 | 4,00 | | | | |
| O-Rings | 228,00 | 5,00 | | | | |
| O-Rings | 228,00 | 6,00 | | | | |
| O-Rings | 228,20 | 3,53 | 4900 | 270 | 2-270 | |
| O-Rings | 228,27 | 2,62 | 3900 | 175 | 2-175 | |
| O-Rings | 229,00 | 3,00 | | | | |

| | | |
|---------|--------|------|
| O-Rings | 229,00 | 3,50 |
| O-Rings | 229,00 | 4,00 |
| O-Rings | 229,00 | 5,00 |
| O-Rings | 229,00 | 6,00 |
| O-Rings | 229,10 | 8,40 |
| O-Rings | 229,30 | 5,70 |
| O-Rings | 229,50 | 3,00 |
| O-Rings | 229,50 | 8,40 |
| O-Rings | 230,00 | 3,00 |
| O-Rings | 230,00 | 3,50 |
| O-Rings | 230,00 | 4,00 |
| O-Rings | 230,00 | 5,00 |
| O-Rings | 230,00 | 6,00 |
| O-Rings | 230,00 | 7,00 |
| O-Rings | 231,00 | 3,00 |
| O-Rings | 231,00 | 3,50 |
| O-Rings | 231,00 | 4,00 |
| O-Rings | 231,00 | 5,00 |
| O-Rings | 231,00 | 6,00 |
| O-Rings | 232,00 | 3,00 |
| O-Rings | 232,00 | 3,50 |
| O-Rings | 232,00 | 4,00 |
| O-Rings | 232,00 | 5,00 |
| O-Rings | 232,00 | 6,00 |
| O-Rings | 233,00 | 3,00 |
| O-Rings | 233,00 | 3,50 |
| O-Rings | 233,00 | 4,00 |
| O-Rings | 233,00 | 5,00 |
| O-Rings | 233,00 | 6,00 |
| O-Rings | 234,00 | 3,00 |

| | | | | | |
|---------|--------|------|------|-----|-------|
| O-Rings | 234,00 | 3,50 | | | |
| O-Rings | 234,00 | 4,00 | | | |
| O-Rings | 234,00 | 5,00 | | | |
| O-Rings | 234,00 | 6,00 | | | |
| O-Rings | 234,10 | 8,40 | | | |
| O-Rings | 234,32 | 5,33 | 6920 | 374 | 2-374 |
| O-Rings | 234,32 | 6,99 | 8925 | 678 | |
| O-Rings | 234,50 | 8,40 | | | |
| O-Rings | 234,54 | 3,53 | 4925 | 271 | 2-271 |
| O-Rings | 234,63 | 2,62 | 3925 | 176 | 2-176 |
| O-Rings | 235,00 | 3,00 | | | |
| O-Rings | 235,00 | 3,50 | | | |
| O-Rings | 235,00 | 4,00 | | | |
| O-Rings | 235,00 | 5,00 | | | |
| O-Rings | 235,00 | 6,00 | | | |
| O-Rings | 236,00 | 3,00 | | | |
| O-Rings | 236,00 | 3,50 | | | |
| O-Rings | 236,00 | 4,00 | | | |
| O-Rings | 236,00 | 5,00 | | | |
| O-Rings | 236,00 | 6,00 | | | |
| O-Rings | 236,00 | 7,00 | | | |
| O-Rings | 237,00 | 3,00 | | | |
| O-Rings | 237,00 | 3,50 | | | |
| O-Rings | 237,00 | 4,00 | | | |
| O-Rings | 237,00 | 5,00 | | | |
| O-Rings | 237,00 | 6,00 | | | |
| O-Rings | 238,00 | 3,00 | | | |
| O-Rings | 238,00 | 3,50 | | | |
| O-Rings | 238,00 | 4,00 | | | |
| O-Rings | 238,00 | 5,00 | | | |

| | | | | | | |
|---------|--------|------|------|-----|-------|-----|
| O-Rings | 238,00 | 6,00 | | | | |
| O-Rings | 239,00 | 3,00 | | | | |
| O-Rings | 239,00 | 3,50 | | | | |
| O-Rings | 239,00 | 4,00 | | | | |
| O-Rings | 239,00 | 5,00 | | | | |
| O-Rings | 239,00 | 6,00 | | | | |
| O-Rings | 239,10 | 8,40 | | | | |
| O-Rings | 239,30 | 5,70 | | | | |
| O-Rings | 239,50 | 3,00 | | | | |
| O-Rings | 239,50 | 8,40 | | | | |
| O-Rings | 240,00 | 3,00 | | | | |
| O-Rings | 240,00 | 3,50 | | | | |
| O-Rings | 240,00 | 4,00 | | | | |
| O-Rings | 240,00 | 5,00 | | | | |
| O-Rings | 240,00 | 6,00 | | | | |
| O-Rings | 240,67 | 5,33 | 6945 | 375 | 2-375 | |
| O-Rings | 240,67 | 6,99 | 8950 | 448 | 2-447 | R76 |
| O-Rings | 240,90 | 3,53 | 4950 | 272 | 2-272 | |
| O-Rings | 240,97 | 2,62 | 3950 | 177 | 2-177 | |
| O-Rings | 241,00 | 3,00 | | | | |
| O-Rings | 241,00 | 3,50 | | | | |
| O-Rings | 241,00 | 4,00 | | | | |
| O-Rings | 241,00 | 5,00 | | | | |
| O-Rings | 241,00 | 6,00 | | | | |
| O-Rings | 242,00 | 3,00 | | | | |
| O-Rings | 242,00 | 3,50 | | | | |
| O-Rings | 242,00 | 4,00 | | | | |
| O-Rings | 242,00 | 5,00 | | | | |
| O-Rings | 242,00 | 6,00 | | | | |
| O-Rings | 243,00 | 3,00 | | | | |

| | | | | | |
|---------|--------|------|------|-----|-------|
| O-Rings | 243,00 | 3,50 | | | |
| O-Rings | 243,00 | 4,00 | | | |
| O-Rings | 243,00 | 5,00 | | | |
| O-Rings | 243,00 | 6,00 | | | |
| O-Rings | 243,00 | 7,00 | | | |
| O-Rings | 244,00 | 3,00 | | | |
| O-Rings | 244,00 | 3,50 | | | |
| O-Rings | 244,00 | 4,00 | | | |
| O-Rings | 244,00 | 5,00 | | | |
| O-Rings | 244,00 | 6,00 | | | |
| O-Rings | 244,50 | 8,40 | | | |
| O-Rings | 245,00 | 3,00 | | | |
| O-Rings | 245,00 | 3,50 | | | |
| O-Rings | 245,00 | 4,00 | | | |
| O-Rings | 245,00 | 5,00 | | | |
| O-Rings | 245,00 | 6,00 | | | |
| O-Rings | 246,00 | 3,00 | | | |
| O-Rings | 246,00 | 3,50 | | | |
| O-Rings | 246,00 | 4,00 | | | |
| O-Rings | 246,00 | 5,00 | | | |
| O-Rings | 246,00 | 6,00 | | | |
| O-Rings | 247,00 | 3,00 | | | |
| O-Rings | 247,00 | 3,50 | | | |
| O-Rings | 247,00 | 4,00 | | | |
| O-Rings | 247,00 | 5,00 | | | |
| O-Rings | 247,00 | 6,00 | | | |
| O-Rings | 247,00 | 6,99 | 8975 | 680 | |
| O-Rings | 247,02 | 5,33 | 6975 | 376 | 2-376 |
| O-Rings | 247,26 | 3,53 | 4975 | 273 | 2-273 |
| O-Rings | 247,32 | 2,62 | 3975 | 178 | 2-178 |

| | | |
|---------|--------|------|
| O-Rings | 248,00 | 3,00 |
| O-Rings | 248,00 | 3,50 |
| O-Rings | 248,00 | 4,00 |
| O-Rings | 248,00 | 5,00 |
| O-Rings | 248,00 | 6,00 |
| O-Rings | 249,00 | 3,00 |
| O-Rings | 249,00 | 3,50 |
| O-Rings | 249,00 | 4,00 |
| O-Rings | 249,00 | 5,00 |
| O-Rings | 249,00 | 6,00 |
| O-Rings | 249,10 | 8,40 |
| O-Rings | 249,30 | 5,70 |
| O-Rings | 249,50 | 3,00 |
| O-Rings | 249,50 | 8,40 |
| O-Rings | 250,00 | 3,00 |
| O-Rings | 250,00 | 3,50 |
| O-Rings | 250,00 | 4,00 |
| O-Rings | 250,00 | 4,50 |
| O-Rings | 250,00 | 5,00 |
| O-Rings | 250,00 | 6,00 |
| O-Rings | 250,00 | 7,00 |
| O-Rings | 251,00 | 3,00 |
| O-Rings | 251,00 | 3,50 |
| O-Rings | 251,00 | 4,00 |
| O-Rings | 251,00 | 5,00 |
| O-Rings | 251,00 | 6,00 |
| O-Rings | 252,00 | 3,00 |
| O-Rings | 252,00 | 3,50 |
| O-Rings | 252,00 | 4,00 |
| O-Rings | 252,00 | 5,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 252,00 | 6,00 | | | | |
| O-Rings | 253,00 | 3,00 | | | | |
| O-Rings | 253,00 | 3,50 | | | | |
| O-Rings | 253,00 | 4,00 | | | | |
| O-Rings | 253,00 | 5,00 | | | | |
| O-Rings | 253,00 | 6,00 | | | | |
| O-Rings | 253,37 | 5,33 | 6995 | 377 | 2-377 | |
| O-Rings | 253,57 | 6,99 | 81000 | 449 | 2-449 | R77 |
| O-Rings | 253,60 | 3,53 | 4100 | 274 | 2-274 | |
| O-Rings | 254,00 | 3,00 | | | | |
| O-Rings | 254,00 | 3,50 | | | | |
| O-Rings | 254,00 | 4,00 | | | | |
| O-Rings | 254,00 | 5,00 | | | | |
| O-Rings | 254,00 | 6,00 | | | | |
| O-Rings | 254,50 | 8,40 | | | | |
| O-Rings | 255,00 | 3,00 | | | | |
| O-Rings | 255,00 | 3,50 | | | | |
| O-Rings | 255,00 | 4,00 | | | | |
| O-Rings | 255,00 | 5,00 | | | | |
| O-Rings | 255,00 | 6,00 | | | | |
| O-Rings | 256,00 | 3,00 | | | | |
| O-Rings | 256,00 | 3,50 | | | | |
| O-Rings | 256,00 | 4,00 | | | | |
| O-Rings | 256,00 | 5,00 | | | | |
| O-Rings | 256,00 | 6,00 | | | | |
| O-Rings | 257,00 | 3,00 | | | | |
| O-Rings | 257,00 | 3,50 | | | | |
| O-Rings | 257,00 | 4,00 | | | | |
| O-Rings | 257,00 | 5,00 | | | | |
| O-Rings | 257,00 | 6,00 | | | | |

| | | | | | |
|---------|--------|------|-------|-----|--|
| O-Rings | 258,00 | 3,00 | | | |
| O-Rings | 258,00 | 3,50 | | | |
| O-Rings | 258,00 | 4,00 | | | |
| O-Rings | 258,00 | 5,00 | | | |
| O-Rings | 258,00 | 6,00 | | | |
| O-Rings | 258,00 | 7,00 | | | |
| O-Rings | 259,00 | 3,00 | | | |
| O-Rings | 259,00 | 3,50 | | | |
| O-Rings | 259,00 | 4,00 | | | |
| O-Rings | 259,00 | 5,00 | | | |
| O-Rings | 259,00 | 6,00 | | | |
| O-Rings | 259,30 | 5,70 | | | |
| O-Rings | 259,50 | 8,40 | | | |
| O-Rings | 259,70 | 6,99 | 81025 | 682 | |
| O-Rings | 260,00 | 3,00 | | | |
| O-Rings | 260,00 | 3,50 | | | |
| O-Rings | 260,00 | 4,00 | | | |
| O-Rings | 260,00 | 5,00 | | | |
| O-Rings | 260,00 | 6,00 | | | |
| O-Rings | 261,00 | 3,00 | | | |
| O-Rings | 261,00 | 3,50 | | | |
| O-Rings | 261,00 | 4,00 | | | |
| O-Rings | 261,00 | 5,00 | | | |
| O-Rings | 261,00 | 6,00 | | | |
| O-Rings | 262,00 | 3,00 | | | |
| O-Rings | 262,00 | 3,50 | | | |
| O-Rings | 262,00 | 4,00 | | | |
| O-Rings | 262,00 | 5,00 | | | |
| O-Rings | 262,00 | 6,00 | | | |
| O-Rings | 263,00 | 3,00 | | | |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 263,00 | 3,50 | | | | |
| O-Rings | 263,00 | 4,00 | | | | |
| O-Rings | 263,00 | 5,00 | | | | |
| O-Rings | 263,00 | 6,00 | | | | |
| O-Rings | 264,00 | 3,00 | | | | |
| O-Rings | 264,00 | 3,50 | | | | |
| O-Rings | 264,00 | 4,00 | | | | |
| O-Rings | 264,00 | 5,00 | | | | |
| O-Rings | 264,00 | 6,00 | | | | |
| O-Rings | 264,50 | 8,40 | | | | |
| O-Rings | 265,00 | 3,00 | | | | |
| O-Rings | 265,00 | 3,50 | | | | |
| O-Rings | 265,00 | 4,00 | | | | |
| O-Rings | 265,00 | 5,00 | | | | |
| O-Rings | 265,00 | 6,00 | | | | |
| O-Rings | 265,00 | 7,00 | | | | |
| O-Rings | 266,00 | 3,00 | | | | |
| O-Rings | 266,00 | 3,50 | | | | |
| O-Rings | 266,00 | 4,00 | | | | |
| O-Rings | 266,00 | 5,00 | | | | |
| O-Rings | 266,00 | 6,00 | | | | |
| O-Rings | 266,07 | 5,33 | 61050 | 378 | 2-378 | |
| O-Rings | 266,07 | 6,99 | 81050 | 450 | 2-450 | R78 |
| O-Rings | 266,30 | 3,53 | 41050 | 275 | 2-275 | |
| O-Rings | 267,00 | 3,00 | | | | |
| O-Rings | 267,00 | 3,50 | | | | |
| O-Rings | 267,00 | 4,00 | | | | |
| O-Rings | 267,00 | 4,50 | | | | |
| O-Rings | 267,00 | 5,00 | | | | |
| O-Rings | 267,00 | 6,00 | | | | |

| | | | | | |
|---------|--------|------|-------|-----|--|
| O-Rings | 268,00 | 3,00 | | | |
| O-Rings | 268,00 | 3,50 | | | |
| O-Rings | 268,00 | 4,00 | | | |
| O-Rings | 268,00 | 5,00 | | | |
| O-Rings | 268,00 | 6,00 | | | |
| O-Rings | 269,00 | 3,00 | | | |
| O-Rings | 269,00 | 3,50 | | | |
| O-Rings | 269,00 | 4,00 | | | |
| O-Rings | 269,00 | 5,00 | | | |
| O-Rings | 269,00 | 6,00 | | | |
| O-Rings | 269,30 | 5,70 | | | |
| O-Rings | 269,50 | 8,40 | | | |
| O-Rings | 270,00 | 3,00 | | | |
| O-Rings | 270,00 | 3,50 | | | |
| O-Rings | 270,00 | 4,00 | | | |
| O-Rings | 270,00 | 5,00 | | | |
| O-Rings | 270,00 | 6,00 | | | |
| O-Rings | 271,00 | 3,00 | | | |
| O-Rings | 271,00 | 3,50 | | | |
| O-Rings | 271,00 | 4,00 | | | |
| O-Rings | 271,00 | 5,00 | | | |
| O-Rings | 271,00 | 6,00 | | | |
| O-Rings | 272,00 | 3,00 | | | |
| O-Rings | 272,00 | 3,50 | | | |
| O-Rings | 272,00 | 4,00 | | | |
| O-Rings | 272,00 | 5,00 | | | |
| O-Rings | 272,00 | 6,00 | | | |
| O-Rings | 272,00 | 7,00 | | | |
| O-Rings | 272,40 | 6,99 | 81075 | 684 | |
| O-Rings | 273,00 | 3,00 | | | |

| | | |
|---------|--------|------|
| O-Rings | 273,00 | 3,50 |
| O-Rings | 273,00 | 4,00 |
| O-Rings | 273,00 | 5,00 |
| O-Rings | 273,00 | 6,00 |
| O-Rings | 274,00 | 3,00 |
| O-Rings | 274,00 | 3,50 |
| O-Rings | 274,00 | 4,00 |
| O-Rings | 274,00 | 5,00 |
| O-Rings | 274,00 | 6,00 |
| O-Rings | 274,50 | 8,40 |
| O-Rings | 275,00 | 3,00 |
| O-Rings | 275,00 | 3,50 |
| O-Rings | 275,00 | 4,00 |
| O-Rings | 275,00 | 5,00 |
| O-Rings | 275,00 | 6,00 |
| O-Rings | 276,00 | 3,00 |
| O-Rings | 276,00 | 3,50 |
| O-Rings | 276,00 | 4,00 |
| O-Rings | 276,00 | 5,00 |
| O-Rings | 276,00 | 6,00 |
| O-Rings | 277,00 | 3,00 |
| O-Rings | 277,00 | 3,50 |
| O-Rings | 277,00 | 4,00 |
| O-Rings | 277,00 | 5,00 |
| O-Rings | 277,00 | 6,00 |
| O-Rings | 278,00 | 3,00 |
| O-Rings | 278,00 | 3,50 |
| O-Rings | 278,00 | 4,00 |
| O-Rings | 278,00 | 5,00 |
| O-Rings | 278,00 | 6,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 278,77 | 5,33 | 61100 | 379 | 2-379 | |
| O-Rings | 278,77 | 6,99 | 81100 | 451 | 2-451 | R79 |
| O-Rings | 279,00 | 3,00 | | | | |
| O-Rings | 279,00 | 3,50 | | | | |
| O-Rings | 279,00 | 3,53 | 41100 | 276 | 2-276 | |
| O-Rings | 279,00 | 4,00 | | | | |
| O-Rings | 279,00 | 5,00 | | | | |
| O-Rings | 279,00 | 6,00 | | | | |
| O-Rings | 279,30 | 5,70 | | | | |
| O-Rings | 279,50 | 8,40 | | | | |
| O-Rings | 280,00 | 3,00 | | | | |
| O-Rings | 280,00 | 3,50 | | | | |
| O-Rings | 280,00 | 4,00 | | | | |
| O-Rings | 280,00 | 4,50 | | | | |
| O-Rings | 280,00 | 5,00 | | | | |
| O-Rings | 280,00 | 6,00 | | | | |
| O-Rings | 280,00 | 7,00 | | | | |
| O-Rings | 281,00 | 3,00 | | | | |
| O-Rings | 281,00 | 3,50 | | | | |
| O-Rings | 281,00 | 4,00 | | | | |
| O-Rings | 281,00 | 5,00 | | | | |
| O-Rings | 281,00 | 6,00 | | | | |
| O-Rings | 282,00 | 3,00 | | | | |
| O-Rings | 282,00 | 3,50 | | | | |
| O-Rings | 282,00 | 4,00 | | | | |
| O-Rings | 282,00 | 5,00 | | | | |
| O-Rings | 282,00 | 6,00 | | | | |
| O-Rings | 283,00 | 3,00 | | | | |
| O-Rings | 283,00 | 3,50 | | | | |
| O-Rings | 283,00 | 4,00 | | | | |

| | | | | | | |
|---------|--------|------|-------|-----|--|--|
| O-Rings | 283,00 | 5,00 | | | | |
| O-Rings | 283,00 | 6,00 | | | | |
| O-Rings | 284,00 | 3,00 | | | | |
| O-Rings | 284,00 | 3,50 | | | | |
| O-Rings | 284,00 | 4,00 | | | | |
| O-Rings | 284,00 | 5,00 | | | | |
| O-Rings | 284,00 | 6,00 | | | | |
| O-Rings | 284,50 | 8,40 | | | | |
| O-Rings | 285,00 | 3,00 | | | | |
| O-Rings | 285,00 | 3,50 | | | | |
| O-Rings | 285,00 | 4,00 | | | | |
| O-Rings | 285,00 | 5,00 | | | | |
| O-Rings | 285,00 | 6,00 | | | | |
| O-Rings | 285,10 | 6,99 | 81125 | 686 | | |
| O-Rings | 286,00 | 3,00 | | | | |
| O-Rings | 286,00 | 3,50 | | | | |
| O-Rings | 286,00 | 4,00 | | | | |
| O-Rings | 286,00 | 5,00 | | | | |
| O-Rings | 286,00 | 6,00 | | | | |
| O-Rings | 287,00 | 3,00 | | | | |
| O-Rings | 287,00 | 3,50 | | | | |
| O-Rings | 287,00 | 4,00 | | | | |
| O-Rings | 287,00 | 5,00 | | | | |
| O-Rings | 287,00 | 6,00 | | | | |
| O-Rings | 288,00 | 3,00 | | | | |
| O-Rings | 288,00 | 3,50 | | | | |
| O-Rings | 288,00 | 4,00 | | | | |
| O-Rings | 288,00 | 5,00 | | | | |
| O-Rings | 288,00 | 6,00 | | | | |
| O-Rings | 289,00 | 3,00 | | | | |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 289,00 | 3,50 | | | | |
| O-Rings | 289,00 | 4,00 | | | | |
| O-Rings | 289,00 | 5,00 | | | | |
| O-Rings | 289,00 | 6,00 | | | | |
| O-Rings | 289,30 | 5,70 | | | | |
| O-Rings | 289,50 | 8,40 | | | | |
| O-Rings | 290,00 | 3,00 | | | | |
| O-Rings | 290,00 | 3,50 | | | | |
| O-Rings | 290,00 | 4,00 | | | | |
| O-Rings | 290,00 | 5,00 | | | | |
| O-Rings | 290,00 | 6,00 | | | | |
| O-Rings | 290,00 | 7,00 | | | | |
| O-Rings | 291,00 | 3,00 | | | | |
| O-Rings | 291,00 | 3,50 | | | | |
| O-Rings | 291,00 | 4,00 | | | | |
| O-Rings | 291,00 | 5,00 | | | | |
| O-Rings | 291,00 | 6,00 | | | | |
| O-Rings | 291,47 | 5,33 | 61150 | 380 | 2-380 | |
| O-Rings | 291,47 | 6,99 | 81150 | 452 | 2-452 | R80 |
| O-Rings | 291,70 | 3,53 | 41150 | 277 | 2-277 | |
| O-Rings | 292,00 | 3,00 | | | | |
| O-Rings | 292,00 | 3,50 | | | | |
| O-Rings | 292,00 | 4,00 | | | | |
| O-Rings | 292,00 | 5,00 | | | | |
| O-Rings | 292,00 | 6,00 | | | | |
| O-Rings | 293,00 | 3,00 | | | | |
| O-Rings | 293,00 | 3,50 | | | | |
| O-Rings | 293,00 | 4,00 | | | | |
| O-Rings | 293,00 | 5,00 | | | | |
| O-Rings | 293,00 | 6,00 | | | | |

| | | | | | |
|---------|--------|------|-------|-----|--|
| O-Rings | 294,00 | 3,00 | | | |
| O-Rings | 294,00 | 3,50 | | | |
| O-Rings | 294,00 | 4,00 | | | |
| O-Rings | 294,00 | 5,00 | | | |
| O-Rings | 294,00 | 6,00 | | | |
| O-Rings | 294,50 | 8,40 | | | |
| O-Rings | 295,00 | 3,00 | | | |
| O-Rings | 295,00 | 3,50 | | | |
| O-Rings | 295,00 | 4,00 | | | |
| O-Rings | 295,00 | 5,00 | | | |
| O-Rings | 295,00 | 6,00 | | | |
| O-Rings | 296,00 | 3,00 | | | |
| O-Rings | 296,00 | 3,50 | | | |
| O-Rings | 296,00 | 4,00 | | | |
| O-Rings | 296,00 | 5,00 | | | |
| O-Rings | 296,00 | 6,00 | | | |
| O-Rings | 297,00 | 3,00 | | | |
| O-Rings | 297,00 | 3,50 | | | |
| O-Rings | 297,00 | 4,00 | | | |
| O-Rings | 297,00 | 5,00 | | | |
| O-Rings | 297,00 | 6,00 | | | |
| O-Rings | 297,80 | 6,99 | 81175 | 688 | |
| O-Rings | 298,00 | 3,00 | | | |
| O-Rings | 298,00 | 3,50 | | | |
| O-Rings | 298,00 | 4,00 | | | |
| O-Rings | 298,00 | 5,00 | | | |
| O-Rings | 298,00 | 6,00 | | | |
| O-Rings | 299,00 | 3,00 | | | |
| O-Rings | 299,00 | 3,50 | | | |
| O-Rings | 299,00 | 4,00 | | | |

| | | |
|---------|--------|------|
| O-Rings | 299,00 | 5,00 |
| O-Rings | 299,00 | 6,00 |
| O-Rings | 299,30 | 5,70 |
| O-Rings | 299,50 | 8,40 |
| O-Rings | 300,00 | 3,00 |
| O-Rings | 300,00 | 3,50 |
| O-Rings | 300,00 | 4,00 |
| O-Rings | 300,00 | 5,00 |
| O-Rings | 300,00 | 6,00 |
| O-Rings | 300,00 | 7,00 |
| O-Rings | 301,00 | 3,00 |
| O-Rings | 301,00 | 3,50 |
| O-Rings | 301,00 | 4,00 |
| O-Rings | 301,00 | 5,00 |
| O-Rings | 301,00 | 6,00 |
| O-Rings | 302,00 | 3,00 |
| O-Rings | 302,00 | 3,50 |
| O-Rings | 302,00 | 4,00 |
| O-Rings | 302,00 | 5,00 |
| O-Rings | 302,00 | 6,00 |
| O-Rings | 303,00 | 3,00 |
| O-Rings | 303,00 | 3,50 |
| O-Rings | 303,00 | 4,00 |
| O-Rings | 303,00 | 5,00 |
| O-Rings | 303,00 | 6,00 |
| O-Rings | 304,00 | 3,00 |
| O-Rings | 304,00 | 3,50 |
| O-Rings | 304,00 | 4,00 |
| O-Rings | 304,00 | 5,00 |
| O-Rings | 304,00 | 6,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 304,17 | 5,33 | 61200 | 381 | 2-381 | |
| O-Rings | 304,17 | 6,99 | 81200 | 453 | 2-453 | R81 |
| O-Rings | 304,40 | 3,53 | 41200 | 278 | 2-278 | |
| O-Rings | 305,00 | 3,00 | | | | |
| O-Rings | 305,00 | 3,50 | | | | |
| O-Rings | 305,00 | 4,00 | | | | |
| O-Rings | 305,00 | 5,00 | | | | |
| O-Rings | 305,00 | 6,00 | | | | |
| O-Rings | 306,00 | 3,00 | | | | |
| O-Rings | 306,00 | 3,50 | | | | |
| O-Rings | 306,00 | 4,00 | | | | |
| O-Rings | 306,00 | 5,00 | | | | |
| O-Rings | 306,00 | 6,00 | | | | |
| O-Rings | 307,00 | 3,00 | | | | |
| O-Rings | 307,00 | 3,50 | | | | |
| O-Rings | 307,00 | 4,00 | | | | |
| O-Rings | 307,00 | 5,00 | | | | |
| O-Rings | 307,00 | 6,00 | | | | |
| O-Rings | 307,00 | 7,00 | | | | |
| O-Rings | 308,00 | 3,00 | | | | |
| O-Rings | 308,00 | 3,50 | | | | |
| O-Rings | 308,00 | 4,00 | | | | |
| O-Rings | 308,00 | 5,00 | | | | |
| O-Rings | 308,00 | 6,00 | | | | |
| O-Rings | 309,00 | 3,00 | | | | |
| O-Rings | 309,00 | 3,50 | | | | |
| O-Rings | 309,00 | 4,00 | | | | |
| O-Rings | 309,00 | 5,00 | | | | |
| O-Rings | 309,00 | 6,00 | | | | |
| O-Rings | 310,00 | 3,00 | | | | |

| | | | | | |
|---------|--------|------|-----|--|--|
| O-Rings | 310,00 | 3,50 | | | |
| O-Rings | 310,00 | 4,00 | | | |
| O-Rings | 310,00 | 5,00 | | | |
| O-Rings | 310,00 | 6,00 | | | |
| O-Rings | 310,50 | 6,99 | 648 | | |
| O-Rings | 311,00 | 3,00 | | | |
| O-Rings | 311,00 | 3,50 | | | |
| O-Rings | 311,00 | 4,00 | | | |
| O-Rings | 311,00 | 5,00 | | | |
| O-Rings | 311,00 | 6,00 | | | |
| O-Rings | 312,00 | 3,00 | | | |
| O-Rings | 312,00 | 3,50 | | | |
| O-Rings | 312,00 | 4,00 | | | |
| O-Rings | 312,00 | 5,00 | | | |
| O-Rings | 312,00 | 6,00 | | | |
| O-Rings | 313,00 | 3,00 | | | |
| O-Rings | 313,00 | 3,50 | | | |
| O-Rings | 313,00 | 4,00 | | | |
| O-Rings | 313,00 | 5,00 | | | |
| O-Rings | 313,00 | 6,00 | | | |
| O-Rings | 314,00 | 3,00 | | | |
| O-Rings | 314,00 | 3,50 | | | |
| O-Rings | 314,00 | 4,00 | | | |
| O-Rings | 314,00 | 5,00 | | | |
| O-Rings | 314,00 | 6,00 | | | |
| O-Rings | 314,50 | 8,40 | | | |
| O-Rings | 315,00 | 3,00 | | | |
| O-Rings | 315,00 | 3,50 | | | |
| O-Rings | 315,00 | 4,00 | | | |
| O-Rings | 315,00 | 4,50 | | | |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 315,00 | 5,00 | | | | |
| O-Rings | 315,00 | 6,00 | | | | |
| O-Rings | 315,00 | 7,00 | | | | |
| O-Rings | 316,00 | 3,00 | | | | |
| O-Rings | 316,00 | 3,50 | | | | |
| O-Rings | 316,00 | 4,00 | | | | |
| O-Rings | 316,00 | 5,00 | | | | |
| O-Rings | 316,00 | 6,00 | | | | |
| O-Rings | 316,87 | 6,99 | 81250 | 454 | 2-454 | R82 |
| O-Rings | 317,00 | 3,00 | | | | |
| O-Rings | 317,00 | 3,50 | | | | |
| O-Rings | 317,00 | 4,00 | | | | |
| O-Rings | 317,00 | 5,00 | | | | |
| O-Rings | 317,00 | 6,00 | | | | |
| O-Rings | 318,00 | 3,00 | | | | |
| O-Rings | 318,00 | 3,50 | | | | |
| O-Rings | 318,00 | 4,00 | | | | |
| O-Rings | 318,00 | 5,00 | | | | |
| O-Rings | 318,00 | 6,00 | | | | |
| O-Rings | 319,00 | 3,00 | | | | |
| O-Rings | 319,00 | 3,50 | | | | |
| O-Rings | 319,00 | 4,00 | | | | |
| O-Rings | 319,00 | 5,00 | | | | |
| O-Rings | 319,00 | 6,00 | | | | |
| O-Rings | 319,30 | 5,70 | | | | |
| O-Rings | 319,50 | 8,40 | | | | |
| O-Rings | 320,00 | 3,00 | | | | |
| O-Rings | 320,00 | 3,50 | | | | |
| O-Rings | 320,00 | 4,00 | | | | |
| O-Rings | 320,00 | 5,00 | | | | |

| | | |
|---------|--------|------|
| O-Rings | 320,00 | 6,00 |
| O-Rings | 321,00 | 3,00 |
| O-Rings | 321,00 | 3,50 |
| O-Rings | 321,00 | 4,00 |
| O-Rings | 321,00 | 5,00 |
| O-Rings | 321,00 | 6,00 |
| O-Rings | 322,00 | 3,00 |
| O-Rings | 322,00 | 3,50 |
| O-Rings | 322,00 | 4,00 |
| O-Rings | 322,00 | 5,00 |
| O-Rings | 322,00 | 6,00 |
| O-Rings | 323,00 | 3,00 |
| O-Rings | 323,00 | 3,50 |
| O-Rings | 323,00 | 4,00 |
| O-Rings | 323,00 | 5,00 |
| O-Rings | 323,00 | 6,00 |
| O-Rings | 323,20 | 6,99 |
| O-Rings | 324,00 | 3,00 |
| O-Rings | 324,00 | 3,50 |
| O-Rings | 324,00 | 4,00 |
| O-Rings | 324,00 | 5,00 |
| O-Rings | 324,00 | 6,00 |
| O-Rings | 325,00 | 3,00 |
| O-Rings | 325,00 | 3,50 |
| O-Rings | 325,00 | 4,00 |
| O-Rings | 325,00 | 5,00 |
| O-Rings | 325,00 | 6,00 |
| O-Rings | 325,00 | 7,00 |
| O-Rings | 326,00 | 3,00 |
| O-Rings | 326,00 | 3,50 |

649

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 326,00 | 4,00 | | | | |
| O-Rings | 326,00 | 5,00 | | | | |
| O-Rings | 326,00 | 6,00 | | | | |
| O-Rings | 327,00 | 3,00 | | | | |
| O-Rings | 327,00 | 3,50 | | | | |
| O-Rings | 327,00 | 4,00 | | | | |
| O-Rings | 327,00 | 5,00 | | | | |
| O-Rings | 327,00 | 6,00 | | | | |
| O-Rings | 328,00 | 3,00 | | | | |
| O-Rings | 328,00 | 3,50 | | | | |
| O-Rings | 328,00 | 4,00 | | | | |
| O-Rings | 328,00 | 5,00 | | | | |
| O-Rings | 328,00 | 6,00 | | | | |
| O-Rings | 329,00 | 3,00 | | | | |
| O-Rings | 329,00 | 3,50 | | | | |
| O-Rings | 329,00 | 4,00 | | | | |
| O-Rings | 329,00 | 5,00 | | | | |
| O-Rings | 329,00 | 6,00 | | | | |
| O-Rings | 329,30 | 5,70 | | | | |
| O-Rings | 329,57 | 5,33 | 61300 | 382 | 2-382 | |
| O-Rings | 329,57 | 6,99 | 81300 | 455 | 2-455 | R83 |
| O-Rings | 329,80 | 3,53 | 41300 | 279 | 2-279 | |
| O-Rings | 330,00 | 3,00 | | | | |
| O-Rings | 330,00 | 3,50 | | | | |
| O-Rings | 330,00 | 4,00 | | | | |
| O-Rings | 330,00 | 5,00 | | | | |
| O-Rings | 330,00 | 6,00 | | | | |
| O-Rings | 331,00 | 3,00 | | | | |
| O-Rings | 331,00 | 3,50 | | | | |
| O-Rings | 331,00 | 4,00 | | | | |

| | | | | | |
|---------|--------|------|-----|--|--|
| O-Rings | 331,00 | 5,00 | | | |
| O-Rings | 331,00 | 6,00 | | | |
| O-Rings | 332,00 | 3,00 | | | |
| O-Rings | 332,00 | 3,50 | | | |
| O-Rings | 332,00 | 4,00 | | | |
| O-Rings | 332,00 | 5,00 | | | |
| O-Rings | 332,00 | 6,00 | | | |
| O-Rings | 333,00 | 3,00 | | | |
| O-Rings | 333,00 | 3,50 | | | |
| O-Rings | 333,00 | 4,00 | | | |
| O-Rings | 333,00 | 5,00 | | | |
| O-Rings | 333,00 | 6,00 | | | |
| O-Rings | 334,00 | 3,00 | | | |
| O-Rings | 334,00 | 3,50 | | | |
| O-Rings | 334,00 | 4,00 | | | |
| O-Rings | 334,00 | 5,00 | | | |
| O-Rings | 334,00 | 6,00 | | | |
| O-Rings | 334,50 | 8,40 | | | |
| O-Rings | 335,00 | 3,00 | | | |
| O-Rings | 335,00 | 3,50 | | | |
| O-Rings | 335,00 | 4,00 | | | |
| O-Rings | 335,00 | 5,00 | | | |
| O-Rings | 335,00 | 6,00 | | | |
| O-Rings | 335,00 | 7,00 | | | |
| O-Rings | 335,90 | 6,99 | 650 | | |
| O-Rings | 336,00 | 3,00 | | | |
| O-Rings | 336,00 | 3,50 | | | |
| O-Rings | 336,00 | 4,00 | | | |
| O-Rings | 336,00 | 5,00 | | | |
| O-Rings | 336,00 | 6,00 | | | |

| | | |
|---------|--------|------|
| O-Rings | 337,00 | 3,00 |
| O-Rings | 337,00 | 3,50 |
| O-Rings | 337,00 | 4,00 |
| O-Rings | 337,00 | 5,00 |
| O-Rings | 337,00 | 6,00 |
| O-Rings | 338,00 | 3,00 |
| O-Rings | 338,00 | 3,50 |
| O-Rings | 338,00 | 4,00 |
| O-Rings | 338,00 | 5,00 |
| O-Rings | 338,00 | 6,00 |
| O-Rings | 339,00 | 3,00 |
| O-Rings | 339,00 | 3,50 |
| O-Rings | 339,00 | 4,00 |
| O-Rings | 339,00 | 5,00 |
| O-Rings | 339,00 | 6,00 |
| O-Rings | 339,30 | 5,70 |
| O-Rings | 339,50 | 8,40 |
| O-Rings | 340,00 | 3,00 |
| O-Rings | 340,00 | 3,50 |
| O-Rings | 340,00 | 4,00 |
| O-Rings | 340,00 | 5,00 |
| O-Rings | 340,00 | 6,00 |
| O-Rings | 341,00 | 3,00 |
| O-Rings | 341,00 | 3,50 |
| O-Rings | 341,00 | 4,00 |
| O-Rings | 341,00 | 5,00 |
| O-Rings | 341,00 | 6,00 |
| O-Rings | 342,00 | 3,00 |
| O-Rings | 342,00 | 3,50 |
| O-Rings | 342,00 | 4,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 342,00 | 5,00 | | | | |
| O-Rings | 342,00 | 6,00 | | | | |
| O-Rings | 342,27 | 6,99 | 81350 | 456 | 2-456 | R84 |
| O-Rings | 343,00 | 3,00 | | | | |
| O-Rings | 343,00 | 3,50 | | | | |
| O-Rings | 343,00 | 4,00 | | | | |
| O-Rings | 343,00 | 5,00 | | | | |
| O-Rings | 343,00 | 6,00 | | | | |
| O-Rings | 344,00 | 3,00 | | | | |
| O-Rings | 344,00 | 3,50 | | | | |
| O-Rings | 344,00 | 4,00 | | | | |
| O-Rings | 344,00 | 5,00 | | | | |
| O-Rings | 344,00 | 6,00 | | | | |
| O-Rings | 345,00 | 3,00 | | | | |
| O-Rings | 345,00 | 3,50 | | | | |
| O-Rings | 345,00 | 4,00 | | | | |
| O-Rings | 345,00 | 5,00 | | | | |
| O-Rings | 345,00 | 6,00 | | | | |
| O-Rings | 345,00 | 7,00 | | | | |
| O-Rings | 346,00 | 3,00 | | | | |
| O-Rings | 346,00 | 3,50 | | | | |
| O-Rings | 346,00 | 4,00 | | | | |
| O-Rings | 346,00 | 5,00 | | | | |
| O-Rings | 346,00 | 6,00 | | | | |
| O-Rings | 347,00 | 3,00 | | | | |
| O-Rings | 347,00 | 3,50 | | | | |
| O-Rings | 347,00 | 4,00 | | | | |
| O-Rings | 347,00 | 5,00 | | | | |
| O-Rings | 347,00 | 6,00 | | | | |
| O-Rings | 348,00 | 3,00 | | | | |

| | | |
|---------|--------|------|
| O-Rings | 348,00 | 3,50 |
| O-Rings | 348,00 | 4,00 |
| O-Rings | 348,00 | 5,00 |
| O-Rings | 348,00 | 6,00 |
| O-Rings | 349,00 | 3,00 |
| O-Rings | 349,00 | 3,50 |
| O-Rings | 349,00 | 4,00 |
| O-Rings | 349,00 | 5,00 |
| O-Rings | 349,00 | 6,00 |
| O-Rings | 350,00 | 3,00 |
| O-Rings | 350,00 | 3,50 |
| O-Rings | 350,00 | 4,00 |
| O-Rings | 350,00 | 5,00 |
| O-Rings | 350,00 | 6,00 |
| O-Rings | 351,00 | 3,00 |
| O-Rings | 351,00 | 3,50 |
| O-Rings | 351,00 | 4,00 |
| O-Rings | 351,00 | 5,00 |
| O-Rings | 351,00 | 6,00 |
| O-Rings | 352,00 | 3,00 |
| O-Rings | 352,00 | 3,50 |
| O-Rings | 352,00 | 4,00 |
| O-Rings | 352,00 | 5,00 |
| O-Rings | 352,00 | 6,00 |
| O-Rings | 353,00 | 3,00 |
| O-Rings | 353,00 | 3,50 |
| O-Rings | 353,00 | 4,00 |
| O-Rings | 353,00 | 5,00 |
| O-Rings | 353,00 | 6,00 |
| O-Rings | 354,00 | 3,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 354,00 | 3,50 | | | | |
| O-Rings | 354,00 | 4,00 | | | | |
| O-Rings | 354,00 | 5,00 | | | | |
| O-Rings | 354,00 | 6,00 | | | | |
| O-Rings | 354,50 | 8,40 | | | | |
| O-Rings | 354,97 | 5,33 | 61400 | 383 | 2-383 | |
| O-Rings | 354,97 | 6,99 | 81400 | 457 | 2-457 | R85 |
| O-Rings | 355,00 | 3,00 | | | | |
| O-Rings | 355,00 | 3,50 | | | | |
| O-Rings | 355,00 | 4,00 | | | | |
| O-Rings | 355,00 | 5,00 | | | | |
| O-Rings | 355,00 | 6,00 | | | | |
| O-Rings | 355,00 | 7,00 | | | | |
| O-Rings | 355,20 | 3,53 | 41400 | 280 | 2-280 | |
| O-Rings | 356,00 | 3,00 | | | | |
| O-Rings | 356,00 | 3,50 | | | | |
| O-Rings | 356,00 | 4,00 | | | | |
| O-Rings | 356,00 | 5,00 | | | | |
| O-Rings | 356,00 | 6,00 | | | | |
| O-Rings | 357,00 | 3,00 | | | | |
| O-Rings | 357,00 | 3,50 | | | | |
| O-Rings | 357,00 | 4,00 | | | | |
| O-Rings | 357,00 | 5,00 | | | | |
| O-Rings | 357,00 | 6,00 | | | | |
| O-Rings | 358,00 | 3,00 | | | | |
| O-Rings | 358,00 | 3,50 | | | | |
| O-Rings | 358,00 | 4,00 | | | | |
| O-Rings | 358,00 | 5,00 | | | | |
| O-Rings | 358,00 | 6,00 | | | | |
| O-Rings | 359,00 | 3,00 | | | | |

| | | |
|---------|--------|------|
| O-Rings | 359,00 | 3,50 |
| O-Rings | 359,00 | 4,00 |
| O-Rings | 359,00 | 5,00 |
| O-Rings | 359,00 | 6,00 |
| O-Rings | 359,30 | 5,70 |
| O-Rings | 359,50 | 8,40 |
| O-Rings | 360,00 | 3,00 |
| O-Rings | 360,00 | 3,50 |
| O-Rings | 360,00 | 4,00 |
| O-Rings | 360,00 | 5,00 |
| O-Rings | 360,00 | 6,00 |
| O-Rings | 361,00 | 3,00 |
| O-Rings | 361,00 | 3,50 |
| O-Rings | 361,00 | 4,00 |
| O-Rings | 361,00 | 5,00 |
| O-Rings | 361,00 | 6,00 |
| O-Rings | 362,00 | 3,00 |
| O-Rings | 362,00 | 3,50 |
| O-Rings | 362,00 | 4,00 |
| O-Rings | 362,00 | 5,00 |
| O-Rings | 362,00 | 6,00 |
| O-Rings | 363,00 | 3,00 |
| O-Rings | 363,00 | 3,50 |
| O-Rings | 363,00 | 4,00 |
| O-Rings | 363,00 | 5,00 |
| O-Rings | 363,00 | 6,00 |
| O-Rings | 364,00 | 3,00 |
| O-Rings | 364,00 | 3,50 |
| O-Rings | 364,00 | 4,00 |
| O-Rings | 364,00 | 5,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 364,00 | 6,00 | | | | |
| O-Rings | 365,00 | 3,00 | | | | |
| O-Rings | 365,00 | 3,50 | | | | |
| O-Rings | 365,00 | 4,00 | | | | |
| O-Rings | 365,00 | 5,00 | | | | |
| O-Rings | 365,00 | 6,00 | | | | |
| O-Rings | 365,00 | 7,00 | | | | |
| O-Rings | 366,00 | 3,00 | | | | |
| O-Rings | 366,00 | 3,50 | | | | |
| O-Rings | 366,00 | 4,00 | | | | |
| O-Rings | 366,00 | 5,00 | | | | |
| O-Rings | 366,00 | 6,00 | | | | |
| O-Rings | 367,00 | 3,00 | | | | |
| O-Rings | 367,00 | 3,50 | | | | |
| O-Rings | 367,00 | 4,00 | | | | |
| O-Rings | 367,00 | 5,00 | | | | |
| O-Rings | 367,00 | 6,00 | | | | |
| O-Rings | 367,67 | 6,99 | 81450 | 458 | 2-458 | R86 |
| O-Rings | 368,00 | 3,00 | | | | |
| O-Rings | 368,00 | 3,50 | | | | |
| O-Rings | 368,00 | 4,00 | | | | |
| O-Rings | 368,00 | 5,00 | | | | |
| O-Rings | 368,00 | 6,00 | | | | |
| O-Rings | 369,00 | 3,00 | | | | |
| O-Rings | 369,00 | 3,50 | | | | |
| O-Rings | 369,00 | 4,00 | | | | |
| O-Rings | 369,00 | 5,00 | | | | |
| O-Rings | 369,00 | 6,00 | | | | |
| O-Rings | 370,00 | 3,00 | | | | |
| O-Rings | 370,00 | 3,50 | | | | |

| | | |
|---------|--------|------|
| O-Rings | 370,00 | 4,00 |
| O-Rings | 370,00 | 5,00 |
| O-Rings | 370,00 | 6,00 |
| O-Rings | 371,00 | 3,00 |
| O-Rings | 371,00 | 3,50 |
| O-Rings | 371,00 | 4,00 |
| O-Rings | 371,00 | 5,00 |
| O-Rings | 371,00 | 6,00 |
| O-Rings | 372,00 | 3,00 |
| O-Rings | 372,00 | 3,50 |
| O-Rings | 372,00 | 4,00 |
| O-Rings | 372,00 | 5,00 |
| O-Rings | 372,00 | 6,00 |
| O-Rings | 373,00 | 3,00 |
| O-Rings | 373,00 | 3,50 |
| O-Rings | 373,00 | 4,00 |
| O-Rings | 373,00 | 5,00 |
| O-Rings | 373,00 | 6,00 |
| O-Rings | 374,00 | 3,00 |
| O-Rings | 374,00 | 3,50 |
| O-Rings | 374,00 | 4,00 |
| O-Rings | 374,00 | 5,00 |
| O-Rings | 374,00 | 6,00 |
| O-Rings | 374,50 | 8,40 |
| O-Rings | 375,00 | 3,00 |
| O-Rings | 375,00 | 3,50 |
| O-Rings | 375,00 | 4,00 |
| O-Rings | 375,00 | 5,00 |
| O-Rings | 375,00 | 6,00 |
| O-Rings | 375,00 | 7,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 376,00 | 3,00 | | | | |
| O-Rings | 376,00 | 3,50 | | | | |
| O-Rings | 376,00 | 4,00 | | | | |
| O-Rings | 376,00 | 5,00 | | | | |
| O-Rings | 376,00 | 6,00 | | | | |
| O-Rings | 377,00 | 3,00 | | | | |
| O-Rings | 377,00 | 3,50 | | | | |
| O-Rings | 377,00 | 4,00 | | | | |
| O-Rings | 377,00 | 5,00 | | | | |
| O-Rings | 377,00 | 6,00 | | | | |
| O-Rings | 378,00 | 3,00 | | | | |
| O-Rings | 378,00 | 3,50 | | | | |
| O-Rings | 378,00 | 4,00 | | | | |
| O-Rings | 378,00 | 5,00 | | | | |
| O-Rings | 378,00 | 6,00 | | | | |
| O-Rings | 379,00 | 3,00 | | | | |
| O-Rings | 379,00 | 3,50 | | | | |
| O-Rings | 379,00 | 4,00 | | | | |
| O-Rings | 379,00 | 5,00 | | | | |
| O-Rings | 379,00 | 6,00 | | | | |
| O-Rings | 379,30 | 5,70 | | | | |
| O-Rings | 380,00 | 3,00 | | | | |
| O-Rings | 380,00 | 3,50 | | | | |
| O-Rings | 380,00 | 4,00 | | | | |
| O-Rings | 380,00 | 5,00 | | | | |
| O-Rings | 380,00 | 6,00 | | | | |
| O-Rings | 380,37 | 5,33 | 61500 | 384 | 2-384 | |
| O-Rings | 380,37 | 6,99 | 81500 | 459 | 2-459 | R87 |
| O-Rings | 380,60 | 3,53 | 41500 | 281 | 2-281 | |
| O-Rings | 381,00 | 3,00 | | | | |

| | | |
|---------|--------|------|
| O-Rings | 381,00 | 3,50 |
| O-Rings | 381,00 | 4,00 |
| O-Rings | 381,00 | 5,00 |
| O-Rings | 381,00 | 6,00 |
| O-Rings | 382,00 | 3,00 |
| O-Rings | 382,00 | 3,50 |
| O-Rings | 382,00 | 4,00 |
| O-Rings | 382,00 | 5,00 |
| O-Rings | 382,00 | 6,00 |
| O-Rings | 383,00 | 3,00 |
| O-Rings | 383,00 | 3,50 |
| O-Rings | 383,00 | 4,00 |
| O-Rings | 383,00 | 5,00 |
| O-Rings | 383,00 | 6,00 |
| O-Rings | 384,00 | 3,00 |
| O-Rings | 384,00 | 3,50 |
| O-Rings | 384,00 | 4,00 |
| O-Rings | 384,00 | 5,00 |
| O-Rings | 384,00 | 6,00 |
| O-Rings | 384,50 | 8,40 |
| O-Rings | 385,00 | 3,00 |
| O-Rings | 385,00 | 3,50 |
| O-Rings | 385,00 | 4,00 |
| O-Rings | 385,00 | 5,00 |
| O-Rings | 385,00 | 6,00 |
| O-Rings | 386,00 | 3,00 |
| O-Rings | 386,00 | 3,50 |
| O-Rings | 386,00 | 4,00 |
| O-Rings | 386,00 | 5,00 |
| O-Rings | 386,00 | 6,00 |

| | | |
|---------|--------|------|
| O-Rings | 387,00 | 3,00 |
| O-Rings | 387,00 | 3,50 |
| O-Rings | 387,00 | 4,00 |
| O-Rings | 387,00 | 5,00 |
| O-Rings | 387,00 | 6,00 |
| O-Rings | 387,00 | 7,00 |
| O-Rings | 388,00 | 3,00 |
| O-Rings | 388,00 | 3,50 |
| O-Rings | 388,00 | 4,00 |
| O-Rings | 388,00 | 5,00 |
| O-Rings | 388,00 | 6,00 |
| O-Rings | 389,00 | 3,00 |
| O-Rings | 389,00 | 3,50 |
| O-Rings | 389,00 | 4,00 |
| O-Rings | 389,00 | 5,00 |
| O-Rings | 389,00 | 6,00 |
| O-Rings | 390,00 | 3,00 |
| O-Rings | 390,00 | 3,50 |
| O-Rings | 390,00 | 4,00 |
| O-Rings | 390,00 | 5,00 |
| O-Rings | 390,00 | 6,00 |
| O-Rings | 391,00 | 3,00 |
| O-Rings | 391,00 | 3,50 |
| O-Rings | 391,00 | 4,00 |
| O-Rings | 391,00 | 5,00 |
| O-Rings | 391,00 | 6,00 |
| O-Rings | 392,00 | 3,00 |
| O-Rings | 392,00 | 3,50 |
| O-Rings | 392,00 | 4,00 |
| O-Rings | 392,00 | 5,00 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|-----|
| O-Rings | 392,00 | 6,00 | | | | |
| O-Rings | 393,00 | 3,00 | | | | |
| O-Rings | 393,00 | 3,50 | | | | |
| O-Rings | 393,00 | 4,00 | | | | |
| O-Rings | 393,00 | 5,00 | | | | |
| O-Rings | 393,00 | 6,00 | | | | |
| O-Rings | 393,07 | 6,99 | 81550 | 460 | 2-460 | R88 |
| O-Rings | 394,00 | 3,00 | | | | |
| O-Rings | 394,00 | 3,50 | | | | |
| O-Rings | 394,00 | 4,00 | | | | |
| O-Rings | 394,00 | 5,00 | | | | |
| O-Rings | 394,00 | 6,00 | | | | |
| O-Rings | 395,00 | 3,00 | | | | |
| O-Rings | 395,00 | 3,50 | | | | |
| O-Rings | 395,00 | 4,00 | | | | |
| O-Rings | 395,00 | 5,00 | | | | |
| O-Rings | 395,00 | 6,00 | | | | |
| O-Rings | 396,00 | 3,00 | | | | |
| O-Rings | 396,00 | 3,50 | | | | |
| O-Rings | 396,00 | 4,00 | | | | |
| O-Rings | 396,00 | 5,00 | | | | |
| O-Rings | 396,00 | 6,00 | | | | |
| O-Rings | 397,00 | 3,00 | | | | |
| O-Rings | 397,00 | 3,50 | | | | |
| O-Rings | 397,00 | 4,00 | | | | |
| O-Rings | 397,00 | 5,00 | | | | |
| O-Rings | 397,00 | 6,00 | | | | |
| O-Rings | 398,00 | 3,00 | | | | |
| O-Rings | 398,00 | 3,50 | | | | |
| O-Rings | 398,00 | 4,00 | | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 398,00 | 5,00 | | | |
| O-Rings | 398,00 | 6,00 | | | |
| O-Rings | 399,00 | 3,00 | | | |
| O-Rings | 399,00 | 3,50 | | | |
| O-Rings | 399,00 | 4,00 | | | |
| O-Rings | 399,00 | 5,00 | | | |
| O-Rings | 399,00 | 6,00 | | | |
| O-Rings | 399,30 | 5,70 | | | |
| O-Rings | 399,50 | 8,40 | | | |
| O-Rings | 400,00 | 3,00 | | | |
| O-Rings | 400,00 | 3,50 | | | |
| O-Rings | 400,00 | 4,00 | | | |
| O-Rings | 400,00 | 5,00 | | | |
| O-Rings | 400,00 | 6,00 | | | |
| O-Rings | 400,00 | 7,00 | | | |
| O-Rings | 401,00 | 3,50 | | | |
| O-Rings | 401,00 | 4,00 | | | |
| O-Rings | 402,00 | 3,50 | | | |
| O-Rings | 402,00 | 4,00 | | | |
| O-Rings | 403,00 | 3,50 | | | |
| O-Rings | 403,00 | 4,00 | | | |
| O-Rings | 404,00 | 3,50 | | | |
| O-Rings | 404,00 | 4,00 | | | |
| O-Rings | 405,00 | 3,50 | | | |
| O-Rings | 405,00 | 4,00 | | | |
| O-Rings | 405,26 | 3,53 | 41600 | 282 | 2-282 |
| O-Rings | 405,26 | 5,33 | 61600 | 385 | 2-385 |
| O-Rings | 405,26 | 6,99 | 81600 | 461 | 2-461 |
| O-Rings | 406,00 | 3,50 | | | |
| O-Rings | 406,00 | 4,00 | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 407,00 | 3,50 | | | |
| O-Rings | 407,00 | 4,00 | | | |
| O-Rings | 408,00 | 3,50 | | | |
| O-Rings | 408,00 | 4,00 | | | |
| O-Rings | 409,00 | 3,50 | | | |
| O-Rings | 409,00 | 4,00 | | | |
| O-Rings | 410,00 | 3,50 | | | |
| O-Rings | 410,00 | 4,00 | | | |
| O-Rings | 411,00 | 3,50 | | | |
| O-Rings | 411,00 | 4,00 | | | |
| O-Rings | 412,00 | 3,50 | | | |
| O-Rings | 412,00 | 4,00 | | | |
| O-Rings | 412,00 | 7,00 | | | |
| O-Rings | 413,00 | 3,50 | | | |
| O-Rings | 413,00 | 4,00 | | | |
| O-Rings | 414,00 | 3,50 | | | |
| O-Rings | 414,00 | 4,00 | | | |
| O-Rings | 415,00 | 3,50 | | | |
| O-Rings | 415,00 | 4,00 | | | |
| O-Rings | 415,00 | 6,00 | | | |
| O-Rings | 416,00 | 3,50 | | | |
| O-Rings | 416,00 | 4,00 | | | |
| O-Rings | 417,00 | 3,50 | | | |
| O-Rings | 417,00 | 4,00 | | | |
| O-Rings | 417,96 | 6,99 | 81650 | 462 | 2-462 |
| O-Rings | 418,00 | 3,50 | | | |
| O-Rings | 418,00 | 4,00 | | | |
| O-Rings | 419,00 | 3,50 | | | |
| O-Rings | 419,00 | 4,00 | | | |
| O-Rings | 419,30 | 5,70 | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 420,00 | 3,50 | | | |
| O-Rings | 420,00 | 4,00 | | | |
| O-Rings | 421,00 | 3,50 | | | |
| O-Rings | 421,00 | 4,00 | | | |
| O-Rings | 422,00 | 3,50 | | | |
| O-Rings | 422,00 | 4,00 | | | |
| O-Rings | 422,00 | 6,00 | | | |
| O-Rings | 423,00 | 3,50 | | | |
| O-Rings | 423,00 | 4,00 | | | |
| O-Rings | 424,00 | 3,50 | | | |
| O-Rings | 424,00 | 4,00 | | | |
| O-Rings | 425,00 | 3,50 | | | |
| O-Rings | 425,00 | 4,00 | | | |
| O-Rings | 425,00 | 7,00 | | | |
| O-Rings | 426,00 | 3,50 | | | |
| O-Rings | 426,00 | 4,00 | | | |
| O-Rings | 427,00 | 3,50 | | | |
| O-Rings | 427,00 | 4,00 | | | |
| O-Rings | 428,00 | 3,50 | | | |
| O-Rings | 428,00 | 4,00 | | | |
| O-Rings | 429,00 | 3,50 | | | |
| O-Rings | 429,00 | 4,00 | | | |
| O-Rings | 429,00 | 6,00 | | | |
| O-Rings | 430,00 | 3,50 | | | |
| O-Rings | 430,00 | 4,00 | | | |
| O-Rings | 430,66 | 3,53 | 41700 | 283 | 2-283 |
| O-Rings | 430,66 | 5,33 | 61700 | 386 | 2-386 |
| O-Rings | 430,66 | 6,99 | 81700 | 463 | 2-463 |
| O-Rings | 431,00 | 3,50 | | | |
| O-Rings | 431,00 | 4,00 | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 432,00 | 3,50 | | | |
| O-Rings | 432,00 | 4,00 | | | |
| O-Rings | 433,00 | 3,50 | | | |
| O-Rings | 433,00 | 4,00 | | | |
| O-Rings | 434,00 | 3,50 | | | |
| O-Rings | 434,00 | 4,00 | | | |
| O-Rings | 435,00 | 3,50 | | | |
| O-Rings | 435,00 | 4,00 | | | |
| O-Rings | 436,00 | 3,50 | | | |
| O-Rings | 436,00 | 4,00 | | | |
| O-Rings | 437,00 | 3,50 | | | |
| O-Rings | 437,00 | 4,00 | | | |
| O-Rings | 437,00 | 7,00 | | | |
| O-Rings | 438,00 | 3,50 | | | |
| O-Rings | 438,00 | 4,00 | | | |
| O-Rings | 439,00 | 3,50 | | | |
| O-Rings | 439,00 | 4,00 | | | |
| O-Rings | 439,30 | 5,70 | | | |
| O-Rings | 440,00 | 3,50 | | | |
| O-Rings | 440,00 | 4,00 | | | |
| O-Rings | 441,00 | 4,00 | | | |
| O-Rings | 442,00 | 4,00 | | | |
| O-Rings | 443,00 | 4,00 | | | |
| O-Rings | 443,36 | 6,99 | 81750 | 464 | 2-464 |
| O-Rings | 444,00 | 4,00 | | | |
| O-Rings | 445,00 | 4,00 | | | |
| O-Rings | 446,00 | 4,00 | | | |
| O-Rings | 446,00 | 6,00 | | | |
| O-Rings | 447,00 | 4,00 | | | |
| O-Rings | 448,00 | 4,00 | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 448,00 | 6,00 | | | |
| O-Rings | 449,00 | 4,00 | | | |
| O-Rings | 450,00 | 4,00 | | | |
| O-Rings | 450,00 | 6,00 | | | |
| O-Rings | 450,00 | 7,00 | | | |
| O-Rings | 451,00 | 4,00 | | | |
| O-Rings | 452,00 | 4,00 | | | |
| O-Rings | 453,00 | 4,00 | | | |
| O-Rings | 453,00 | 6,00 | | | |
| O-Rings | 454,00 | 4,00 | | | |
| O-Rings | 455,00 | 4,00 | | | |
| O-Rings | 456,00 | 4,00 | | | |
| O-Rings | 456,06 | 3,53 | 41800 | 284 | 2-284 |
| O-Rings | 456,06 | 5,33 | 61800 | 387 | 2-387 |
| O-Rings | 456,06 | 6,99 | 81800 | 465 | 2-465 |
| O-Rings | 457,00 | 4,00 | | | |
| O-Rings | 457,00 | 7,00 | | | |
| O-Rings | 458,00 | 4,00 | | | |
| O-Rings | 459,00 | 4,00 | | | |
| O-Rings | 459,30 | 5,70 | | | |
| O-Rings | 460,00 | 4,00 | | | |
| O-Rings | 461,00 | 4,00 | | | |
| O-Rings | 462,00 | 4,00 | | | |
| O-Rings | 462,00 | 7,00 | | | |
| O-Rings | 463,00 | 4,00 | | | |
| O-Rings | 464,00 | 4,00 | | | |
| O-Rings | 465,00 | 4,00 | | | |
| O-Rings | 466,00 | 4,00 | | | |
| O-Rings | 467,00 | 4,00 | | | |
| O-Rings | 468,00 | 4,00 | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 468,76 | 6,99 | 81850 | 466 | 2-466 |
| O-Rings | 469,00 | 4,00 | | | |
| O-Rings | 470,00 | 4,00 | | | |
| O-Rings | 470,00 | 6,00 | | | |
| O-Rings | 471,00 | 4,00 | | | |
| O-Rings | 472,00 | 4,00 | | | |
| O-Rings | 473,00 | 4,00 | | | |
| O-Rings | 474,00 | 4,00 | | | |
| O-Rings | 475,00 | 4,00 | | | |
| O-Rings | 475,00 | 7,00 | | | |
| O-Rings | 476,00 | 4,00 | | | |
| O-Rings | 477,00 | 4,00 | | | |
| O-Rings | 478,00 | 4,00 | | | |
| O-Rings | 478,00 | 6,00 | | | |
| O-Rings | 479,00 | 4,00 | | | |
| O-Rings | 479,30 | 5,70 | | | |
| O-Rings | 480,00 | 4,00 | | | |
| O-Rings | 480,00 | 6,00 | | | |
| O-Rings | 481,00 | 4,00 | | | |
| O-Rings | 481,41 | 5,33 | 61900 | 388 | 2-388 |
| O-Rings | 481,46 | 6,99 | 81900 | 467 | 2-467 |
| O-Rings | 482,00 | 4,00 | | | |
| O-Rings | 483,00 | 4,00 | | | |
| O-Rings | 483,00 | 6,00 | | | |
| O-Rings | 484,00 | 4,00 | | | |
| O-Rings | 485,00 | 4,00 | | | |
| O-Rings | 486,00 | 4,00 | | | |
| O-Rings | 486,00 | 6,00 | | | |
| O-Rings | 487,00 | 4,00 | | | |
| O-Rings | 487,00 | 7,00 | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 488,00 | 4,00 | | | |
| O-Rings | 489,00 | 4,00 | | | |
| O-Rings | 489,00 | 6,00 | | | |
| O-Rings | 490,00 | 4,00 | | | |
| O-Rings | 491,00 | 4,00 | | | |
| O-Rings | 492,00 | 4,00 | | | |
| O-Rings | 493,00 | 4,00 | | | |
| O-Rings | 494,00 | 4,00 | | | |
| O-Rings | 494,00 | 7,00 | | | |
| O-Rings | 494,16 | 6,99 | 81950 | 468 | 2-468 |
| O-Rings | 494,67 | 7,00 | | | |
| O-Rings | 495,00 | 4,00 | | | |
| O-Rings | 496,00 | 4,00 | | | |
| O-Rings | 497,00 | 4,00 | | | |
| O-Rings | 498,00 | 4,00 | | | |
| O-Rings | 499,00 | 4,00 | | | |
| O-Rings | 499,30 | 5,70 | | | |
| O-Rings | 500,00 | 4,00 | | | |
| O-Rings | 500,00 | 6,00 | | | |
| O-Rings | 500,00 | 7,00 | | | |
| O-Rings | 504,00 | 6,00 | | | |
| O-Rings | 505,00 | 6,00 | | | |
| O-Rings | 506,81 | 5,33 | 62000 | 388 | 2-389 |
| O-Rings | 506,86 | 6,99 | 82000 | 469 | 2-469 |
| O-Rings | 508,00 | 6,00 | | | |
| O-Rings | 510,00 | 6,00 | | | |
| O-Rings | 515,00 | 7,00 | | | |
| O-Rings | 516,00 | 6,00 | | | |
| O-Rings | 530,00 | 6,00 | | | |
| O-Rings | 530,00 | 7,00 | | | |

| | | | | | |
|---------|--------|------|-------|-----|-------|
| O-Rings | 532,21 | 5,33 | 62100 | 389 | 2-390 |
| O-Rings | 532,26 | 6,99 | 82100 | 470 | 2-470 |
| O-Rings | 540,00 | 6,00 | | | |
| O-Rings | 544,00 | 6,00 | | | |
| O-Rings | 545,00 | 7,00 | | | |
| O-Rings | 545,47 | 7,00 | | | |
| O-Rings | 549,00 | 6,00 | | | |
| O-Rings | 552,00 | 6,00 | | | |
| O-Rings | 555,00 | 6,00 | | | |
| O-Rings | 557,61 | 5,33 | 62200 | 391 | 2-391 |
| O-Rings | 557,66 | 6,99 | 82200 | 471 | 2-471 |
| O-Rings | 560,00 | 6,00 | | | |
| O-Rings | 560,00 | 7,00 | | | |
| O-Rings | 569,00 | 6,00 | | | |
| O-Rings | 575,00 | 6,00 | | | |
| O-Rings | 579,00 | 6,00 | | | |
| O-Rings | 580,00 | 7,00 | | | |
| O-Rings | 582,62 | 5,33 | 62300 | 392 | 2-392 |
| O-Rings | 582,68 | 6,99 | 82300 | 472 | 2-472 |
| O-Rings | 596,27 | 7,00 | | | |
| O-Rings | 600,00 | 7,00 | | | |
| O-Rings | 608,08 | 5,33 | 62400 | 393 | 2-393 |
| O-Rings | 608,80 | 6,99 | 82400 | 473 | 2-473 |
| O-Rings | 615,00 | 7,00 | | | |
| O-Rings | 630,00 | 7,00 | | | |
| O-Rings | 633,48 | 5,33 | 62500 | 394 | 2-394 |
| O-Rings | 633,48 | 6,99 | 82500 | 474 | 2-474 |
| O-Rings | 647,00 | 7,00 | | | |
| O-Rings | 650,00 | 7,00 | | | |
| O-Rings | 658,88 | 5,33 | 62600 | 395 | 2-395 |

| | | | | | | |
|---------|--------|------|-------|-----|-------|--|
| O-Rings | 658,88 | 6,99 | 82600 | 475 | 2-475 | |
| O-Rings | 670,00 | 7,00 | | | | |